

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N5919A</b> MRF323 1 MOTA	<b>2N5945</b> (Cont'd) 2N946 3 MOTA	<b>2N5950</b> (Cont'd) J203-18 3 SIX	<b>2N5952</b> (Cont'd) THJ5669 3 SPR	<b>2N5953-18</b> (Cont'd) TP5953 3 SPR	<b>2N5974</b> (Cont'd) D45VH4 1 GESY
<b>2N5922</b> BLV20 1 PHIN	2N5645 3 MOTA	J204 3 INL	THJ305 3 SPR	<b>2N5954</b> 2N6318 1 MOTA	DE183 1 DGE
2N5641 3 MOTA	2N5847 3 MOTA	J304-18 3 SIX	TIS75 3 IFC	DE218 1 DGE	BD132 3 PHIN
<b>2N5927</b> D60T259010 1 WESY	2N5944 3 MOTA	MPF102 3 MOTA	TMPPF4303 3 SPR	DE218 1 DGE	BDT82 3 APX
<b>2N5928</b> D60T259010SPL 1 WESY	2N5946 3 MOTA	PN4223-18 3 NSC	TMPPF5458 3 SPR	SDT3577 1 SOD	D45C6 3 GESY
<b>2N5929</b> D60T259010SPL 1 WESY	2N5947 3 MOTA	THJ5486 3 SPR	TMPPF5484 3 SPR	SDT3705 1 SOD	DE332 3 DGE
2N5671 1 RCA	BLX67 3 PHIN	THJ5639 3 SPR	TMPPF5640 3 SPR	SDT3714 1 SOD	<b>2N5975</b> 2N6490 1 RCA
2N6338 1 MOTA	D40D1 3 GESY	THJ5670 3 SPR	TMPPF5669 3 SPR	SDT3718 1 SOD	D45VH7 1 GESY
2N5672 3 RCA	D42C1 3 GESY	TIS74 3 IFC	TMPPF5669 3 SPR	SDT3723 1 SOD	DE183 1 DGE
BUX10 3 SGSI	DE363 3 DGE	TMPPF5486 3 SPR	TP4303 3 SPR	SDT3728 1 SOD	2N5875 3 SGSI
DE327 3 DGE	MRF652 3 MOTA	TMPPF5639 3 SPR	TP5669 3 SPR	SDT3731 1 SOD	BDT82 3 APX
<b>2N5930</b> 2N5672 1 RCA	MRF752 3 MOTA	TMPPF5670 3 SPR	<b>2N5952-18</b> 2N5484 3 INL	2N3741 3 MOTA	D45C8 3 GESY
2N6338 1 MOTA	NE050320-12 3 NECE	TP5670 3 SPR	2N5640 3 MOTA	BD140 3 PHIN	DE332 3 DGE
2N5672 3 TRWS	SD1135 3 THCS	<b>2N5950-18</b> 2N5486 3 INL	2N5953-18 3 NSC	D45C10 3 GESY	<b>2N5976</b> 2N6491 1 RCA
2N6339 3 MOTA	<b>2N5946</b> 2N5590 3 MOTA	2N5639 3 MOTA	SIX 3 SIX	D45VH10 3 GESY	D45VH10 1 GESY
BUX10 3 SGSI	2N5637 3 MOTA	PN4416 3 SIX	J305 3 SIX	THC6318 3 SPR	DE183 1 DGE
DE327 3 DGE	2N5646 3 MOTA	THJ5950 3 SPR	SX3819 3 TII	<b>2N5955</b> 2N6317 1 MOTA	2N5876 3 SGSI
<b>2N5931</b> 2N6341 1 MOTA	2N5945 3 THCS	TMPPF5950 3 SPR	THJ5952 3 SPR	DE218 1 DGE	BDT84 3 APX
BUX11N 3 SGSI	BLX68 3 PHIN	TP5950 3 SPR	THJ5953 3 SPR	SDT3576 1 SOD	BDW52C 3 SGSI
DE327 3 DGE	D42C2 3 GESY	<b>2N5951</b> 2N5486 1 INL	TIS58 3 TII	SDT3702 1 SOD	D45C8 3 GESY
TIP516 3 TII	D44C1 3 GESY	2N5486 1 MOTA	TMPPF5952 3 SPR	SDT3704 1 SOD	DE332 3 DGE
<b>2N5932</b> 2N6341 1 MOTA	DE364 3 DGE	2N5640 1 MOTA	TMPPF5953 3 SPR	SDT3707 1 SOD	<b>2N5977</b> 2N6486 1 RCA
2N6338 1 MOTA	MRF653 3 MOTA	2N5951-18 1 NSC	TP5952 3 SPR	SDT3708 1 SOD	D44VH4 1 GESY
2N5672 3 RCA	MRF654 3 MOTA	SIX 3 SIX	TP5953 3 SPR	SDT3711 1 SOD	DE182 1 DGE
BUX10 3 SGSI	MRF754 3 MOTA	PN4416 1 SIX	<b>2N5953</b> 2N5484 1 INL	SDT3716 1 SOD	2N5877 3 SGSI
DE327 3 DGE	NE020620-07 3 NECE	THJ5951 1 SPR	2N5640 1 MOTA	SDT3722 1 SOD	BD131 3 PHIN
<b>2N5933</b> 2N5672 1 RCA	NE021020-12 3 NECE	TMPPF5951 1 SPR	2N5952-18 1 SIX	SDT3727 1 SOD	BD241 3 SGSI
2N6338 1 MOTA	NE051025-12 3 NECE	TP5951 1 SPR	2N5953-18 1 NSC	SDT3730 1 SOD	BDT81 3 APX
2N5672 3 TRWS	SD1136 3 THCS	TIS59 2 TII	2N5484 3 INL	2N3740 3 MOTA	D42C3 3 GESY
2N6339 3 MOTA	<b>2N5947</b> 2N5847 3 MOTA	2N5247 3 IFC	J305 1 SIX	2N4898 3 MOTA	D44C6 3 GESY
BUX10 3 SGSI	2N5945 3 MOTA	2N5338 3 MOTA	THJ5953 1 SPR	2N5956 3 RCA	DE331 3 DGE
DE327 3 DGE	THCS 3 THCS	2N5458 3 INL	TMPPF5953 1 SPR	D45C4 3 GESY	<b>2N5978</b> 2N6487 1 RCA
<b>2N5935</b> 2N6032 1 RCA	BLX67 3 PHIN	2N5485 3 INL	TP5953 1 SPR	D45C5 3 GESY	D44VH7 1 GESY
2N6341 1 MOTA	D40D1 3 GESY	2N5670 3 MOTA	SX3819 2 TII	D45C6 3 GESY	DE182 1 DGE
2N6275 3 MOTA	MRF587 3 MOTA	2N5949 3 IFC	TIS58 2 TII	D45C7 3 GESY	2N5878 3 SGSI
BUX11N 3 SGSI	SD1005 3 THCS	2N5949 1 SPR	2N3684 3 INL	D45C8 3 GESY	BDT81 3 APX
DE327 3 DGE	SD1005-4 3 THCS	TP5949 1 SPR	2N3685 3 INL	DE128 3 DGE	D44C8 3 GESY
DE387 3 DGE	SD1006 3 THCS	SX3819 2 TII	2N3819 3 SIX	SVT200-10B 3 TRWS	DE331 3 DGE
TIP516 3 TII	<b>2N5949</b> 2N5486 1 INL	TIS59 2 TII	2N3823 3 MOTA	THC6317 3 SPR	<b>2N5979</b> 2N6488 1 RCA
<b>2N5936</b> 2N6033 1 RCA	2N5638 1 MOTA	THJ4304 3 SPR	2N4340 3 INL	<b>2N5956</b> 2N6317 1 MOTA	D44VH10 1 GESY
2N6338 1 MOTA	2N5949-18 1 NSC	THJ4549 3 SPR	NSC 3 NSC	DE218 1 DGE	DE182 1 DGE
2N5672 3 RCA	BSV80 3 PHIN	THJ5486 3 SPR	2N4341 3 INL	SDT3575 1 SOD	BDT83 3 APX
TRWS 3 TRWS	DE451 3 DGE	THJ5640 3 SPR	SIX 3 SIX	SDT3701 1 SOD	BDW51C 3 SGSI
2N6277 3 MOTA	DE457 3 DGE	TIS75 3 IFC	2N4391 3 INL	SDT3703 1 SOD	DE331 3 DGE
BUX10 3 SGSI	ITE4416 3 INL	TMPPF4304 3 SPR	2N4889 3 INL	SDT3706 1 SOD	<b>2N5980</b> 2N6489 1 RCA
DE327 3 DGE	PN4304-18 3 NSC	TMPPF5459 3 SPR	2N5246 3 IFC	SDT3709 1 SOD	D45VH4 1 GESY
DE387 3 DGE	THCS 3 THCS	TMPPF5486 3 SPR	2N5337 3 MOTA	SDT3712 1 SOD	DE183 1 DGE
<b>2N5937</b> 2N6341 1 MOTA	2N5949 1 SPR	TMPPF5486 3 SPR	2N5457 3 INL	SDT3715 1 SOD	MJE2955 1 MOTA
BUX11N 3 SGSI	TP5949 1 SPR	TMPPF5555 3 SPR	2N5458 3 MOTA	SDT3716 1 SOD	BDT82 3 APX
DE327 3 DGE	SX3819 2 TII	TMPPF5638 3 SPR	2N5459 3 MOTA	SDT3720 1 SOD	D45VH7 3 GESY
TIP516 3 TII	TIS59 2 TII	U1837 3 SIX	2N5639 3 MOTA	SDT3721 1 SOD	<b>2N5981</b> 2N6490 1 RCA
<b>2N5939</b> 2N5659 1 TRWS	THJ5486 3 SPR	<b>2N5951-18</b> 2N5486 3 INL	2N5949 3 IFC	SDT3725 1 SOD	D45VH7 1 GESY
2N5941 1 TRWS	THJ5555 3 SPR	2N5640 3 MOTA	2N5952 3 IFC	SDT3726 1 SOD	DE183 1 DGE
BLX14 1 PHIN	THJ5638 3 SPR	PN4416 3 SIX	BF245A 3 PHIN	SDT3728 1 SOD	BDT84 3 APX
MRF466 1 MOTA	THJ5951 3 SPR	THCS 3 THCS	BF245C 3 PHIN	SDT3729 1 SOD	DE332 3 DGE
MRF464A 3 MOTA	TIS73 3 IFC	2N5949 1 SPR	BSV80 3 PHIN	SDT3733 1 SOD	<b>2N5982</b> 2N5988 1 MOTA
<b>2N5942</b> BLX15 1 PHIN	TMPPF5486 3 SPR	TP5949 1 SPR	DE180 3 DGE	2N4898 3 MOTA	2N6491 1 RCA
MRF464 1 MOTA	TMPPF5555 3 SPR	THJ4304 3 SPR	DE451 3 DGE	2N5955 3 RCA	D45VH10 1 GESY
MRF428 3 MOTA	TMPPF5638 3 SPR	THJ4549 3 SPR	DE457 3 DGE	D45C2 3 GESY	DE183 1 DGE
THX15 3 THCS	U1837 3 SIX	THJ5951 3 SPR	ITE4416 3 INL	D45C3 3 GESY	D45VH7 3 GESY
<b>2N5943</b> BRF95 1 APX	<b>2N5949-18</b> 2N5486 3 INL	TP5951 3 SPR	J202-18 3 NSC	D45C4 3 GESY	BDT81 3 APX
2N4428 3 MOTA	2N5638 3 MOTA	TP5952 3 SPR	2N5458 3 MOTA	D45C6 3 GESY	DE332 3 DGE
2N5109 3 MOTA	PN4416 3 SIX	TIS58 2 TII	2N5639 3 MOTA	D45C8 3 GESY	<b>2N5983</b> 2N6488 1 RCA
BFR95 3 APX	SX3819 3 TII	TMPPF5951 3 SPR	2N5949 3 IFC	D45VH7 3 GESY	D44VH4 1 GESY
D40D3 3 GESY	THJ5949 3 SPR	TP5951 3 SPR	2N5952 3 IFC	D45VH10 3 GESY	DE182 1 DGE
MRF586 3 MOTA	TIS59 3 TII	2N5952 3 IFC	BF245A 3 PHIN	DE183 1 DGE	MJE3055 1 MOTA
SD1006 3 THCS	TP5949 3 SPR	2N5458 3 INL	BF245C 3 PHIN	BDT83 3 APX	D44VH7 3 GESY
<b>2N5944</b> 2N945 3 MOTA	<b>2N5950</b> 2N5486 1 INL	2N5640 3 MOTA	BSV80 3 PHIN	DE331 3 DGE	<b>2N5984</b> 2N6487 1 RCA
2N5589 3 MOTA	2N5639 3 MOTA	PN4416 3 SIX	DE180 3 DGE	<b>2N5985</b> 2N5991 1 MOTA	D45VH4 1 GESY
2N5644 3 MOTA	2N5950-18 1 NSC	THJ5950 1 SPR	DE451 3 DGE	2N6488 1 RCA	D45VH7 1 GESY
2N5945 3 MOTA	2N5638 3 MOTA	THJ5951 3 SPR	DE457 3 DGE	2N6491 1 RCA	DE182 1 DGE
THCS 3 THCS	PN4416 3 SIX	TIS73 3 IFC	ITE4416 3 INL	2N6490 1 RCA	DE183 1 DGE
2N6080 3 MOTA	SX3819 3 TII	TMPPF5486 3 SPR	J203-18 3 SIX	2N6488 1 RCA	BDT83 3 APX
BLX67 3 PHIN	THJ5949 3 SPR	TMPPF5486 3 SPR	J232-18 3 SIX	2N6487 1 RCA	DE331 3 DGE
D40D1 3 GESY	TIS59 3 TII	TMPPF5555 3 SPR	J304 3 SIX	2N6472 1 MOTA	DE182 1 DGE
DE362 3 DGE	TP5949 3 SPR	TMPPF5638 3 SPR	J305-18 3 NSC	2N6472 1 MOTA	BDT83 3 APX
MRF553 3 MOTA	<b>2N5950</b> 2N5486 1 INL	U1837 3 SIX	J305-18 3 NSC	DE284 1 DGE	BDW51B 3 SGSI
MRF616 3 MOTA	2N5639 3 MOTA	2N5458 3 INL	J305-18 3 NSC	BDX95 3 PHIN	DE331 3 DGE
MRF630 3 MOTA	2N5950-18 1 NSC	2N5458 3 INL	J305-18 3 NSC	DE181 3 DGE	<b>2N5986</b> 2N6489 1 RCA
MRF652 3 MOTA	PN4416 3 SIX	2N5458 3 INL	J305-18 3 NSC	2N6472 1 RCA	D45VH4 1 GESY
MRF752 3 MOTA	SX3819 3 TII	2N5486 3 INL	J305-18 3 NSC	MJ15003 3 MOTA	DE182 1 DGE
NE050320-12 3 NECE	THJ5949 3 SPR	2N5486 3 INL	J305-18 3 NSC	2N6882 3 MOTA	BDT82 3 APX
SD1080-2 3 THCS	TIS59 3 TII	2N5486 3 INL	J305-18 3 NSC	BDW51B 3 SGSI	DE332 3 DGE
SD1115-2 3 THCS	TMPPF5949 3 SPR	2N5486 3 INL	J305-18 3 NSC	BDX95 3 PHIN	<b>2N5987</b> 2N6490 1 RCA
SD1134 3 THCS	TP5949 3 SPR	2N5486 3 INL	J305-18 3 NSC	DE181 3 DGE	D45VH7 1 GESY
<b>2N5945</b> 2N945 3 MOTA	<b>2N5950</b> 2N5486 1 INL	2N5486 3 INL	J305-18 3 NSC	<b>2N5972</b> 2N6472 1 RCA	DE183 1 DGE