

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N1713 DE126A 1 DGE	2N1758 2N2139 1 LTE DE121 3 DGE	2N1840 (Cont'd) D40E1 1 GESY MPSH04 3 MOTA	2N1905 DE127 1 DGE	2N1972 (Cont'd) GES2219 3 GESY THC2219 3 SPR TN2219 3 NSC TP2219 3 SPR	2N1986 (Cont'd) BFY55 1 PHIN DE128 1 DGE 2N697 3 RCA 2N1613 3 SGSI BCX55-10 3 SIEG BSS79C 3 SIEG GES2218 3 GESY GES2219A 3 GESY GES3053 3 GESY THC2218 3 SPR THC2219A 3 SPR THC3053 3 SPR TN2218 3 NSC TN2219A 3 NSC TP2218 3 SPR TP2219A 3 SPR
2N1714 2N4237 1 MOTA BSX21 1 PHIN D40D7 1 GESY DE128 1 DGE 2N5786 3 RCA BC394 3 SGSI D40D4 3 GESY	2N1757 2N2140 1 LTE DE121 3 DGE 2N1758 2N2141 1 LTE DE121 3 DGE 2N1759 2N2143 1 LTE DE121 3 DGE 2N1760 2N2144 1 LTE BDX92 1 PHIN 2N4905 3 RCA BDW22A 3 SGSI DE121 3 DGE	2N1886 2N2892 1 GSE D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N1907 DE127 1 DGE 2N1907A DE127 1 DGE 2N1905 DE127 1 DGE 2N1908 DE128 1 DGE 2N1908A 2N1905 1 LTE DE127 3 DGE 2N1923 2N3498 1 MOTA THC3498 3 SPR	2N1973 2N1893 1 PHIN 2N3019 1 MOTA 2N3020 1 PHIN D40D8 1 GESY DE128 1 DGE 2N1893 3 RCA 2N4305 3 TRWS BCX56-16 3 SIEG D38H4 3 GESY D38H5 3 GESY D42T1 3 SPR THC3019 3 SPR THC3020 3 SPR TN3019 3 NSC TN3020 3 NSC	2N1987 2N697 1 RCA 2N1613 1 SGSI 2N2218A 1 MOTA BFY50 1 PHIN BFY55 1 PHIN DE128 1 DGE 2N1711 3 PHIN 2N4400 3 NSC D40D7 3 GESY DE123 3 DGE DE126 3 DGE GES2218A 3 GESY PN2221A 3 NSC THC697 3 SPR THC1613 3 SPR THC2218A 3 SPR TN2218A 3 NSC TP2218A 3 SPR
2N1715 2N5681 1 MOTA D44T1 1 GESY D44T2 3 GESY DE128 3 DGE 2N1716 2N4237 1 MOTA D40D7 1 GESY 2N5786 3 RCA D40D4 3 GESY DE128 3 DGE 2N1717 2N5681 1 MOTA D44T1 1 GESY D44T2 3 GESY DE128 3 DGE 2N1718 2N3420 1 GSE BFS23A 1 PHIN D44C7 1 GESY 2N4307 3 TRWS 2N5336 3 MOTA 2N6292 3 RCA BD239A 3 RCA BU407 3 APX D42C8 3 GESY SD1212-1 3 THCS ST44C7 3 STI	2N1761 2N2145 1 LTE BDX96 1 PHIN BDW22C 3 SGSI DE121 3 DGE 2N1762 2N2146 1 LTE DE121 3 DGE 2N1764 2N2369A 1 MOTA BSX20 3 PHIN PN2369A 3 NSC 2N1768 D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C6 3 STI 2N1769 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N1889 2N699 1 RCA BSW66 1 PHIN D40D7 1 GESY D44T1 3 GESY DE128 3 DGE THC699 3 SPR 2N1890 BSW66 1 PHIN BSY55 1 SGSI D40D8 1 GESY 2N1893 3 RCA BSW67 3 PHIN D44T1 3 GESY 2N1893 D42T1 1 GESY DE128 1 DGE PHIN 3 PHIN 2N1613 3 RCA 2N2102 3 RCA 2N2405 3 RCA 2N3019 3 MOTA 2N3020 3 MOTA 2N3053 3 MOTA 2N3440 3 RCA 2N4305 3 TRWS 2N5320 3 RCA	2N1943 2N3020 1 MOTA D40D7 1 GESY 2N1893 3 RCA 2N4305 3 TRWS D38H4 3 GESY DE128 3 DGE THC3020 3 SPR TN3020 3 NSC 2N1944 2N2219A 1 MOTA DE123A 1 DGE GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR 2N1945 2N2219A 1 MOTA DE123A 1 DGE GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR 2N1946 2N2219A 1 MOTA DE123A 1 DGE GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR 2N1947 DE123A 1 DGE 2N1948 DE123A 1 DGE 2N1949 DE123A 1 DGE 2N1950 DE123A 1 DGE 2N1951 DE123A 1 DGE 2N1952 DE123A 1 DGE 2N1953 2N2218 1 MOTA DE123A 1 DGE 2N697 3 RCA DE128 3 DGE GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR 2N1954 2N651 1 LTE DE102A 1 DGE DE102 3 DGE 2N1955 2N1190 1 LTE DE102A 1 DGE 2N1956 2N651 1 LTE DE102A 1 DGE DE102 3 DGE 2N1957 2N1187 1 LTE DE102A 1 DGE DE102 3 DGE 2N1958 D40E5 1 GESY DE102A 1 DGE 2N1958A D40E5 1 GESY 2N1959 2N5859 1 MOTA D40E5 1 GESY 2N4307 3 TRWS DE324 3 DGE 2N1959A D40E5 1 GESY 2N1970 DE105 1 DGE 2N1971 DE121 1 DGE 2N1972 2N2219 1 PHIN D40E5 1 GESY DE128 1 DGE	2N1974 2N1893 1 PHIN 2N3020 1 MOTA D40D7 1 GESY DE128 1 DGE RCA1A01 1 RCA 2N1893 3 RCA 2N4305 3 TRWS BC394 3 SGSI D38H4 3 GESY THC3020 3 SPR TN3020 3 NSC 2N1975 2N3020 1 MOTA BSX21 1 PHIN D40V1 1 GESY DE128 1 DGE RCA1A01 1 RCA 2N1893 3 RCA 2N4305 3 TRWS BC394 3 SGSI D38H4 3 GESY THC3020 3 SPR TN3020 3 NSC 2N1980 DE105 1 DGE 2N1981 DE105 1 DGE 2N1982 DE105 1 DGE 2N1983 2N2218 1 MOTA 2N2219 1 SGSI BFY55 1 PHIN DE128 1 DGE 2N697 3 RCA 2N1613 3 SGSI GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR 2N1984 2N2218 1 SGSI 2N2219 1 MOTA BFY50 1 PHIN BFY55 1 PHIN DE128 1 DGE RCA1A01 1 RCA 2N697 3 RCA 2N1613 3 SGSI GES2218 3 GESY GES2219 3 GESY THC2218 3 SPR THC2219 3 SPR TN2218 3 NSC TP2218 3 SPR TP2219 3 SPR 2N1985 2N1613 1 SGSI 2N2218 1 PHIN BFY55 1 PHIN DE128 1 DGE RCA1A01 1 RCA 2N697 3 RCA 2N1613 3 SGSI GES2218 3 GESY GES2219 3 GESY THC2218 3 SPR THC2219 3 SPR TN2218 3 NSC TP2218 3 SPR TP2219 3 SPR	2N1988 2N1711 1 PHIN 2N3020 1 MOTA PHIN 3 PHIN 2N1893 3 RCA 2N4305 3 TRWS D38H4 3 GESY D40D5 3 GESY DE128 3 DGE PN2222A 3 NSC THC1721 3 SPR THC3020 3 SPR TN3020 3 NSC 2N1989 2N3020 1 MOTA PHIN 3 PHIN BFY50 1 PHIN 2N697 3 RCA 2N1893 3 RCA 2N4305 3 TRWS D38H4 3 GESY DE128 3 DGE THC3020 3 SPR TN3020 3 NSC 2N1990 2N1893 1 SGSI 2N3440 1 RCA BSX21 1 PHIN D38H7 1 GESY BC394 3 SGSI BD115 3 PHIN BFN18 3 SIEG BFN26 3 SIEG D42T1 3 GESY D44T2 3 GESY DE128 3 DGE DE396 3 DGE TN3440 3 NSC 2N1991 2N2904 1 PHIN SGSI 3 SGSI 2N2905 1 PHIN DE129 3 DGE THC2904 3 SPR THC2905 3 SPR TN2904 3 NSC TN2905 3 NSC TP2904 3 SPR TP2905 3 SPR 2N1992 DE123A 1 DGE 2N1994 DE101 1 DGE 2N1995 DE101 1 DGE 2N1996 DE101 1 DGE 2N1997 DE100 1 DGE 2N1998 DE100 1 DGE 2N1999 DE126A 1 DGE 2N2000 DE179 1 DGE 2N2001 DE179 1 DGE