

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>J107-18</b> (Cont'd) TPJ107 3 SPR	<b>J111A</b> (Cont'd) THJJ111 3 SPR	<b>J174-18</b> (Cont'd) TMPFJ174 3 SPR	<b>J202-18</b> (Cont'd) 2N5639 3 MOTA 2N5953 3 IFC THJJ202 3 SPR TMPFJ202 3 SPR	<b>J212</b> (Cont'd) DE452 3 DGE J212-18 3 NSC THJ5397 3 SPR TMPF5397 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>J270-18</b> (Cont'd) MPF4093 3 MOTA THJJ270 3 SPR TMPFJ270 3 SPR
<b>J108</b> J105 1 INL MFE2012 1 MOTA THJJ108 1 SPR TPJ108 1 SPR 2N5432 3 SIX 2N5433 3 INL NSC SIX 2N5434 3 INL THJJ105 3 SPR TPJ105 3 SPR	<b>J112</b> THJJ112 1 SPR TMPFJ112 1 SPR 2N5459 3 MOTA J112-18 3 NSC SIX MPF4392 3 MOTA PN4092 3 NSC THJJ112A 3 SPR TIS74 3 IFC TMPFJ112A 3 SPR	<b>J175</b> THJJ175 1 SPR TMPFJ175 1 SPR J174 3 SIX J175-18 3 NSC SIX J176 3 SIX MPF970 3 MOTA P1086 3 NSC SIX P1087 3 NSC SIX	<b>J203</b> THJJ203 1 SPR TMPFJ203 1 SPR 2N4869 3 INL 2N5459 3 MOTA 2N5485 3 MOTA J203-18 3 NSC SIX MPF4222 3 MOTA PN4222 3 NSC THJJ232 3 SPR TMPF232 3 SPR	<b>J212-18</b> 2N5397 3 INL 2N5486 3 MOTA J212 3 MOTA SIX	<b>J271</b> MPF4092 1 MOTA THJJ271 1 SPR TMPFJ271 1 SPR J271-18 3 NSC SIX MPF970 3 MOTA
<b>J108-18</b> J105 1 INL MFE2010 1 MOTA 2N4856 3 NSC SIX 2N4859 3 IFC INL 2N5434 3 SIX J106 3 INL J106-18 3 SIX J107 3 INL J107-18 3 SIX MFE2012 3 MOTA MPF4391 3 MOTA THJJ105 3 SPR TPJ105 3 SPR	<b>J112-18</b> J112 1 INL MPF4392 3 MOTA THJJ112 3 SPR TIS74 3 IFC TMPFJ112 3 SPR	<b>J175-18</b> J175 1 INL MOTA MPF970 3 MOTA THJJ175 3 SPR TMPFJ175 3 SPR	<b>J203-18</b> J203 1 INL 2N4341 3 INL 2N4391 3 NSC 2N4869 3 INL 2N5458 3 INL 2N5459 3 INL MOTA 2N5486 3 MOTA 2N5950 3 IFC 2N5953 3 IFC J105-18 3 SIX J232-18 3 SIX MPF102 3 MOTA THJJ203 3 SPR TMPFJ203 3 SPR	<b>J230</b> 2N4867 1 INL 2N5484 1 MOTA J202 1 NSC THJJ230 1 SPR TMPF230 1 SPR 2N4220A 3 MOTA 2N4339 3 NSC 2N5246 3 IFC DE180 3 DGE DE459 3 DGE THJ4867 3 SPR THJ5484 3 SPR THJJ202 3 SPR TMPF4867 3 SPR TMPF5484 3 SPR TMPFJ202 3 SPR TP4867 3 SPR	<b>J271-18</b> J271 1 INL MPF970 3 MOTA MPF4092 3 MOTA THJJ271 3 SPR TMPFJ271 3 SPR
<b>J109</b> J106 1 INL MFE2011 1 MOTA THJJ109 1 SPR TPJ109 1 SPR 2N5433 3 INL NSC SIX MFE2012 3 MOTA THJJ106 3 SPR TPJ106 3 SPR	<b>J112A</b> J112 1 INL THJJ112 3 SPR TMPFJ112 3 SPR	<b>J176-18</b> J176 1 INL MOTA MPF971 3 MOTA THJJ176 3 SPR TMPFJ176 3 SPR	<b>J204</b> 2N3823 3 MOTA 2N5457 3 MOTA 2N5486 3 MOTA 2N5950 3 IFC 2N5952 3 IFC A5T3821 3 IFC J114 3 SIX J114-18 3 NSC SIX J201-18 3 SIX J204-18 3 SIX J304-18 3 SIX J305 3 SIX J305-18 3 NSC MPF102 3 MOTA MPF4220 3 MOTA PN4220 3 NSC PN4220-18 3 NSC PN4223-18 3 NSC	<b>J230-18</b> 2N3460 3 IFC 2N4867 3 INL 2N5457 3 MOTA PN3686-18 3 NSC PN3821-18 3 NSC	<b>J300</b> 2N5397 1 INL MPF4093 1 MOTA 2N5245 3 IFC 2N5245 3 IFC 2N5486 3 MOTA DE452 3 DGE J300-18 3 NSC THJ5397 3 SPR TMPF5397 3 SPR U309 3 MOTA U310 3 SIX
<b>J109-18</b> J106 1 INL MFE2010 1 MOTA 2N4856 3 NSC SIX 2N4859 3 IFC INL 2N5434 3 SIX MFE2012 3 MOTA MPF4391 3 MOTA THJJ106 3 SPR TPJ106 3 SPR	<b>J112A</b> 2N5459 1 MOTA J112 1 INL PN4092 1 NSC THJJ112A 1 SPR TMPFJ112A 1 SPR 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE ITE4092 3 INL THJ5459 3 SPR THJJ112 3 SPR TMPF5459 3 SPR TMPFJ112 3 SPR	<b>J177-18</b> J177 1 INL MOTA THJJ177 3 SPR TMPFJ177 3 SPR	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J231</b> 2N3460 3 IFC 2N4867 3 INL 2N5457 3 MOTA PN3686-18 3 NSC PN3821-18 3 NSC	<b>J300-18</b> 2N5245 3 IFC 2N5397 3 INL 2N5486 3 MOTA J210 3 SIX J300 3 SIX MPF4093 3 MOTA
<b>J110</b> MFE2012 3 MOTA THJJ106 3 SPR TPJ106 3 SPR	<b>J113</b> THJJ113 1 SPR TMPFJ113 1 SPR 2N5458 3 MOTA J113-18 3 NSC SIX MPF4393 3 MOTA PN4093 3 NSC THJJ113A 3 SPR TIS75 3 IFC TMPFJ113A 3 SPR	<b>J177-18</b> J177 1 INL MOTA THJJ177 3 SPR TMPFJ177 3 SPR	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J231</b> 2N4868 1 INL 2N5484 1 MOTA J202 1 NSC THJJ231 1 SPR THJJ231 1 SPR TMPF231 1 SPR 2N3459 3 NSC SIX 2N4220A 3 MOTA 2N5246 3 IFC DE180 3 DGE DE459 3 DGE THJ4868 3 SPR THJ5484 3 SPR THJJ202 3 SPR TMPF4868 3 SPR TMPF5484 3 SPR TMPFJ202 3 SPR TP4868 3 SPR	<b>J300A</b> THJJ300A 1 SPR TMPFJ300A 1 SPR
<b>J110-18</b> J106 1 INL MFE2010 1 MOTA 2N4856 3 NSC SIX 2N4859 3 IFC INL 2N5434 3 SIX MFE2012 3 MOTA MPF4391 3 MOTA THJJ106 3 SPR TPJ106 3 SPR	<b>J113A</b> J113 1 INL THJJ113 3 SPR TMPFJ113 3 SPR	<b>J177-18</b> J177 1 INL MOTA THJJ177 3 SPR TMPFJ177 3 SPR	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J231</b> 2N4868 1 INL 2N5484 1 MOTA J202 1 NSC THJJ231 1 SPR THJJ231 1 SPR TMPF231 1 SPR 2N3459 3 NSC SIX 2N4220A 3 MOTA 2N5246 3 IFC DE180 3 DGE DE459 3 DGE THJ4868 3 SPR THJ5484 3 SPR THJJ202 3 SPR TMPF4868 3 SPR TMPF5484 3 SPR TMPFJ202 3 SPR TP4868 3 SPR	<b>J300B</b> THJJ300B 1 SPR TMPFJ300B 1 SPR
<b>J110-18</b> J107 1 INL MFE2011 1 MOTA THJJ110 1 SPR TPJ110 1 SPR 2N5433 3 INL NSC SIX THJJ107 3 SPR TPJ107 3 SPR	<b>J113A</b> 2N5458 1 MOTA J113 1 INL PN4093 1 NSC THJJ113A 1 SPR TMPFJ113A 1 SPR 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE ITE4093 3 INL THJ5458 3 SPR THJJ113 3 SPR TMPF5458 3 SPR TMPFJ113 3 SPR	<b>J201</b> THJJ201 1 SPR TMPFJ201 1 SPR 2N3686 3 INL 2N4338 3 INL 2N4339 3 SIX 2N4867A 3 INL 2N5457 3 MOTA 2N5486 3 MOTA J201-18 3 NSC SIX PN3686 3 NSC	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J231</b> 2N4868 1 INL 2N5484 1 MOTA J202 1 NSC THJJ231 1 SPR THJJ231 1 SPR TMPF231 1 SPR 2N3459 3 NSC SIX 2N4220A 3 MOTA 2N5246 3 IFC DE180 3 DGE DE459 3 DGE THJ4868 3 SPR THJ5484 3 SPR THJJ202 3 SPR TMPF4868 3 SPR TMPF5484 3 SPR TMPFJ202 3 SPR TP4868 3 SPR	<b>J300C</b> THJJ300C 1 SPR TMPFJ300C 1 SPR
<b>J111</b> THJJ111 1 SPR 2N5640 3 MOTA ITE4392 3 INL ITE4393 3 INL J111-18 3 NSC SIX MPF111 3 MOTA MPF4391 3 MOTA PN4091 3 NSC THJJ111A 3 SPR TIS73 3 IFC TMPFJ111A 3 SPR	<b>J113A</b> 2N5458 1 MOTA J113 1 INL PN4093 1 NSC THJJ113A 1 SPR TMPFJ113A 1 SPR 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE ITE4093 3 INL THJ5458 3 SPR THJJ113 3 SPR TMPF5458 3 SPR TMPFJ113 3 SPR	<b>J201-18</b> J201 1 INL 2N3460 3 IFC 2N3686 3 INL 2N3687 3 INL 2N4338 3 INL 2N4339 3 INL NSC 2N5457 3 MOTA 2N5486 3 MOTA 2N5639 3 MOTA A5T3821 3 IFC J204 3 INL THJJ201 3 SPR TMPFJ201 3 SPR	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J231</b> 2N3459 3 IFC 2N4868 3 INL 2N5458 3 MOTA PN3686-18 3 NSC PN3685-18 3 NSC	<b>J300D</b> THJJ300D 1 SPR TMPFJ300D 1 SPR
<b>J111-18</b> J111 1 INL MPF4391 3 MOTA THJJ111 3 SPR TIS73 3 IFC	<b>J114</b> 2N5555 1 INL MPF4393 1 MOTA 2N5486 3 MOTA 2N5949 3 IFC ITE4393 3 INL ITE4393 3 INL J114-18 3 NSC SIX J204 3 INL J310 3 INL PN4393 3 SIX PN4393-18 3 SIX THJ5555 3 SPR TMPF5555 3 SPR	<b>J202</b> THJJ202 1 SPR TMPFJ202 1 SPR 2N4867 3 INL 2N4868 3 INL 2N5458 3 MOTA 2N5484 3 MOTA J202-18 3 NSC SIX MPF4221 3 MOTA MPF4224 3 MOTA PN4221 3 NSC PN4223 3 NSC PN4224 3 NSC THJJ231 3 SPR THJJ230 3 SPR THJJ231 3 SPR TMPF230 3 SPR TMPF231 3 SPR	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J232</b> 2N4869 1 INL 2N5485 1 MOTA J203 1 NSC THJJ232 1 SPR TMPF232 1 SPR 2N4221 3 MOTA 2N4341 3 NSC SIX 2N5245 3 IFC DE451 3 DGE DE459 3 DGE THJ4869 3 SPR THJ5485 3 SPR THJJ203 3 SPR TMPF4869 3 SPR TMPF5485 3 SPR TMPFJ203 3 SPR TP4869 3 SPR	<b>J300E</b> THJJ300E 1 SPR TMPFJ300E 1 SPR
<b>J111A</b> J111 1 INL THJJ111 3 SPR	<b>J114-18</b> 2N5486 3 MOTA J114 3 SIX J204 3 INL	<b>J202-18</b> J202 1 INL 2N3685 3 INL 2N4340 3 INL NSC 2N5457 3 INL MOTA 2N5458 3 MOTA 2N5486 3 MOTA	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J232</b> 2N4869 3 INL 2N5485 3 MOTA 2N5953 3 IFC J203-18 3 NSC	<b>J300F</b> THJJ300F 1 SPR TMPFJ300F 1 SPR
<b>J111A</b> J111 1 INL MPF111 1 MOTA PN4091 1 NSC THJJ111A 1 SPR TMPFJ111A 1 SPR 2N3819 3 IFC 2N5458 3 INL ITE4091 3 INL MPF4091 3 MOTA	<b>J174-18</b> J174 1 INL MOTA MPF970 3 MOTA THJJ174 3 SPR	<b>J202-18</b> J202 1 INL 2N3685 3 INL 2N4340 3 INL NSC 2N5457 3 INL MOTA 2N5458 3 MOTA 2N5486 3 MOTA	<b>J204-18</b> J204 1 INL MOTA PN4220-18 3 NSC	<b>J232</b> 2N4869 3 INL 2N5485 3 MOTA 2N5953 3 IFC J203-18 3 NSC	<b>J300G</b> THJJ300G 1 SPR TMPFJ300G 1 SPR