

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
BC548C (Cont'd) BCW60D 1 PHIN MMBT5088 3 MOTA SCE238 3 MIKG	BC557A (Cont'd) BC549 1 SPR MPS6522C 3 SPR SCE307 3 MIKG	BC584 (Cont'd) BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	BC848C BCW33 1 MOTA SCE238 3 MIKG	BCV26 (Cont'd) TMPTA63 3 SPR TMPTA64 3 SPR	BCW34 (Cont'd) THC2222A 3 SPR TMPT2222A 3 SPR TP2222A 3 SPR TPQ2222A 3 SPR
BC549 BC109 1 SGSI 2N2221 3 MOTA 2N5089 3 MOTA BC108 3 SGSI BC109 3 PHIN BC548 3 PHIN BCF32 3 PHIN DE123 3 DGE DE289A 3 DGE THBC109 3 SPR THBC169 3 SPR THBC319 3 SPR THC5223 3 SPR	BC557B BCW70 1 PHIN THBC557B 1 SPR BCX71H 3 SIEG BF870 3 PHIN MJE350 3 MOTA MPS6523C 3 SPR SCE307 3 MIKG	BC585 BFY76 1 SGSI 2N2484 3 PHIN	BC849 SCE239 1 MIKG	BCV27 MMBTA13 1 MOTA MMBTA14 2 MOTA MPSA13C 3 SPR MPSA14C 3 SPR TMPTA13 3 SPR TMPTA14 3 SPR	BCW35 2N2907A 1 PHIN BSS82C 3 SGSI PN2907A 3 SIEG THC2907A 3 NSC TMPT2907A 3 SPR TP2907A 3 SPR
BC549B BCF32 1 PHIN 2N5089 3 MOTA BC107 3 SGSI BC184L 3 SPR THBC184 3 SPR	BC558 BC478 1 SGSI BC858A 1 PHIN THBC558 1 SPR BC177 3 SGSI BC178 3 PHIN	BC586 BC177 1 SGSI BC875A 3 PHIN SGSI BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	BC856A MMBTA55 1 MOTA BC477 3 SGSI BC856B 3 SIEG BCX42 3 SIEG PMBTA55 3 APX THBC556 3 SPR	BCV28 MXTA64 1 MOTA	BCW36 2N2222A 1 PHIN BSS79C 3 SGSI DE102A 3 DGE DE123A 3 DGE GES2222A 3 GESY PN2222A 3 NSC THC2222A 3 SPR TMPT2222A 3 SPR TPQ2222A 3 SPR
BC549C BCF33 1 PHIN BCW60D 3 SIEG BCY59 3 SGSI DE123AP 3 DGE THC5089 3 SPR TMPT5089 3 SPR	BC559 BC179 3 SGSI BC107 3 PHIN BCW29 3 MOTA BSS80B 3 SIEG BSX29 3 SGSI DE159 3 DGE DE234 3 DGE PN200 3 NSC PN5139-18 3 NSC THC4060 3 SPR THC4125 3 SPR THC5139 3 SPR TMPT4125 3 SPR TP5139 3 SPR	BC587 BCX55 1 PHIN THBC637 1 SPR 2N5320 3 RCA BFY56 3 SGSI BFY76 3 SGSI DE128 3 DGE GES3569 3 GESY PN3569-5 3 NSC THC3569 3 SPR TP3569 3 SPR	BC856B MMBTA55 2 MOTA MMBTA56 2 MOTA BCX42 3 SIEG MPSA55C 3 SPR MPSA56C 3 SPR PMBTA55 3 APX PMBTA56 3 APX TMPTA55 3 SPR TMPTA56 3 SPR	BCV29 MXTA14 1 MOTA	BCW37 2N2907A 1 PHIN BSS82C 3 SIEG PN2907A 3 NSC THC2907A 3 SPR TMPT2907A 3 SPR TP2907A 3 SPR
BC550 BC107 1 SGSI BC108 3 SGSI BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC413 3 SPR THBC414 3 SPR	BC558A BCW29 1 PHIN BCW61A 1 PHIN THBC558A 1 SPR BC177 3 SGSI BC178 3 SGSI BC178A 3 PHIN DE234 3 DGE SCE308 3 MIKG THC4061 3 SPR THC4288 3 SPR	BC588 BCX56 1 PHIN THBC639 1 SPR 2N2102 3 RCA 2N2405 3 RCA BC141 3 SGSI BC300 3 SGSI BCY59 3 SGSI BF258 3 SGSI D44T1 3 GESY	BC857A BCW69 1 MOTA SCE307 3 MIKG	BCV30 BCY78 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW38 2N1613 1 SGSI RCA1A01 1 RCA D40D7 3 GESY DE123 3 DGE PN2221A 3 NSC THC1613 3 SPR
BC550C BC850C 1 PHIN BCF81 1 PHIN	BC558B BCW30 1 PHIN BCW61B 1 PHIN BCW61C 1 PHIN THBC558B 1 SPR BC178 3 SGSI BC178B 3 PHIN BC478 3 SGSI DE234 3 DGE SCE308 3 MIKG THC4059 3 SPR THC4062 3 SPR	BC589 BCX56 1 PHIN THBC640 1 SPR 2N4036 3 RCA 2N4037 3 RCA BC161 3 SGSI BC303 3 SGSI BC477 3 SGSI	BC857B BCW70 1 MOTA BCX71H 3 SIEG SCE307 3 MIKG	BCV31 BCY79 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW39 40362 1 RCA BFX41 1 SGSI 2N2904A 3 PHIN BD140 3 PHIN D41D8 3 GESY
BC556 BC477 1 SGSI BC856A 1 PHIN THBC556 1 SPR BC177 3 SGSI BC212L 3 SPR BC394 3 SGSI BC640 3 PHIN DE159 3 DGE MMBTA55 3 MOTA MPS8598 3 MOTA PN4249-18 3 NSC THBC212 3 SPR THC4249 3 SPR	BC559A BCW61D 1 PHIN	BC590 BCX52 1 PHIN THBC638 1 SPR BC160 3 SGSI	BC857C BCW70 1 MOTA BCX71H 3 SIEG SCE307 3 MIKG	BCV32 BCY79 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW40 40362 1 RCA BFX41 1 SGSI 2N2904A 3 PHIN BD140 3 PHIN D41D8 3 GESY
BC556A BCW89 1 PHIN THBC556A 1 SPR BC177 3 SGSI BC327 3 PHIN THC4289 3 SPR	BC559B BCW30 1 PHIN BCW61B 1 PHIN BCW61C 1 PHIN THBC558B 1 SPR BC178 3 SGSI BC178B 3 PHIN BC478 3 SGSI DE234 3 DGE SCE308 3 MIKG THC4059 3 SPR THC4062 3 SPR	BC591 BCX56 1 PHIN THBC639 1 SPR 2N2102 3 RCA 2N2405 3 RCA BC141 3 SGSI BC300 3 SGSI BCY59 3 SGSI BF258 3 SGSI D44T1 3 GESY	BC857D BCW70 1 MOTA BCX71H 3 SIEG SCE307 3 MIKG	BCV33 BCY79 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW41 40362 1 RCA BFX41 1 SGSI 2N2904A 3 PHIN BD140 3 PHIN D41D8 3 GESY
BC557 BC478 1 SGSI BC875A 1 PHIN BCX71G 1 PHIN BCX71H 1 PHIN BCX71J 1 PHIN BCX71K 1 PHIN THBC557 1 SPR 2N3250 3 MOTA 2N3251 3 MOTA BC117 3 PHIN BC177 3 PHIN SGSI BCX71C 3 PHIN SIEG BCX71D 3 SIEG BCY78 3 SGSI BCY79 3 SGSI DE159 3 DGE DE234 3 DGE MMBT3906 3 MOTA MMBTA70 3 MOTA MPS3702 3 GESY MPS3703 3 GESY PN200 3 NSC PN4250-18 3 NSC THBC213 3 SPR THBC257 3 SPR THC3702 3 SPR THC3703 3 SPR THC4250 3 SPR THC5086 3 SPR TMPT5086 3 SPR	BC559C BC479 1 SGSI BC859A 1 PHIN 2N5087 3 MOTA BC159 3 PHIN BC179 3 PHIN SGSI BC214L 3 SPR BC557 3 PHIN THBC214 3 SPR	BC592 BCX52 1 PHIN THBC638 1 SPR BC160 3 SGSI	BC857E BCW70 1 MOTA BCX71H 3 SIEG SCE307 3 MIKG	BCV34 BCY79 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW42 40362 1 RCA BFX41 1 SGSI 2N2904A 3 PHIN BD140 3 PHIN D41D8 3 GESY
BC557A BCW69 1 PHIN	BC559D BCF29 1 PHIN BC179A 3 PHIN	BC593 BCX56 1 PHIN THBC639 1 SPR 2N2102 3 RCA 2N2405 3 RCA BC141 3 SGSI BC300 3 SGSI BCY59 3 SGSI BF258 3 SGSI D44T1 3 GESY	BC857F BCW70 1 MOTA BCX71H 3 SIEG SCE307 3 MIKG	BCV35 BCY79 1 SGSI BC859A 3 PHIN BCF29 3 PHIN BCF30 3 PHIN	BCW43 40362 1 RCA BFX41 1 SGSI 2N2904A 3 PHIN BD140 3 PHIN D41D8 3 GESY