

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>BC153</b> BC177 1 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	<b>BC171</b> (Cont'd) BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR <b>BC172</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR <b>BC173</b> 2N5089 1 MOTA BC109 1 SGSI BC549 1 PHIN BC549C 3 PHIN BCF32 3 PHIN BCW60D 3 SIEG BCY59 3 SGSI DE123AP 3 DGE THBC109 3 SPR THC5089 3 SPR TMPT5089 3 SPR <b>BC174</b> BFY76 1 SGSI MPS8096 1 MOTA 2N2484 3 PHIN MPS8098C 3 SPR <b>BC174A</b> 2N2219A 1 PHIN GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR <b>BC174B</b> 2N2219A 1 PHIN GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR <b>BC177A</b> BC875A 1 PHIN BCX71G 1 PHIN BCX71H 1 PHIN BCX71J 1 PHIN BCX71K 1 PHIN THBC177 1 SPR 2N2907A 3 PHIN 2N5087 3 MOTA BC178 3 SGSI BC212L 3 SPR BC327 3 PHIN BC328 3 PHIN BC477 3 SGSI BC556 3 PHIN BC556A 3 PHIN BC557 3 PHIN BC558 3 PHIN BC558A 3 PHIN BCW70 3 MOTA BCY72 3 PHIN DE159 3 DGE DE234 3 DGE GES4248 3 GESY MMBT3906 3 MOTA MMBT470 3 MOTA MPS8598 3 MOTA PN4248-18 3 NSC PN4249-18 3 NSC SC307 3 MIKG THBC212 3 SPR THBC257 3 SPR THBC307 3 SPR THC4058 3 SPR THC4060 3 SPR THC4061 3 SPR THC4248 3 SPR THC4249 3 SPR THC4289 3 SPR <b>BC177A</b> THBC177A 1 SPR <b>BC177B</b> THBC177B 1 SPR <b>BC178</b> BC858A 1 PHIN THBC178 1 SPR 2N5087 3 MOTA BC177 3 PHIN BC179 3 SGSI BC213L 3 SPR BC328 3 PHIN BC557 3 PHIN BC558 3 PHIN BC558A 3 PHIN BCW29 3 MOTA DE159 3 DGE THBC183 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC182 3 SPR <b>BC182A</b> BC182A 2 THBC182A 3 SPR <b>BC182B</b> BC182B 2 THBC182B 3 SPR <b>BC183</b> BC107 1 SGSI BC183L 1 SPR BC547 1 PHIN BC548 3 PHIN MPS8598 3 MOTA THBC182 3 SPR <b>BC182A</b> BC182A 2 THBC182A 3 SPR <b>BC182B</b> BC182B 2 THBC182B 3 SPR <b>BC183</b> BC107 1 SGSI BC183L 1 SPR BC547 1 PHIN THBC183 3 PHIN BCX71J 3 PHIN THBC177 3 SPR THBC178 3 SPR THBC557 3 SPR <b>BC183A</b> BC183A 1 SPR THBC183A 1 SPR	<b>BC178</b> (Cont'd) THC4288 3 SPR <b>BC178A</b> BCW29 1 PHIN THBC178A 1 SPR BC558A 3 PHIN SCE308 3 MIKG <b>BC178B</b> BCW30 1 PHIN THBC178B 1 SPR BC558B 3 PHIN SCE308 3 MIKG <b>BC178C</b> THBC178C 1 SPR <b>BC179</b> BC859A 1 PHIN BCF29 1 PHIN THBC179 1 SPR 2N5087 3 MOTA BC178 3 PHIN BC214L 3 SPR BC327-16 3 PHIN BC328 3 PHIN BC558 3 PHIN BC559 3 PHIN DE290 3 DGE PN200 3 NSC PN4258-18 3 NSC SC309 3 MIKG THBC214 3 SPR THBC259 3 SPR THBC309 3 SPR THC4290 3 SPR THC4291 3 SPR <b>BC179A</b> BC559A 3 PHIN <b>BC179B</b> THBC179B 1 SPR BC559B 3 PHIN <b>BC179C</b> THBC179C 1 SPR <b>BC180</b> BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC547 3 SPR <b>BC181</b> BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR <b>BC182</b> BC107 1 SGSI BC182L 1 SPR BC548 1 PHIN MPS8598 1 MOTA THBC182 1 SPR BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN MPS8598C 3 SPR THBC107 3 SPR THBC548 3 SPR <b>BC182A</b> BC182LA 1 SPR THBC182A 1 SPR <b>BC182B</b> BC182LB 1 SPR THBC182B 1 SPR <b>BC182L</b> BC182 2 BC107 3 SGSI BC548 3 PHIN MPS8598 3 MOTA THBC182 3 SPR <b>BC182A</b> BC182A 2 THBC182A 3 SPR <b>BC182B</b> BC182B 2 THBC182B 3 SPR <b>BC183</b> BC107 1 SGSI BC183L 1 SPR BC547 1 PHIN THBC183 3 PHIN BCX71J 3 PHIN THBC177 3 SPR THBC178 3 SPR THBC557 3 SPR <b>BC183A</b> BC183LA 1 SPR THBC183A 1 SPR	<b>BC183B</b> BC183LB 1 SPR THBC183B 1 SPR <b>BC183C</b> BC183LC 1 SPR THBC183C 1 SPR <b>BC183L</b> BC183 2 BC107 3 SGSI BC547 3 PHIN THBC183 3 SPR <b>BC183LA</b> BC183A 2 THBC183A 3 SPR <b>BC183LB</b> BC183B 2 THBC183B 3 SPR <b>BC183LC</b> BC183C 2 THBC183C 3 SPR <b>BC184</b> 2N5089 1 MOTA BC107 1 SGSI BC184L 1 PHIN THBC184 1 SPR BC549B 3 PHIN THBC184 1 SPR BCF32 3 PHIN BCW60D 3 SIEG BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN BCY59 3 SGSI DE123AP 3 DGE THBC107 3 SPR THC5089 3 SPR TMPT5089 3 SPR <b>BC184B</b> BC184LB 1 SPR THBC184B 1 SPR <b>BC184C</b> BC184LC 1 SPR THBC184C 1 SPR <b>BC184L</b> BC184 2 2N5089 3 MOTA BC107 3 SGSI BC549B 3 PHIN THBC184 3 SPR <b>BC184LB</b> BC184B 2 THBC184B 3 SPR <b>BC184LC</b> BC184C 2 THBC184C 3 SPR <b>BC185</b> 2N2219 1 PHIN 2N3053 1 RCA BC301 1 SGSI 2N699 3 RCA BCX55-10 3 SIEG BD139 3 PHIN BSS79C 3 SIEG D40D7 3 GESY DE128 3 DGE GES2219 3 GESY GES3053 3 GESY THC2219 3 SPR THC3053 3 SPR TN2219 3 NSC TP2219 3 SPR <b>BC186</b> BC177 1 PHIN SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR <b>BC187</b> BC177 1 PHIN BC178 1 SGSI BC557 1 PHIN BC478 3 SGSI BC858A 3 PHIN BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR <b>BC187</b> BC177 1 PHIN BC178 1 SGSI BC557 1 PHIN BC478 3 SGSI BC858A 3 PHIN BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC178 3 SPR THBC557 3 SPR <b>BC190</b> BC107 1 SGSI BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN	<b>BC190</b> (Cont'd) THBC107 3 SPR <b>BC190A</b> BC107A 1 PHIN BC547A 1 PHIN BCW71 3 PHIN THBC107A 3 SPR THBC547A 3 SPR <b>BC190B</b> BC107B 1 PHIN BC547B 1 PHIN BCW72 3 PHIN THBC107B 3 SPR THBC547B 3 SPR <b>BC192</b> BC298 1 SGSI BC328 1 PHIN BCX18 3 PHIN THBC328 3 SPR <b>BC194</b> BC337 1 PHIN BC377 3 SGSI BCX19 3 PHIN THBC337 3 SPR <b>BC196</b> BC200-01 1 PHIN <b>BC197</b> BC146-01 1 PHIN <b>BC198</b> BC146-01 1 PHIN <b>BC200</b> BC179 1 SGSI BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR <b>BC201</b> BC200-01 1 PHIN <b>BC202</b> BC200-01 1 PHIN <b>BC203</b> BC200-01 1 PHIN <b>BC204</b> BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR <b>BC205</b> BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR <b>BC206</b> BC179 1 SGSI BC559 1 PHIN BC479 3 SGSI BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR <b>BC207</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR <b>BC208</b> BC108 1 SGSI BC548 1 PHIN BC549 1 PHIN BC109 3 SGSI THBC108 3 SPR THBC548 3 SPR <b>BC209</b> BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR <b>BC210</b> 2N2222 1 PHIN BC377 1 SGSI BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR <b>BC211</b> BC141 1 SGSI BSX61 1 PHIN 2N3725 3 SGSI 2N5320 3 RCA 2N5321 3 RCA D40D4 3 GESY D40D7 3 GESY	<b>BC212</b> BC177 1 SGSI BC212L 1 SPR BC556 1 PHIN MPS8598 1 MOTA THBC212 1 SPR BC477 3 SGSI BC856A 3 PHIN BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN MPS8598C 3 SPR THBC177 3 SPR THBC556 3 SPR <b>BC212A</b> BC212LA 1 SPR THBC212A 1 SPR <b>BC212B</b> BC212LB 1 SPR THBC212B 1 SPR <b>BC212L</b> BC212 2 BC177 3 SGSI BC556 3 PHIN MPS8598 3 MOTA THBC212 3 SPR <b>BC212LA</b> BC212A 2 THBC212A 3 SPR <b>BC212LB</b> BC212B 2 THBC212B 3 SPR <b>BC213</b> BC178 1 SGSI BC213L 1 SPR BC557 1 PHIN THBC213 1 SPR BC478 3 SGSI BC858A 3 PHIN BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC178 3 SPR THBC557 3 SPR <b>BC213A</b> BC213LA 1 SPR THBC213A 1 SPR <b>BC213B</b> BC213LB 1 SPR THBC213B 1 SPR <b>BC213C</b> BC213LC 1 SPR THBC213C 1 SPR <b>BC213L</b> BC213 2 BC178 3 SGSI BC557 3 PHIN THBC213 3 SPR <b>BC213LA</b> BC213A 2 THBC213A 3 SPR <b>BC213LB</b> BC213B 2 THBC213B 3 SPR <b>BC213LC</b> BC213C 2 THBC213C 3 SPR <b>BC214</b> 2N5087 1 MOTA BC179 1 SGSI BC214L 1 SPR BC559 1 PHIN THBC214 1 SPR BC479 3 SGSI BC859A 3 PHIN BCF29 3 PHIN BCX71C 3 SIEG BCX71D 3 SIEG BCY79 3 SGSI DE159 3 DGE PN200 3 NSC THBC179 3 SPR THC5087 3 SPR TMPT5087 3 SPR <b>BC214A</b> BC214LA 1 SPR THBC214A 1 SPR <b>BC214B</b> BC214LB 1 SPR THBC214B 1 SPR <b>BC214C</b> BC214LC 1 SPR THBC214C 1 SPR <b>BC214L</b> BC214 2 2N5087 3 MOTA BC179 3 SGSI BC559 3 PHIN THBC214 3 SPR	