

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N5454</b> (Cont'd)	<b>2N5458</b> (Cont'd)	<b>2N5459</b> (Cont'd)	<b>2N5466</b> (Cont'd)	<b>2N5476</b> (Cont'd)	<b>2N5484</b> (Cont'd)
MP3958 3 MPS	2N4303 3 SIX	2N5486 3 MOTA	BUS12 3 APX	THJ5020 3 SPR	TMFFBF244A 3 SPR
THJ5046 3 SPR	2N4304 3 SIX	2N5640 3 MOTA	BUS22 3 APX	TMFF5020 3 SPR	TMFFBF256A 3 SPR
THJ5047 3 SPR	2N4338 3 INL	2N5950 3 IFC	BUX11 3 PHIN	TP5020 3 SPR	TMFFJ305 3 SPR
THJ5546 3 SPR	2N4339 3 INL	2N5951-18 3 NSC	D64VE3 3 GESY	<b>2N5477</b>	TP5246 3 SPR
U233 3 SIX	2N4340 3 SIX		D64VP5 3 GESY	2N5347 1 MOTA	TP5668 3 SPR
U234 3 SIX	2N4416 3 INL	2N5952 3 IFC	TIP537 3 TII	2N3926 3 MOTA	TP5952 3 SPR
U410 3 SIX	2N4868 3 INL	2N5953 3 IFC	TIP556 3 TII	2N3927 3 MOTA	TP5953 3 SPR
<b>2N5455</b>	2N5246 3 IFC	A5T3822 3 IFC	TIP559 3 TII	2N5071 3 MOTA	<b>2N5484-18</b>
DE159 1 DGE	2N5338 3 MOTA	BF245B 3 PHIN	TIP560 3 TII	BLY93A 3 PHIN	2N5484 3 INL
<b>2N5457</b>	2N5457 3 INL	DE457 3 DGE	TIP561 3 TII	D44C7 3 GESY	SIX
2N5953 1 IFC	2N5458-18 3 NSC	J105-18 3 SIX	<b>2N5467</b>	D44VM10 3 GESY	<b>2N5485</b>
BF245A 1 PHIN	SIX	J112 3 INL	2N6545 1 MOTA	SD1014 3 THCS	2N5245 1 IFC
DE451 1 DGE	2N5459 3 SIX	J203 3 INL	2N6671 1 RCA	<b>2N5478</b>	DE451 1 DGE
THJ5457 1 SPR	MOTA	J203-18 3 NSC	DE283 1 DGE	2N5347 1 MOTA	THJ5485 1 SPR
TMFF5457 1 SPR	2N5484 3 INL	SIX	2N6544 3 MOTA	D44VM10 3 GESY	TMFF5485 1 SPR
2N3459 3 IFC	2N5486 3 MOTA	J232-18 3 SIX	2N6673 3 MOTA	<b>2N5479</b>	2N3822 3 INL
NSC	2N5466 3 MOTA	J309 3 MOTA	BUS12 3 APX	2N5349 1 MOTA	2N4416 1 IFC
SIX	2N5640 3 MOTA	PN4092 3 NSC	BUS22 3 APX	D44VM10 3 GESY	2N4869 3 INL
2N3460 3 IFC	2N5950 3 IFC	PN4221-18 3 NSC	BUX81 3 PHIN	<b>2N5480</b>	2N5078 3 NSC
2N3684 3 INL	2N5951 3 IFC	PN4222 3 NSC	D64VE3 3 GESY	2N5349 1 MOTA	SIX
SIX	2N5952-18 3 NSC	PN4222-18 3 NSC	D64VP5 3 GESY	D44VM10 3 GESY	2N5245-18 3 SIX
2N3687 3 INL	SIX	PN4303 3 NSC	TIP537 3 TII	<b>2N5482</b>	2N5248-18 3 NSC
SIX	2N5953 3 IFC	PN4303-18 3 NSC	TIP556 3 TII	D40D1 1 GESY	2N5397 3 INL
2N3821 3 INL	A5T3821 3 IFC	PN4304 3 NSC	TIP559 3 TII	<b>2N5483</b>	NSC
NSC	A5T3822 3 IFC	PN4416 3 SIX	TIP560 3 TII	D44C1 1 GESY	SIX
SIX	A5T6449 3 IFC	THJ4303 3 SPR	TIP561 3 TII	2N6288 3 RCA	2N5459 3 MOTA
2N4220 3 INL	A5T6450 3 IFC	THJ5951 3 SPR	<b>2N5470</b>	BD239 3 RCA	2N5484 3 INL
2N4221 3 MOTA	BF245A 3 PHIN	THJJ112A 3 SPR	D40D7 1 GESY	BU407 3 APX	MOTA
2N4302 3 INL	DE457 3 DGE	TIS59 3 TII	<b>2N5471</b>	ST44C1 3 STI	2N5485-18 3 NSC
SIX	J113 3 INL	TMPP4303 3 SPR	2N5020 1 NSC	<b>2N5484</b>	SIX
2N4338 3 INL	J202 3 INL	TMPP5951 3 SPR	SIX	2N5246 1 IFC	2N5486 3 INL
SIX	J202-18 3 NSC	TMPPF1112A 3 SPR	2N5265 1 INL	DE180 1 DGE	SIX
2N4339 3 INL	SIX	TP4303 3 SPR	2N2607 3 INL	THJ5484 1 SPR	2N5951 3 IFC
2N4340 3 NSC	J203-18 3 SIX	TP5951 3 SPR	2N2808 3 SIX	TMPP5484 1 SPR	2N5952 3 IFC
SIX	J231-18 3 SIX	<b>2N5459-18</b>	2N2843 3 INL	2N3819 3 IFC	BF245B 3 PHIN
2N4341 3 SIX	J305 3 SIX	2N3458 3 IFC	2N3929 3 MOTA	SIX	BF512 3 PHIN
2N4416 3 INL	J305-18 3 SIX	2N3458 3 IFC	2N5265 3 MOTA	2N3819-18 3 NSC	BF513 3 PHIN
2N4867 3 INL	J309 3 MOTA	2N5459 3 INL	DE460 3 DGE	2N3821 3 NSC	DE129 3 DGE
2N4868 3 INL	MPF102 3 MOTA	<b>2N5460</b>	THJ5020 3 SPR	2N3822 3 INL	ITE4416 3 INL
2N4868A 3 INL	PN3684-18 3 NSC	DE326 1 DGE	TMPPF5020 3 SPR	J203 3 NSC	J203 3 NSC
2N5457-18 3 NSC	PN3685-18 3 NSC	MRF454 1 MOTA	TP5020 3 SPR	J211 3 SIX	J211 3 SIX
SIX	PN4093 3 NSC	THJ5460 1 SPR	<b>2N5472</b>	J211-18 3 NSC	J211-18 3 NSC
2N5458 3 MOTA	PN4221 3 NSC	TMPP5460 1 SPR	2N5020 1 NSC	SIX	J305 3 SIX
2N5459 3 INL	PN4221-18 3 NSC	2N2808 3 SIX	2N5265 1 INL	2N4867 3 INL	J305-18 3 NSC
2N5484 3 INL	PN4302-18 3 NSC	2N2808-18 3 NSC	2N2608 3 INL	2N4868 3 INL	MPF4416 3 MOTA
2N5640 3 MOTA	PN4303 3 NSC	2N5019 3 INL	2N2843 3 INL	2N5246-18 3 NSC	PN4416 3 SIX
2N5952-18 3 SIX	PN4303-18 3 NSC	2N5516 3 INL	2N3299 3 SIX	SIX	THJ5245 3 SPR
2N5953-18 3 NSC	PN4304 3 NSC	A5T5460 3 IFC	2N5265 3 MOTA	2N5397 3 INL	THJ5669 3 SPR
SIX	PN4304 3 NSC	A5T5462 3 IFC	DE460 3 DGE	2N5457 3 MOTA	THJBF244B 3 SPR
A5T3821 3 IFC	PN4304-18 3 NSC	P1087-18 3 NSC	THJ5020 3 SPR	2N5458 3 MOTA	THJ232 3 SPR
A5T3822 3 IFC	PN5163-18 3 NSC	PN4360-18 3 NSC	TMPPF5020 3 SPR	2N5459 3 MOTA	TMPPF232 3 SPR
J201 3 INL	SIX	PN5033-18 3 NSC	TP5020 3 SPR	2N5484-18 3 NSC	TMPPF5245 3 SPR
J201-18 3 NSC	THJ4304 3 SPR	SIX	<b>2N5473</b>	SIX	TMPPF5669 3 SPR
SIX	THJ5163 3 SPR	SIX	2N5020 1 NSC	2N5485 3 INL	TMPPFB244B 3 SPR
J202-18 3 NSC	THJ5952 3 SPR	SD1405 3 THCS	2N5265 1 INL	TP5245 3 MOTA	TP5669 3 SPR
SIX	THJBC264B 3 SPR	SX3820 3 TII	2N2607 3 INL	2N5486 3 MOTA	2N5485-18 3 IFC
J204 3 INL	THJBC264C 3 SPR	THJ5033 3 SPR	2N2608 3 INL	2N5555 3 INL	2N5485 3 INL
J230-18 3 SIX	THJJ113A 3 SPR	THJP1087 3 SPR	SIX	SIX	SIX
J305 3 SIX	TIS58 3 TII	TMPPF1087 3 SPR	2N2843 3 INL	2N5640 3 MOTA	ITE4416 3 INL
MPF4393 3 MOTA	TMPPF4304 3 SPR	TMPPF5033 3 SPR	2N3329 3 SIX	2N5949 3 IFC	MPF4393 3 MOTA
PN3684-18 3 NSC	TMPPF5163 3 SPR	TP5033 3 SPR	2N5265 3 MOTA	2N5952 3 IFC	<b>2N5486</b>
PN3686 3 NSC	TMPPF5952 3 SPR	<b>2N5461</b>	DE460 3 DGE	2N5952-18 3 NSC	2N5247 1 IFC
PN3686-18 3 NSC	TMPPF5952 3 SPR	DE326 1 DGE	THJ5020 3 SPR	SIX	THJ5486 1 SPR
PN3687 3 NSC	TMPPF5952 3 SPR	THJ5461 1 SPR	TMPPF5020 3 SPR	2N5953 3 IFC	TMPPF5486 1 SPR
PN3821-18 3 NSC	TMPPF5952 3 SPR	TMPPF5461 1 SPR	TP5020 3 SPR	2N5953-18 3 NSC	2N3460 3 IFC
PN4220 3 NSC	TMPPF5952 3 SPR	2N3994 3 IFC	<b>2N5474</b>	SIX	2N3686 3 INL
PN4220-18 3 NSC	TP4304 3 SPR	2N5115 3 INL	2N5020 1 NSC	BF245A 3 PHIN	2N3687 3 INL
PN4221-18 3 NSC	TP5163 3 SPR	2N5398 3 INL	SIX	BF245C 3 PHIN	2N3819 3 IFC
PN4302 3 NSC	TP5952 3 SPR	2N5462 3 IFC	2N5265 1 INL	DE132 3 DGE	2N3822 3 INL
SIX	TPBC264B 3 SPR	P1086-18 3 NSC	2N2607 3 INL	DE457 3 DGE	2N3824 3 MOTA
PN4302-18 3 NSC	TPBC264C 3 SPR	SIX	J202 3 NSC	J210 3 SIX	SIX
SIX	<b>2N5458-18</b>	PN4342-18 3 NSC	J210-18 3 NSC	J210-18 3 NSC	2N4338 3 INL
SX3819 3 TII	2N3459 3 IFC	THJP1086 3 SPR	J305 3 MOTA	J305 3 NSC	NSC
THJ5953 3 SPR	2N5458 3 INL	TMPPF1086 3 SPR	2N5486 3 MOTA	2N5485 3 INL	2N4339 3 INL
THJBC264A 3 SPR	<b>2N5459</b>	<b>2N5462</b>	2N5555 3 INL	SIX	NSC
TIS58 3 TII	2N5951 1 IFC	DE326 1 DGE	2N5640 3 MOTA	2N5640 3 MOTA	NSC
TMPPF5953 3 SPR	BF245C 1 PHIN	THJ5462 1 SPR	2N5949 3 IFC	2N5952 3 IFC	NSC
TMPPFBC264A 3 SPR	DE451 1 DGE	TMPPF5462 1 SPR	2N5952 3 IFC	2N5952-18 3 NSC	NSC
TP5953 3 SPR	THJ5459 1 SPR	2N2809 3 INL	2N5953 3 IFC	2N5953-18 3 NSC	NSC
TPBC264A 3 SPR	TMPPF5459 1 SPR	2N3909 3 SIX	2N5952-18 3 NSC	BF245A 3 PHIN	2N4338 3 INL
<b>2N5457-18</b>	2N3458 3 IFC	2N3993 3 IFC	2N5952-18 3 NSC	DE132 3 DGE	2N4339 3 INL
2N3459 3 IFC	2N3823 3 NSC	2N4342 3 MOTA	2N5952-18 3 NSC	DE457 3 DGE	NSC
2N5457 3 INL	SIX	2N5398 3 INL	2N5952-18 3 NSC	J210 3 SIX	SIX
MOTA	2N4303 3 SIX	2N5461 3 NSC	2N5952-18 3 NSC	J210-18 3 NSC	2N4338 3 INL
SIX	2N4339 3 INL	SIX	2N5952-18 3 NSC	J305 3 MOTA	NSC
<b>2N5458</b>	2N4416 3 INL	THJBC264B 3 SPR	2N5952-18 3 NSC	2N5486 3 MOTA	NSC
2N5952 1 IFC	2N4869 3 INL	THJBC264C 3 SPR	2N5952-18 3 NSC	2N5555 3 INL	NSC
BF245B 1 PHIN	2N4869A 3 INL	THJJP1087 3 SPR	2N5952-18 3 NSC	2N5640 3 MOTA	NSC
DE451 1 DGE	2N4869 3 INL	TMPPF1087 3 SPR	2N5952-18 3 NSC	2N5952 3 IFC	NSC
THJ5458 1 SPR	2N4869 3 INL	TMPPF5033 3 SPR	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
TMPPF5458 1 SPR	2N4869 3 INL	TP5033 3 SPR	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3459 3 IFC	2N4869 3 INL	<b>2N5461</b>	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3685 3 INL	2N4869 3 INL	SX3820 3 TII	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
SIX	2N4869 3 INL	<b>2N5462-5</b>	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3819 3 IFC	2N4869 3 INL	2N2608 3 INL	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
SIX	2N4869 3 INL	2N2609 3 SIX	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3822 3 INL	2N4869 3 INL	<b>2N5463</b>	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
NSC	2N4869 3 INL	DE326 1 DGE	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
SIX	2N4869 3 INL	<b>2N5464</b>	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3955A 3 INL	2N4869 3 INL	DE326 1 DGE	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N3956 3 INL	2N4869 3 INL	<b>2N5466</b>	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
2N4302 3 SIX	2N4869 3 INL	2N6545 1 MOTA	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
	2N4869 3 INL	2N6671 1 RCA	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
	2N4869 3 INL	DE283 1 DGE	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
	2N4869 3 INL	2N6544 3 MOTA	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC
	2N4869 3 INL	2N6673 3 RCA	2N5952-18 3 NSC	2N5952-18 3 NSC	NSC