

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N2195</b> (Cont'd)	<b>2N2206</b> (Cont'd)	<b>2N2218A</b> (Cont'd)	<b>2N2221</b> (Cont'd)	<b>2N2222A</b>	<b>2N2243A</b> (Cont'd)
2N2219 1 MOTA	DE123AP 3 DGE	RC1A101 3 RCA	40317 3 RCA	BSS79C 1 SIEG	D38H4 3 GESY
BS2218 1 SGSI	THC3903 3 SPR	RC1A103 3 RCA	BC107 3 PHIN	DE102A 1 DGE	D42T1 3 GESY
DE128 1 DGE	TMPT3903 3 SPR	THC3642 3 SPR	BC109 3 PHIN	DE123A 1 DGE	DE128 3 DGE
THC2195 1 SPR	<b>2N2207</b>	TP3642 3 SPR	BC547 3 PHIN	GES2222A 1 GESY	THC3020 3 SPR
2N1613 3 SGSI	DE126A 1 DGE	<b>2N2219</b>	BC549 3 PHIN	PN2222A 1 NSC	TN3020 3 NSC
2N4400 3 NSC	<b>2N2208</b>	DE128 1 DGE	BCX70G 3 SIEG	THC2222A 1 SPR	<b>2N2244</b>
D40D5 3 GESY	DE126A 1 DGE	GES2219 1 GESY	BF185 3 PHIN	TMPT2222A 1 SPR	DE123A 1 DGE
D40D7 3 GESY	<b>2N2210</b>	THC2219 1 SPR	BF495 3 PHIN	TP2222A 1 SPR	<b>2N2250</b>
DE126 3 DGE	DE105 1 DGE	TN2219 1 NSC	BFY55 3 PHIN	TPQ2222A 1 SPR	DE123A 1 DGE
GES2219 3 GESY	<b>2N2212</b>	TP2219 1 SPR	BSS26 3 SGSI	2B2222A 3 SGSI	<b>2N2251</b>
PN2222A 3 NSC	DE121 1 DGE	2N697 3 RCA	BSS79C 3 SIEG	2N2221 3 SGSI	DE123A 1 DGE
THC697 3 SPR	<b>2N2217</b>	2N1711 3 PHIN	BSW41A 3 PHIN	2N4401 3 MOTA	<b>2N2252</b>
THC1711 3 SPR	2N697 1 RCA	2N2218 3 PHIN	BSX19 3 PHIN	BC337 3 PHIN	DE123A 1 DGE
THC2219 3 SPR	2N2218 1 MOTA	PHIN 3 PHIN	D40D1 3 GESY	BCX70G 3 SIEG	<b>2N2253</b>
TN2219 3 NSC	PHIN 3 PHIN	SGSI 3 SGSI	D40E5 3 GESY	BSR14 3 APX	DE123A 1 DGE
TP2219 3 SPR	BS2218 1 SGSI	2N2218A 3 PHIN	D40E5 3 GESY	BSS26 3 SGSI	<b>2N2254</b>
<b>2N2195A</b>	D40E5 1 GESY	2N2221A 3 PHIN	DE123 3 DGE	D40D1 3 GESY	DE123A 1 DGE
2N697 1 RCA	DE128 1 DGE	2N2221A 3 MOTA	DE123AP 3 DGE	DE123AP 3 DGE	<b>2N2255</b>
2N2219 1 MOTA	2N1613 3 SGSI	PHIN 3 PHIN	DE128 3 DGE	DE199 3 DGE	DE123A 1 DGE
THC2195A 1 SPR	2N1711 3 PHIN	2N3053 3 RCA	DE154 3 DGE	MMBT2222A 3 MOTA	<b>2N2256</b>
2N1613 3 SGSI	2N4400 3 NSC	2N3553 3 MOTA	GES2221 3 GESY	MMBT3904 3 MOTA	2N706 1 MOTA
2N1711 3 PHIN	D40D7 3 GESY	2N4401 3 NSC	MMBT4123 3 MOTA	MMBT4401 3 MOTA	2N3903 1 GESY
2N4400 3 NSC	DE126 3 DGE	2N5681 3 MOTA	MPS2221 3 GESY	MPS3704 3 GESY	BC108 1 PHIN
D40D7 3 GESY	GES2218 3 GESY	2N5859 3 MOTA	MPS6532C 3 SPR	MPS3705 3 GESY	BC548 1 PHIN
DE126 3 DGE	THC697 3 SPR	BC140 3 SGSI	PN100 3 NSC	MPS6531C 3 SPR	DE123A 1 DGE
DE128 3 DGE	THC2218 3 SPR	BC301 3 SGSI	THC3115 3 SPR	MPS6566C 3 SPR	2N2222 3 SGSI
GES2219 3 GESY	TN2218 3 NSC	BFY50 3 PHIN	THC3904 3 SPR	MPSA05 3 MOTA	BC108 3 SGSI
THC697 3 SPR	TP2218 3 SPR	BFY55 3 PHIN	TMPT3904 3 SPR	PMBT2222A 3 APX	BC548A 3 PHIN
THC2219 3 SPR	<b>2N2218</b>	BS2218 3 SGSI	<b>2N2221A</b>	PN100 3 NSC	BSX19 3 PHIN
TN2219 3 NSC	2N697 1 RCA	BSX60 3 PHIN	BSS79B 1 SIEG	THC3704 3 SPR	BSX26 3 SGSI
TP2219 3 SPR	DE128 1 DGE	D40D1 3 GESY	GES2221A 1 GESY	THC3705 3 SPR	DE123AP 3 DGE
<b>2N2195B</b>	GES2218 1 GESY	D40D2 3 GESY	THC2221A 1 SPR	THC3904 3 SPR	MP5706 3 NSC
2N2219 1 MOTA	THC2218 1 SPR	D40D4 3 GESY	TMPT2221A 1 SPR	TMPT3904 3 SPR	THBC108 3 SPR
DE128 3 DGE	TN2218 1 NSC	D40D7 3 GESY	TP2221A 1 SPR	<b>2N2223</b>	THC548 3 SPR
GES2219 3 GESY	TP2218 1 SPR	D40E5 3 GESY	2N2222A 3 SGSI	IT122 1 INL	THC3903 3 SPR
THC2219 3 SPR	2N1613 3 SGSI	D44T1 3 GESY	2N720A 3 MOTA	MP310 3 MPS	TMPT3903 3 SPR
TN2219 3 NSC	2N1711 3 PHIN	DE123A 3 DGE	2N740 3 MOTA	<b>2N2223A</b>	<b>2N2257</b>
TP2219 3 SPR	SGSI 3 SGSI	DE123AP 3 DGE	2N2219 3 MOTA	IT121 1 INL	2N3903 1 GESY
<b>2N2196</b>	2N2219 3 MOTA	MPS2221 3 GESY	2N2221 3 MOTA	MP311 3 MPS	BC108 1 PHIN
2N2987 1 GSE	PHIN 3 PHIN	PN3643-5 3 NSC	2N222 3 SGSI	<b>2N2224</b>	BC548 1 PHIN
BSW66 1 PHIN	SGSI 3 SGSI	PN5128-5 3 NSC	2N222 3 PHIN	2N2218 1 MOTA	2N222 3 SGSI
D44C9 1 GESY	2N2219A 3 MOTA	RC1A101 3 RCA	2N3020 3 PHIN	D40D4 1 GESY	BC108 3 SGSI
DE128 1 DGE	2N2221 3 PHIN	RC1A106 3 RCA	2N4400 3 NSC	DE123 1 DGE	BC548A 3 PHIN
2N4238 3 MOTA	SGSI 3 SGSI	THC1420 3 SPR	BC107 3 PHIN	2N697 3 RCA	DE123AP 3 DGE
2N6292 3 RCA	2N2369 3 MOTA	THC2195 3 SPR	BC547 3 PHIN	D40D4C 3 SPR	THBC108 3 SPR
BD239A 3 RCA	2N3053 3 RCA	THC2195A 3 SPR	BFR18 3 SGSI	DE128 3 DGE	THBC548 3 SPR
BU407 3 APX	2N3866 3 PHIN	THC3300 3 SPR	BS2483 3 SGSI	GES2218 3 GESY	THC3903 3 SPR
D44T1 3 GESY	2N4237 3 MOTA	THC3643 3 SPR	BSX20 3 SGSI	THC2218 3 SPR	TMPT3903 3 SPR
ST44C9 3 STI	2N4238 3 MOTA	THC5128 3 SPR	DE123A 3 DGE	TN2218 3 NSC	<b>2N2258</b>
<b>2N2197</b>	2N4400 3 NSC	TP3300 3 SPR	DE154 3 DGE	TP2218 3 SPR	MM2258 1 MOTA
2N2987 1 GSE	40317 3 RCA	TP3643 3 SPR	MMBT4400 3 MOTA	<b>2N2236</b>	D44T2 3 GESY
BD131 1 PHIN	BF115 3 PHIN	<b>2N2219A</b>	MPS6530C 3 SPR	2N2218 1 MOTA	<b>2N2259</b>
D44C8 1 GESY	BF494 3 PHIN	GES2219A 1 GESY	MPS6565 3 NSC	DE123A 1 DGE	MM2259 1 MOTA
DE128 1 DGE	BFY50 3 PHIN	THC2219A 1 SPR	MPS6565C 3 SPR	2N697 3 RCA	D44T2 3 GESY
2N4238 3 MOTA	BFY55 3 PHIN	TN2219A 1 NSC	MPSA05 3 MOTA	DE128 3 DGE	<b>2N2260</b>
2N6292 3 RCA	BS2218 3 SGSI	TP2219A 1 SPR	THC718 3 SPR	GES2218 3 GESY	MM2260 1 MOTA
BD239A 3 RCA	BSX32 3 SGSI	2N699 3 RCA	THC915 3 SPR	THC2218 3 SPR	D44T2 3 GESY
BU407 3 APX	D40D1 3 GESY	2N1711 3 SGSI	<b>2N2222</b>	TN2218 3 NSC	<b>2N2266</b>
D44C5 3 GESY	D40D2 3 GESY	2N2218 3 SGSI	BSS81C 1 SIEG	TP2218 3 SPR	2N2563 1 LTE
ST44C8 3 STI	D40D3 3 GESY	2N2218A 3 PHIN	GES2222 1 GESY	<b>2N2237</b>	DE105 1 DGE
<b>2N2198</b>	D40D4 3 GESY	2N3019 3 MOTA	PN2222 1 NSC	2N2218 1 MOTA	DE176 3 DGE
DE128 1 DGE	D40D7 3 GESY	2N3053 3 RCA	THC2222 1 SPR	DE123A 1 DGE	<b>2N2267</b>
<b>2N2199</b>	D40E5 3 GESY	2N5859 3 MOTA	TMPT2222 1 SPR	2N697 3 RCA	2N2562 1 LTE
DE126A 1 DGE	DE123 3 DGE	BFY50 3 PHIN	TP2222 1 SPR	DE128 3 DGE	DE105 1 DGE
<b>2N2200</b>	DE123A 3 DGE	BFY55 3 PHIN	2N2219 3 PHIN	GES2218 3 GESY	DE176 3 DGE
DE126A 1 DGE	DE126 3 DGE	BS2218A 3 SGSI	2N2221 3 PHIN	THC2218 3 SPR	<b>2N2268</b>
<b>2N2201</b>	PN3641-5 3 NSC	BSX32 3 SGSI	2N2221A 3 MOTA	TN2218 3 NSC	2N2563 1 LTE
2N5681 1 GSE	PN3643-5 3 NSC	D40D2 3 GESY	2N2907A 3 PHIN	TP2218 3 SPR	DE105 1 DGE
MOTA 1 MOTA	RC1A101 3 RCA	D40D3 3 GESY	2N4400 3 NSC	<b>2N2238</b>	DE176 3 DGE
DE128 1 DGE	THC697 3 SPR	D40D4 3 GESY	2N4401 3 MOTA	DE160 1 DGE	<b>2N2269</b>
D44T2 3 GESY	THC3299 3 SPR	D40D5 3 GESY	BC377 3 SGSI	<b>2N2239</b>	2N2562 1 LTE
<b>2N2202</b>	THC3641 3 SPR	DE123 3 DGE	BC548A 3 PHIN	D40D7 1 GESY	DE105 1 DGE
2N5681 1 GSE	THC3643 3 SPR	DE123A 3 DGE	BCY59 3 SGSI	<b>2N2240</b>	DE176 3 DGE
MOTA 1 MOTA	TP3299 3 SPR	DE128 3 DGE	BSW41A 3 PHIN	DE123 1 DGE	<b>2N2270</b>
DE128 1 DGE	TP3641 3 SPR	MPS2222 3 GESY	BC548A 3 PHIN	<b>2N2241</b>	D40D4 1 GESY
D44T2 3 GESY	TP3643 3 SPR	THC2192 3 SPR	BCY59 3 SGSI	DE123 1 DGE	DE128 1 DGE
<b>2N2203</b>	<b>2N2218A</b>	<b>2N2220</b>	2N2221 1 MOTA	<b>2N2242</b>	THC2270 1 SPR
2N5681 1 GSE	GES2218A 1 GESY	2N2221 1 MOTA	PHIN 3 PHIN	2N708 1 MOTA	2N2102 3 RCA
DE128 1 DGE	THC2218A 1 SPR	DE123A 1 DGE	DE123A 1 DGE	2N3903 1 GESY	2N4404 3 MOTA
D44T2 3 GESY	TN2218A 1 NSC	D40E5 1 GESY	DE123 3 DGE	2N2222 3 SGSI	2N5334 3 GSE
<b>2N2204</b>	TP2218A 1 SPR	BS2218 3 SIEG	DE123AP 3 DGE	BC548A 3 PHIN	BD139 3 PHIN
2N5681 1 GSE	2N697 3 RCA	GES222A 3 GESY	DE195A 3 DGE	DE123A 3 DGE	BSX59 3 PHIN
MOTA 1 MOTA	2N699 3 RCA	PN2221 3 NSC	GES2221 3 SPR	DE123AP 3 DGE	D40D4C 3 SPR
DE128 1 DGE	2N1613 3 PHIN	THC2221 3 SPR	GES3567 3 GESY	PN3646 3 NSC	D40D7 3 GESY
D44T2 3 GESY	SGSI 3 SGSI	TMPT2221 3 SPR	GES3568 3 GESY	THC3903 3 SPR	DE324 3 DGE
<b>2N2205</b>	2N2219 3 MOTA	<b>2N2221</b>	MMBT2222 3 MOTA	TMPT3903 3 SPR	THC3945 3 SPR
2N2218 1 PHIN	2N2219A 3 RCA	BSS81B 1 SIEG	MMBT4124 3 MOTA	<b>2N2243A</b>	<b>2N2270S</b>
2N2369 1 MOTA	2N3053 3 RCA	DE123A 1 DGE	MPS2222 3 GESY	2N1893 1 RCA	2N2270 1 RCA
DE123A 1 DGE	2N3553 3 THCS	GES222A 1 GESY	MRF586 3 MOTA	2N3020 1 MOTA	D40D4 3 GESY
2N697 3 RCA	BC140 3 SGSI	PN2221 1 NSC	PN100 3 NSC	BSW67 1 PHIN	DE128 3 DGE
2N3903 3 GESY	BC337 3 PHIN	THC2221 1 SPR	THC3116 3 SPR	DE128 1 DGE	THC2270 3 SPR
BCW60A 3 SIEG	BF257 3 SGSI	TMPT2221 1 SPR	THC3301 3 SPR	THC2243 1 SPR	<b>2N2271</b>
DE128 3 DGE	BFY50 3 PHIN	TP2221 1 SPR	THC3302 3 SPR	2N4305 3 TRWS	DE176 1 DGE
GES2218 3 GESY	BFY55 3 PHIN	2N720A 3 MOTA	THC3903 3 SPR	D38H4 3 GESY	<b>2N2272</b>
PN2369 3 NSC	BFY56A 3 SGSI	2N2218 3 PHIN	THC4013 3 SPR	D42T1 3 GESY	DE123A 1 DGE
THC2218 3 SPR	D40D1 3 GESY	2N2218A 3 PHIN	THC4014 3 SPR	D44T1 3 GESY	<b>2N2280</b>
TN2218 3 NSC	D40D3 3 GESY	2N2221A 3 PHIN	TMPT3903 3 SPR	THC3020 3 SPR	DE159 1 DGE
TP2218 3 SPR	D40D4 3 GESY	2N2222 3 SGSI	TP3301 3 SPR	TN3020 3 NSC	<b>2N2282</b>
<b>2N2206</b>	D40D7 3 GESY	2N2222A 3 PHIN	TP3302 3 SPR	<b>2N2243A</b>	2N1039 1 LTE
2N3903 1 GESY	D44T1 3 GESY	2N2297 3 PHIN	TP4013 3 SPR	2N1893 1 RCA	DE121 1 DGE
DE123A 1 DGE	DE123 3 DGE	2N3020 3 PHIN	TP4014 3 SPR	2N3020 1 MOTA	DE176 3 DGE
2N2222 3 SGSI	DGE 3 DGE	2N3020 3 PHIN		THC2243A 1 SPR	<b>2N2283</b>
BC548A 3 PHIN	PN3642-5 3 NSC			2N4305 3 TRWS	2N1040 1 LTE