

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
SDT9305		2N3054A	3-2	SVT350-5C		MJ13080	3-682
SDT9306		2N4233A	3-64	SVT400-12		MJ13090	3-688
SDT9307		2N3714	3-26	SVT400-3		2N6545	3-221
SDT9308		2N3715	3-26	SVT400-3C		2N6543	3-215
SDT9309		2N3716	3-26	SVT400-5		2N6543	3-215
SDT9701		2N5303	3-93	SVT400-5C		2N6545	3-221
SDT9702		2N5629	3-105	SVT450-3		2N6545	3-221
SDT9703		2N5630	3-105	SVT450-3C		MJ13335	3-700
SDT9704		2N5682	3-123	SVT450-5		2N6543	3-215
SDT9705		2N5629	3-105	SVT450-5C		MJ13080	3-682
SDT9706		2N5630	3-105	SVT6000		MJ10004	3-576
SDT9707		2N3055	3-6	SVT6001		MJ10004	3-576
SDTB01		2N5339	3-97	SVT6002		MJ10005	3-576
SDTB02		2N5339	3-97	SVT6060		MJ10004	3-576
SDTB03		2N5339	3-97	SVT6061		MJ10004	3-576
SDTB05		2N5339	3-97	SVT6062		MJ10005	3-576
SDTB06		2N5339	3-97	SVT6251		MJ10006	3-582
SDTB07		2N5339	3-97	SVT6252		MJ10006	3-582
SE9300	SE9300	—	—	SVT6253		MJ10007	3-582
SE9301	SE9301	—	—	SVT6546		MJ13090	3-688
SE9302	SE9302	—	—	SVT6547		MJ13090	3-688
SE9303		MJ1000	3-528	SVT7520		2N6543	3-215
SE9304		MJ1001	3-528	SVT7521		2N6543	3-215
SE9306		2N6287	3-172	SVT7522		MJ13335	3-700
SE9307		2N6283	3-172	SVT7523		2N6308	3-181
SE9308		2N6285	3-172	SVT7524		2N6543	3-215
SE9331		2N3739	3-37	SVT7525		MJ13335	3-700
SE9400	SE9400	—	—	SVT7530		MJ16006	3-742
SE9401	SE9401	—	—	SVT7531		MJ13080	3-682
SE9402	SE9402	—	—	SVT7532		MJ16004	3-726
SE9403		MJ900	3-528	SVT7533		MJ13080	3-682
SE9404		MJ901	3-528	SVT7534		MJ13080	3-682
SE9406		2N6285	3-172	SVT7535		MJ16004	3-726
SE9407		2N6286	3-172	SVT7540		MJ16008	3-742
SE9408		2N6287	3-172	SVT7541		MJ16008	3-742
SGSF463		MJH16006A	3-750	SVT7542		MJ16008	3-742
SGSF563		MJ16006A	3-750	SVT7543		MJ13080	3-682
SGSF564		MJ16018	3-782	SVT7544		MJ13080	3-682
SGSF464		MJH16018	3-782	SVT7545		MJ16008	3-742
SGSIF464		MJF16018	—	SVT7550		MJ16010	3-758
SGSIF63		MJF16006A	—	SVT7551		MJ16010	3-758
SV7056		MJE340	3-876	SVT7552		MJ16010	3-758
SVT100-5C		2N5882	3-123	SVT7553		MJ13090	3-688
SVT200-10		2N6306	3-181	SVT7554		MJ16010	3-758
SVT200-10C		MJ15022	3-720	SVT7555		MJ16010	3-758
SVT200-5C		2N6306	3-181	SVT7560		MJ16010	3-758
SVT250-10		2N6306	3-181	SVT7561		MJ16012	3-758
SVT250-10C		MJ15024	3-720	SVT7563		MJ13090	3-688
SVT250-3C		2N6308	3-181	SVT7564		MJ13090	3-688
SVT250-5		2N6308	3-181	SVT7565		MJ13090	3-688
SVT250-5C		2N6306	3-181	SVT7570		MJ16010	3-758
SVT300-10		2N6307	3-181	SVT7571		MJ16012	3-758
SVT300-10C		MJ13090	3-688	SVT7573		MJ13090	3-688
SVT300-3C		2N6307	3-181	SVT7574		MJ13090	3-688
SVT300-5		2N6543	3-215	SVT7575		MJ16012	3-758
SVT300-5C		2N6307	3-181	TIP100	TIP100		3-1091
SVT350-12		2N6547	3-225	TIP101	TIP101		3-1091
SVT350-3		2N6545	3-221	TIP102	TIP102		3-1091
SVT350-3C		2N6308	3-181	TIP105	TIP105		3-1091
SVT350-5		2N6308	3-181	TIP106	TIP106		3-1091

*Consult Motorola if a direct replacement is necessary.