

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N5139</b> (Cont'd) TP5139 1 SPR BC478 3 SGSI BC58A 3 PHIN THBC558 3 SPR	<b>2N5160</b> (Cont'd) DE129 1 DGE D41D4C 3 SPR <b>2N5181</b> D45C5 1 GESY 2N6109 3 RCA BD240 3 RCA ST45C5 3 STI <b>2N5163</b> 2N3822 1 INL 2N5246 1 IFC 2N5458 1 MOTA PN5163-18 1 NSC THC5142 1 SPR DE129 3 DGE 2N2905 1 PHIN DE159 1 DGE PN5142-18 1 NSC THC5142 1 SPR DE129 3 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR <b>2N5143</b> DE159 1 DGE PN5143-18 1 NSC <b>2N5145</b> 2N3993 3 MOTA 2N5115 3 INL SIX <b>2N5147</b> 2N6191 1 MOTA <b>2N5148</b> 2N4305 1 TRWS 2N5337 1 MOTA BSW66 1 PHIN 2N5154 3 TRWS D44T1 3 GESY D44VM10 3 GESY <b>2N5149</b> 2N6191 1 MOTA <b>2N5150</b> 2N5337 1 MOTA 2N5154 3 TRWS D44VM10 3 GESY <b>2N5151</b> 2N6191 1 MOTA <b>2N5152</b> 2N5337 1 MOTA BSW66 1 PHIN 2N5154 3 TRWS D44T1 3 GESY D44VM10 3 GESY <b>2N5153</b> 2N6191 1 MOTA <b>2N5154</b> 2N5337 1 MOTA D42C8 3 GESY D44VM10 3 GESY DE324 3 DGE <b>2N5156</b> DE179 1 DGE <b>2N5157</b> 2N5840 1 RCA 2N6545 1 MOTA BUW35 1 SGSI BUX83 1 PHIN D64VE5 1 GESY DE283 1 DGE SVT7534 1 TRWS 2N6673 3 RCA BUX12 3 APX BUX21A 3 APX BUX31B 3 RCA BUX32 3 RCA BUX81 3 PHIN BUX82 3 PHIN D64VP5 3 GESY DE163A 3 DGE MJ13080 3 MOTA SVT7523 3 TRWS TIP537 3 TII TIP556 3 TII TIP559 3 TII TIP560 3 TII TIP561 3 TII <b>2N5158</b> 2N5433 1 NSC SIX 2N5434 1 INL SIX MFE2012 1 MOTA 2N5432 3 SIX 2N5433 3 INL THJ5433 3 SPR THJ5434 3 SPR <b>2N5159</b> 2N5432 1 NSC SIX 2N5433 1 INL SIX 5432 1 SIX MFE2012 1 MOTA 2N5433 3 NSC 2N5434 3 INL THJ5432 3 SPR THJ5433 3 SPR <b>2N5160</b> D41D4 1 GESY	<b>2N5190</b> (Cont'd) BU407 3 APX D44C5 3 GESY ST44C6 3 STI <b>2N5191</b> BD949 1 PHIN D44C8 1 GESY DE184 1 DGE THC5191 1 SPR 2N6292 3 RCA BD239A 3 RCA BD241A 3 RCA BU407 3 APX ST44C8 3 STI <b>2N5192</b> BD951 1 PHIN D44C11 1 GESY DE184 1 DGE THC5192 1 SPR 2N6292 3 RCA BD239B 3 RCA BD241B 3 RCA BU407 3 APX ST44C11 3 STI <b>2N5193</b> BD948 1 PHIN D45C6 1 GESY DE185 1 DGE THC5193 1 SPR 2N6109 3 RCA BD240 3 RCA BD534 3 SGSI D45C5 3 GESY ST45C6 3 STI <b>2N5194</b> BD950 1 PHIN D45C8 1 GESY DE185 1 DGE THC5194 1 SPR 2N6107 3 RCA BD240A 3 RCA BD242A 3 RCA ST45C8 3 STI <b>2N5195</b> BD952 1 PHIN D45C11 1 GESY DE185 1 DGE THC5195 1 SPR 2N6107 3 RCA BD240B 3 RCA BD242B 3 RCA ST45C11 3 STI <b>2N5196</b> MP844 1 MPS THJ5196 1 SPR 2N3954 3 INL 2N3954A 3 NSC 2N5197 3 SIX 2N5520 3 INL MP840 3 MPS <b>2N5197</b> 2N5545 1 IFC MP844 1 MPS THJ5197 1 SPR 2N3921 3 SIX 2N3954 3 INL 2N3955A 3 NSC 2N5196 3 NSC SIX 2N5521 3 INL 2N5547 3 IFC DE461 3 DGE MP841 3 MPS THJ5545 3 SPR <b>2N5198</b> 2N5546 1 IFC MP5911 1 MPS THJ5198 1 SPR 2N3921 3 SIX 2N3954 3 INL 2N3955A 3 INL 2N5911 3 INL DE461 3 DGE MP844 3 MPS THJ5546 3 SPR <b>2N5199</b> 2N5547 1 IFC MP5912 1 MPS THJ5199 1 SPR 2N3921 3 SIX 2N3955 3 INL 2N5523 3 INL 2N5912 3 INL DE461 3 DGE MP842 3 MPS MP845 3 MPS	<b>2N5199</b> (Cont'd) THJ5547 3 SPR <b>2N5202</b> 2N5428 1 MOTA DE286 1 DGE D44C8 3 GESY D44H11 3 GESY <b>2N5208</b> DE106 1 DGE DE172A 1 DGE <b>2N5209</b> BC107 1 SGSI THC5209 1 SPR BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR <b>2N5209-18</b> DE123A 3 DGE THC4966 3 SPR THC4968 3 SPR <b>2N5210</b> BC107 1 SGSI BC547B 1 PHIN DE123AP 1 DGE PN100 1 NSC THC5210 1 SPR 2N930A 3 MOTA 2N3903 3 GESY BCW72 3 PHIN BCX41 3 SIEG BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN BFR17 3 SGSI BSS64 3 SIEG DE123A 3 DGE THBC107 3 SPR THBC547B 3 SPR THC2484 3 SPR THC3117 3 SPR TMPT2484 3 SPR TP2484 3 SPR <b>2N5210-18</b> DE123A 3 DGE THC4967 3 SPR <b>2N5213</b> BD131 1 PHIN D40D7 1 GESY D44C5 3 GESY <b>2N5219</b> BC108 1 SGSI BC547B 1 PHIN DE123AP 1 DGE THC5219 1 SPR BCW72 3 PHIN THBC108 3 SPR THBC547B 3 SPR <b>2N5220</b> DE123AP 1 DGE THC5220 1 SPR <b>2N5221</b> DE159 1 DGE THC5221 1 SPR <b>2N5223</b> BC549 1 PHIN THC5223 1 SPR BC109 3 SGSI <b>2N5225</b> DE123AP 1 DGE THC5225 1 SPR <b>2N5226</b> DE123AP 1 DGE THC5226 1 SPR <b>2N5227</b> DE159 1 DGE THC5227 1 SPR <b>2N5228</b> DE106 1 DGE <b>2N5232</b> DE199 1 DGE THC5232 1 SPR <b>2N5232A</b> THC5232A 1 SPR <b>2N5239</b> 2N6306 1 MOTA BUX82 1 PHIN D44TE3 1 GESY DE162 1 DGE 2N6545 3 MOTA BUW34 3 SGSI BUX22 3 APX BUX31 3 RCA BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE MJE13070 3 MOTA PTC515 3 PTC SVT7534 3 TRWS SVT7541 3 TRWS TIP554 3 TII	<b>2N5240</b> 2N6544 1 MOTA BDY97 1 PHIN BUX82 1 PHIN D44TE4 1 GESY DE162 1 DGE 2N6512 3 RCA 2N6545 3 MOTA BUS22A 3 APX BUX31 3 RCA BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE MJE13070 3 MOTA PTC519 3 PTC SVT7541 3 TRWS TIP535 3 TII TIP536 3 TII TIP558 3 TII <b>2N5241</b> 2N3902 1 MOTA 2N6513 1 RCA BUX18C 1 RCA BUX82 1 PHIN D64VE4 1 GESY DE163 1 DGE SVT7533 1 TRWS 2N6308 3 RCA 2N6545 3 MOTA 2N6672 3 RCA BUW34 3 SGSI BUW35 3 SGSI BUX31 3 RCA BUX80 3 PHIN D64VP4 3 GESY D64VP5 3 GESY DE283 3 DGE MJ13080 3 MOTA SVT7541 3 TRWS SVT7573 3 TRWS <b>2N5242</b> DE129 1 DGE <b>2N5243</b> DE129 1 DGE <b>2N5245</b> 2N5245-18 1 SIX 2N5248-18 1 NSC DE129 1 DGE ITE4416 1 INL PN4416 1 SIX THJ5245 1 SPR TMPF5245 1 SPR TP5245 3 SPR <b>2N5249A</b> THC5249A 1 SPR <b>2N5250</b> D60T257510 1 WESY <b>2N5251</b> D60T257510 1 WESY <b>2N5252</b> D44T3 1 GESY <b>2N5253</b> D44T4 1 GESY <b>2N5254</b> 2N3806 1 MOTA IT132 1 INL 2N3811A 3 MOTA DE82 3 DGE IT122 3 INL MP351 3 MPS MP351-78 3 MPS <b>2N5255</b> 2N3806 1 MOTA IT132 1 INL 2N3811A 3 MOTA DE82 3 DGE IT122 3 INL MP351 3 MPS MP351-78 3 MPS <b>2N5256</b> IT130 1 INL MP352 3 MPS <b>2N5257</b> 2N5457 1 INL SIX 2N5953 1 IFC 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 NSC SIX BF245A 3 PHIN DE451 3 DGE J305 3 SIX SX3819 3 TII THJ5457 3 SPR THJ5953 3 SPR TIS58 3 TII TMPF5457 3 SPR TMPF5953 3 SPR TP5953 3 SPR <b>2N5258</b> 2N5458 1 INL SIX 2N5952 1 IFC	<b>2N5246-18</b> (Cont'd) DE132 3 DGE J305-18 3 SIX THJ5246 3 SPR TMPF5246 3 SPR TP5246 3 SPR <b>2N5247</b> 2N5247-18 1 NSC SIX 2N5486 1 INL DE132 1 DGE J304-18 1 SIX THJ5247 1 SPR TMPF5247 1 SPR PTC 1 SPR 2N4416 3 INL NSC SIX 2N5486 3 MOTA THJ5486 3 SPR TMPF5486 3 SPR <b>2N5247-18</b> 2N5486 3 INL DE132 3 DGE J304-18 3 SIX THJ5247 3 SPR TMPF5247 3 SPR TP5247 3 SPR <b>2N5248</b> 2N5486 1 INL SIX DE132 1 DGE MPF102 1 MOTA THJ5248 1 SPR TMPF5248 1 SPR 2N3819 3 IFC 2N5247 3 IFC 2N5486 3 MOTA NSC THJ5486 3 SPR TMPF5486 3 SPR <b>2N5248-18</b> 2N5245-18 3 SIX DE129 3 DGE ITE4416 3 INL PN4416 3 SIX THJ5245 3 SPR TMPF5245 3 SPR TP5245 3 SPR <b>2N5249A</b> THC5249A 1 SPR <b>2N5250</b> D60T257510 1 WESY <b>2N5251</b> D60T257510 1 WESY <b>2N5252</b> D44T3 1 GESY <b>2N5253</b> D44T4 1 GESY <b>2N5254</b> 2N3806 1 MOTA IT132 1 INL 2N3811A 3 MOTA DE82 3 DGE IT122 3 INL MP351 3 MPS MP351-78 3 MPS <b>2N5255</b> 2N3806 1 MOTA IT132 1 INL 2N3811A 3 MOTA DE82 3 DGE IT122 3 INL MP351 3 MPS MP351-78 3 MPS <b>2N5256</b> IT130 1 INL MP352 3 MPS <b>2N5257</b> 2N5457 1 INL SIX 2N5953 1 IFC 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 NSC SIX BF245A 3 PHIN DE451 3 DGE J305 3 SIX SX3819 3 TII THJ5457 3 SPR THJ5953 3 SPR TIS58 3 TII TMPF5457 3 SPR TMPF5953 3 SPR TP5953 3 SPR <b>2N5258</b> 2N5458 1 INL SIX 2N5952 1 IFC