

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N5919A MRF323 1 MOTA	2N5945 (Cont'd) 2N946 3 MOTA	2N5950 (Cont'd) J203-18 3 SIX	2N5952 (Cont'd) THJ5669 3 SPR	2N5953-18 (Cont'd) TP5953 3 SPR	2N5974 (Cont'd) D45VH4 1 GESY
2N5922 BLV20 1 PHIN	2N5645 3 MOTA	J204 3 INL	THJ305 3 SPR	2N5954 2N6318 1 MOTA	DE183 1 DGE
2N5641 3 MOTA	2N5847 3 MOTA	J304-18 3 SIX	TIS75 3 IFC	DE218 1 DGE	BD132 3 PHIN
2N5927 D60T259010 1 WESY	2N5944 3 MOTA	MPF102 3 MOTA	TMPP4303 3 SPR	SDT3577 1 SOD	BDT82 3 APX
2N5928 D60T259010SPL 1 WESY	2N5946 3 MOTA	PN4223-18 3 NSC	TMPP5458 3 SPR	SDT3705 1 SOD	D45C6 3 GESY
2N5929 2N5671 1 RCA	2N5947 3 MOTA	THJ5486 3 SPR	TMPP5484 3 SPR	SDT3714 1 SOD	DE332 3 DGE
2N6338 1 MOTA	BLX67 3 PHIN	THJ5639 3 SPR	TMPP5640 3 SPR	SDT3718 1 SOD	2N5975 2N6490 1 RCA
2N5672 3 RCA	D40D1 3 GESY	THJ5670 3 SPR	TMPP5669 3 SPR	SDT3723 1 SOD	D45VH7 1 GESY
BUX10 3 SGSI	D42C1 3 GESY	TIS74 3 IFC	TP4303 3 SPR	SDT3728 1 SOD	DE183 1 DGE
DE327 3 DGE	DE363 3 DGE	TMPP5486 3 SPR	TP5669 3 SPR	SDT3731 1 SOD	2N5875 3 SGSI
2N5930 2N5672 1 RCA	MRF652 3 MOTA	TMPP5670 3 SPR	2N5952-18 2N5484 3 INL	2N3741 3 MOTA	BDT82 3 APX
2N6338 1 MOTA	MRF752 3 MOTA	TP5670 3 SPR	2N5640 3 MOTA	BD140 3 PHIN	D45C8 3 GESY
2N5672 3 TRWS	NE050320-12 3 NECE	2N5950-18 2N5486 3 INL	2N5953-18 3 NSC	D45C10 3 GESY	DE332 3 DGE
2N6339 3 MOTA	SD1135 3 THCS	2N5639 3 MOTA	SIX 3 SIX	D45VH10 3 GESY	2N5976 2N6491 1 RCA
BUX10 3 SGSI	2N5946 2N5590 3 MOTA	PN4416 3 SIX	J305 3 SIX	THC6318 3 SPR	D45VH10 1 GESY
DE327 3 DGE	2N5637 3 MOTA	THJ5950 3 SPR	SX3819 3 TII	2N5955 2N6317 1 MOTA	DE183 1 DGE
2N5931 2N6341 1 MOTA	2N5646 3 MOTA	TMPP5950 3 SPR	THJ5952 3 SPR	DE218 1 DGE	2N5876 3 SGSI
BUX11N 3 SGSI	2N5945 3 MOTA	TP5950 3 SPR	THJ5953 3 SPR	SDT3576 1 SOD	BDT84 3 APX
DE327 3 DGE	BLX68 3 PHIN	2N5951 2N5486 1 INL	TIS58 3 TII	SDT3702 1 SOD	BDW52C 3 SGSI
TIP516 3 TII	D42C2 3 GESY	2N5486 1 MOTA	TMPP5952 3 SPR	SDT3704 1 SOD	D45C8 3 GESY
2N5932 2N5671 1 RCA	D44C1 3 GESY	2N5640 1 MOTA	TMPP5953 3 SPR	SDT3707 1 SOD	DE332 3 DGE
2N6338 1 MOTA	DE364 3 DGE	2N5951-18 1 NSC	TP5952 3 SPR	SDT3708 1 SOD	2N5977 2N6486 1 RCA
2N5672 3 RCA	MRF653 3 MOTA	SIX 3 SIX	TP5953 3 SPR	SDT3710 1 SOD	D44VH4 1 GESY
BUX10 3 TRWS	MRF654 3 MOTA	PN4416 1 SIX	2N5953 2N5484 1 INL	SDT3711 1 SOD	DE182 1 DGE
DE327 3 DGE	MRF754 3 MOTA	THJ5951 1 SPR	2N5640 1 MOTA	SDT3716 1 SOD	2N5877 3 SGSI
2N5933 2N5672 1 RCA	NE020620-07 3 NECE	THJ5951 1 SPR	2N5952-18 1 SIX	SDT3722 1 SOD	BD131 3 PHIN
2N6338 1 MOTA	NE021020-12 3 NECE	TMPP5951 1 SPR	2N5953-18 1 NSC	SDT3727 1 SOD	BD241 3 SGSI
2N5672 3 TRWS	NE051025-12 3 NECE	TP5951 1 SPR	SIX 3 SIX	SDT3730 1 SOD	BDT81 3 APX
2N6339 3 MOTA	SD1136 3 THCS	TIS59 2 TII	J305 1 SIX	2N3740 3 MOTA	D42C3 3 GESY
BUX10 3 SGSI	2N5947 2N5847 3 MOTA	2N5247 3 IFC	THJ5953 1 SPR	2N4898 3 MOTA	D44C6 3 GESY
DE327 3 DGE	2N5945 3 MOTA	2N5338 3 MOTA	TMPP5953 1 SPR	2N5956 3 RCA	DE331 3 DGE
2N5933 2N5672 1 RCA	BLX67 3 PHIN	2N5458 3 INL	TP5953 1 SPR	D45C4 3 GESY	2N5978 2N6487 1 RCA
2N6338 1 MOTA	D40D1 3 GESY	2N5485 3 MOTA	SX3819 2 TII	D45C5 3 GESY	D44VH7 1 GESY
2N5672 3 TRWS	MRF587 3 MOTA	2N5670 3 MOTA	TIS58 2 TII	D45C6 3 GESY	DE182 1 DGE
2N6339 3 MOTA	SD1005 3 THCS	2N5670 3 MOTA	2N3684 3 INL	D45C8 3 GESY	2N5878 3 SGSI
BUX10 3 SGSI	SD1005-4 3 THCS	2N5670 3 MOTA	SIX 3 SIX	D45VH7 3 GESY	BDT81 3 APX
DE327 3 DGE	SD1006 3 THCS	2N5949 3 IFC	2N3685 3 INL	DE128 3 DGE	D44C8 3 GESY
2N5935 2N6032 1 RCA	2N5949 2N5486 1 INL	2N5949 3 IFC	2N3819 3 SIX	SVT200-10B 3 TRWS	DE331 3 DGE
2N6341 1 MOTA	2N5638 1 MOTA	BF245A 3 PHIN	2N3823 3 MOTA	THC6317 3 SPR	2N5979 2N6488 1 RCA
2N6275 3 MOTA	2N5949-18 1 NSC	BSV80 3 PHIN	2N4340 3 INL	2N5956 2N6317 1 MOTA	D44VH10 1 GESY
BUX11N 3 SGSI	PN4416 1 SIX	DE451 3 DGE	2N4341 3 INL	DE218 1 DGE	DE182 1 DGE
DE327 3 DGE	SIX 3 SIX	DE457 3 DGE	2N4391 3 NSC	SDT3575 1 SOD	BDT83 3 APX
DE387 3 DGE	THJ5949 1 SPR	ITE4416 3 INL	2N4889 3 INL	SDT3701 1 SOD	BDW51C 3 SGSI
TIP516 3 TII	TMPP5949 1 SPR	PN4304-18 3 NSC	2N5246 3 IFC	SDT3703 1 SOD	DE331 3 DGE
2N5936 2N6033 1 RCA	TP5949 1 SPR	THJ4304 3 SPR	2N5337 3 MOTA	SDT3706 1 SOD	2N5980 2N6489 1 RCA
2N6338 1 MOTA	SX3819 2 TII	THJ5459 3 SPR	2N5457 3 INL	SDT3709 1 SOD	D45VH4 1 GESY
2N5672 3 RCA	TIS59 2 TII	THJ5486 3 SPR	MOTA 3 MOTA	SDT3712 1 SOD	DE183 1 DGE
TRWS 3 TRWS	2N5247 3 IFC	THJ5640 3 SPR	SIX 3 SIX	SDT3715 1 SOD	MJE2955 1 MOTA
2N6277 3 MOTA	2N5484 3 INL	TIS75 3 IFC	2N5458 3 MOTA	SDT3716 1 SOD	BDT82 1 MOTA
BUX10 3 SGSI	2N5670 3 MOTA	TMPP4304 3 SPR	2N5459 3 MOTA	SDT3720 1 SOD	D45VH7 3 GESY
DE327 3 DGE	2N5951 3 IFC	TMPP5459 3 SPR	2N5484 3 SIX	SDT3721 1 SOD	DE332 3 DGE
DE387 3 DGE	2N5953 3 IFC	TMPP5486 3 SPR	2N5486 3 MOTA	SDT3725 1 SOD	2N5981 2N6490 1 RCA
2N5937 2N6341 1 MOTA	BSV78 3 PHIN	TMPP5640 3 SPR	2N5639 3 MOTA	SDT3726 1 SOD	D45VH7 1 GESY
BUX11N 3 SGSI	ITE4416 3 INL	TP4304 3 SPR	2N5949 3 IFC	SDT3729 1 SOD	DE183 1 DGE
DE327 3 DGE	J304-18 3 SIX	U1837 3 SIX	2N5952 3 IFC	SDT3733 1 SOD	BDT84 3 APX
TIP516 3 TII	J310 3 INL	2N5951-18 2N5486 3 INL	BF245A 3 PHIN	2N4898 3 MOTA	DE332 3 DGE
2N5939 2N5659 1 TRWS	MPF102 3 MOTA	2N5640 3 MOTA	BF245C 3 PHIN	2N5955 3 RCA	MJE2955 1 MOTA
2N5941 BLX14 1 PHIN	THJ5486 3 SPR	PN4416 3 SIX	BSV80 3 PHIN	D45C2 3 GESY	BDT82 3 APX
MRF466 1 MOTA	THJ5555 3 SPR	THJ5951 3 SPR	DE180 3 DGE	D45C3 3 GESY	DE332 3 DGE
MRF464A 3 MOTA	THJ5638 3 SPR	TIS59 3 TII	DE451 3 DGE	D45C4 3 GESY	2N5982 2N5988 1 MOTA
2N5942 BLX15 1 PHIN	TIS73 3 IFC	TMPP5951 3 SPR	DE457 3 DGE	D45C5 3 GESY	2N6491 1 RCA
MRF464 1 MOTA	TMPP5486 3 SPR	TP5951 3 SPR	ITE4416 3 INL	D45C6 3 GESY	D45VH10 1 GESY
MRF428 3 MOTA	TMPP5555 3 SPR	2N5952 2N5484 1 INL	J202-18 3 NSC	D45VH7 3 GESY	DE183 1 DGE
THX15 3 THCS	TMPP5638 3 SPR	2N5484 1 INL	SIX 3 SIX	DE128 3 DGE	BDT84 3 APX
2N5943 BRF95 1 APX	U1837 3 SIX	2N5640 1 MOTA	J203-18 3 SIX	THC6317 3 SPR	DE332 3 DGE
2N4428 3 MOTA	2N5949-18 2N5486 3 INL	2N5952-18 1 NSC	J232-18 3 SIX	2N5972 DE327 1 DGE	2N5983 2N6486 1 RCA
2N5109 3 MOTA	2N5638 3 MOTA	SIX 3 SIX	J304 3 SIX	DE123AP 1 DGE	D44VH4 1 GESY
BFR95 3 APX	PN4416 3 SIX	THJ5952 1 SPR	J305-18 3 NSC	THC5961 1 SPR	DE182 1 DGE
D40D3 3 GESY	SX3819 3 TII	TMPP5952 1 SPR	PN3684-18 3 NSC	TP5961 1 SPR	MJE3055 1 MOTA
MRF586 3 MOTA	THJ5949 3 PHIN	TP5952 1 SPR	PN4302 3 NSC	2N5962 1 SPR	BDT81 3 APX
SD1006 3 THCS	TIS59 2 TII	TIS58 2 TII	PN4302-18 3 NSC	THC5962 1 SPR	D44VH7 3 GESY
2N5944 2N945 3 MOTA	2N5950 1 NSC	2N3823 3 MOTA	THJ4302 3 SPR	TP5962 1 SPR	DE331 3 DGE
2N5589 3 MOTA	2N5639 3 MOTA	2N5246 3 IFC	THJ4507 3 SPR	2N5970 2N5882 1 MOTA	2N6487 1 RCA
2N5644 3 MOTA	2N5950-18 1 NSC	2N5338 3 MOTA	THJ5484 3 SPR	2N6472 1 RCA	D44VH7 1 GESY
2N5945 3 MOTA	PN4416 1 SIX	2N5458 3 INL	THJ5640 3 SPR	DE284 1 DGE	DE182 1 DGE
THCS 3 THCS	THJ5950 1 SPR	2N5485 3 INL	THJ5668 3 SPR	BDW51B 3 SGSI	MJE3055 1 MOTA
2N6080 3 MOTA	TMPP6950 1 SPR	2N5953 3 SIX	TIS75 3 IFC	BDX95 3 PHIN	BDT81 3 APX
BLX67 3 PHIN	TP5950 1 SPR	2N5953 3 IFC	TMPP4302 3 SPR	DE181 3 DGE	DE331 3 DGE
D40D1 3 GESY	2N4341 3 INL	BF245B 3 PHIN	TMPP5457 3 SPR	2N5971 2N5882 1 MOTA	2N5985 2N5991 1 MOTA
DE362 3 DGE	2N4386 3 INL	BSV80 3 PHIN	TMPP5640 3 SPR	2N6472 1 RCA	2N6488 1 RCA
MRF553 3 MOTA	2N5247 3 IFC	DE180 3 DGE	TMPP5668 3 SPR	DE284 1 DGE	D45VH10 1 GESY
MRF616 3 MOTA	2N5458 3 INL	DE451 3 DGE	TP4302 3 SPR	BDW51B 3 SGSI	DE182 1 DGE
MRF630 3 MOTA	2N5459 3 INL	DE457 3 DGE	TP5668 3 SPR	BDX95 3 PHIN	BDT83 3 APX
MRF652 3 MOTA	MOTA 3 MOTA	J204 3 INL	2N5953-18 2N5484 3 INL	DE181 3 DGE	DE331 3 DGE
MRF752 3 MOTA	SIX 3 SIX	J305-18 3 NSC	2N5640 3 MOTA	2N5972 2N6472 1 RCA	2N6489 1 RCA
NE050320-12 3 NECE	2N5486 3 MOTA	SIX 3 SIX	2N5952-18 3 SIX	MJ15003 3 MOTA	D45VH4 1 GESY
SD1080-2 3 THCS	BF245C 3 PHIN	PN4303-18 3 NSC	J305 3 SIX	2N5882 3 MOTA	DE182 1 DGE
SD1115-2 3 THCS	BSV79 3 PHIN	SIX 3 SIX	SX3819 3 TII	BDW51B 3 SGSI	BDT82 3 APX
SD1134 3 THCS	THJ4303 3 SPR	THJ5458 3 SPR	THJ5953 3 SPR	BDX95 3 PHIN	DE332 3 DGE
2N5945 2N945 3 MOTA	ITE4416 3 INL	THJ5484 3 SPR	TIS58 3 TII	DE181 3 DGE	2N5987 2N6490 1 RCA
	J105-18 3 SIX	THJ5640 3 SPR	TMPP5953 3 SPR	2N5974 2N6489 1 RCA	D45VH7 1 GESY
	J203-18 3 NSC				DE183 1 DGE