

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N3330 (Cont'd) 2N5270 3 INL MPF161 3 MOTA THJ3329 3 SPR THJ3332 3 SPR TMPF3329 3 SPR TMPF3332 3 SPR TP3329 3 SPR TP3330 3 SPR	2N3348 (Cont'd) MP351 3 MPS MP351-78 3 MPS 2N3349 2N3726 1 MOTA DE82 1 DGE IT139 1 INL IT131 3 INL MP351 3 MPS MP351-78 3 MPS	2N3369 (Cont'd) THJ3460 3 SPR THJ4339 3 SPR THJ4340 3 SPR TMPF3460 3 SPR TMPF4339 3 SPR TMPF4340 3 SPR TP3460 3 SPR TP4339 3 SPR TP4340 3 SPR	2N3382 (Cont'd) TMPF3994 3 SPR TMPF5116 3 SPR TP3994 3 SPR TP5116 3 SPR 2N3384 2N3993 1 IFC INL THBC338 3 SPR 2N5115 1 NSC SIX 2N3386 2N3993 3 MOT 2N5116 3 NSC DE160 3 DGE THJ3993 3 SPR THJ5115 3 SPR TMPF3993 3 SPR TMPF5115 3 SPR TP3993 3 SPR TP5115 3 SPR	2N3402 (Cont'd) THBC338 3 SPR 2N3403 BC338 1 PHIN DE192A 1 DGE THC3403 1 SPR BC378 3 SGSI BCX20 3 PHIN THBC338 3 SPR 2N3404 BC337 1 PHIN DE192A 1 DGE THC3404 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC337 3 SPR 2N3405 BC337 1 PHIN DE192A 1 DGE THC3405 1 SPR 2N3505 3 BC377 3 SGSI BCX19 3 PHIN THBC337 3 SPR 2N3409 IT122 1 INL MD3409 1 MOTA IT129 3 INL MP310 3 MPS 2N3410 IT122 1 INL MD3410 1 MOTA IT129 3 INL MP310 3 MPS 2N3411 IT122 1 INL MD3410 1 MOTA IT129 3 INL MP310 3 MPS 2N3412 DE126A 1 DGE 2N3413 DE288 1 DGE 2N3414 BC338 1 PHIN DE85 1 DGE PN100 1 NSC THC3414 1 SPR BC378 3 SGSI BCX20 3 PHIN THBC338 3 SPR 2N3415 BC338 1 PHIN DE85 1 DGE PN100 1 NSC THC3415 1 SPR BC378 3 SGSI BCX20 3 PHIN THBC338 3 SPR 2N3417 BC337 1 PHIN DE85 1 DGE PN100 1 NSC THC3417 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC337 3 SPR 2N3418 2N4307 1 TRWS 2N5336 1 MOTA D42C8 1 GESY 2N4309 3 TRWS 2N5337 3 MOTA 2N6292 3 RCA D44VM10 3 GESY MDS27 3 MOTA 2N3419 2N4305 1 TRWS 2N5336 1 MOTA 2N4309 3 TRWS 2N5337 3 MOTA D44VM10 3 GESY MDS27 3 MOTA 2N3420 2N4307 1 TRWS 2N5336 1 MOTA D42C8 1 GESY 2N3632 3 PHIN 2N4309 3 TRWS 2N5337 3 MOTA 2N6292 3 RCA BF523A 3 PHIN D44C7 3 GESY D44C8 3 GESY D44VM10 3 GESY MDS27 3 MOTA	2N3421 2N4305 1 TRWS 2N5336 1 MOTA 2N4309 3 TRWS 2N5337 3 MOTA D44VM10 3 GESY 2N3423 IT122 1 INL MD918 1 MOTA MD8003 3 MOTA MP310 3 MPS 2N3424 IT122 1 INL MD918 1 MOTA MD8003 3 MOTA MP310 3 MPS 2N3425 IT122 1 INL MP318 1 MPS IT120A 3 INL MP310 3 MPS 2N3426 DE195A 1 DGE 2N3427 DE176 1 DGE 2N3428 DE176 1 DGE 2N3431 2N4341 1 MOTA 2N3458 3 IFC BFW11 3 PHIN DE312 3 DGE THJ4341 3 SPR TMPF4341 3 SPR TP4341 3 SPR 2N3436 2N3458 1 IFC 2N4222 1 NSC SIX 2N4341 1 INL SIX NSC BFW10 3 PHIN DE312 3 DGE THJ3458 3 SPR THJ4222 3 SPR THJ4341 3 SPR THJ6449 3 SPR THJ6450 3 SPR TMPF3458 3 SPR TMPF4222 3 SPR TMPF4341 3 SPR TP4222 3 SPR TP4341 3 SPR TP6449 3 SPR TP6450 3 SPR 2N3437 2N3459 1 IFC 2N3968 1 NSC SIX 2N4340 1 INL SIX 2N4341 1 INL SIX 2N6449 3 IFC 2N6450 3 IFC BFW11 3 PHIN BFW12 3 PHIN DE312 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3968 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3968 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR 2N3438 2N3460 1 IFC 2N4338 1 INL SIX 2N4341 1 MOTA SIX 2N4340 3 NSC SIX 2N6449 3 IFC 2N6450 3 IFC BFW11 3 PHIN BFW12 3 PHIN DE312 3 DGE DE459 3 DGE THJ3459 3 SPR THJ3968 3 SPR THJ4340 3 SPR THJ4341 3 SPR TMPF3459 3 SPR TMPF3968 3 SPR TMPF4340 3 SPR TMPF4341 3 SPR