

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
BF25-35 MRF137 1 MOTA MRF171 1 MOTA	BF164 (Cont'd) BF198 1 PHIN	BF198 2N5201 3 MOTA BC107 3 SGSI	BF245A (Cont'd) 2N5458 3 INL 2N5484 3 INL	BF247 (Cont'd) TMPF4091 3 SPR TP4091 3 SPR	BF257 (Cont'd) 40408 3 RCA BD115 3 PHIN	
BF50-35 MRF172 1 MOTA	BF165 BF185 1 PHIN BF495 1 PHIN	BC547A 3 PHIN BC548A 3 PHIN BF196 3 PHIN	2N5951 3 IFC 2N5953 3 IFC DE451 3 DGE	BF247A 2N4091 1 INL DE466 3 DGE	BSW66 3 PHIN BSW67 3 PHIN BSW68 3 PHIN	
BF100-35 MRF174 1 MOTA	BF166 BF200 1 PHIN	THC4286 3 SPR THC4287 3 SPR	DE452 3 DGE DE457 3 DGE PN4304-18 3 NSC	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	D44T1 3 GESY D44T2 3 GESY DE154 3 DGE	
BF108 D44T1 1 GESY	BF169 BF115 1 PHIN BF494 1 PHIN	BF199 MPSH24 1 MOTA SF245 1 MIKG	THJ4304 3 SPR THJ4416 3 SPR THJ5457 3 SPR	BF247B 2N4091 1 INL DE466 3 DGE	MPSA43 3 MOTA	
BF109 D40V1 1 GESY	MPSH04 3 MOTA	BF197 3 PHIN	THJ5668 3 SPR TMPF4304 3 SPR TMPF4416 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	BF258 BF337 1 PHIN D40V1 1 GESY	
BF111 2N3440 1 RCA BD115 3 PHIN	BF174 2N3440 1 RCA BF258 3 SIEG	BF206 2N918 1 PHIN BF799 3 SIEG	DE161 3 DGE PN918 3 NSC TMPF5457 3 SPR	BF247C 2N4091 1 INL DE466 3 DGE	2N3440 3 RCA 2N6515 3 MOTA	
BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF337 3 PHIN BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY	THC918 3 SPR TMP918 3 SPR	TP4304 3 SPR TP4416 3 SPR TP5668 3 SPR	THJ4091 3 SPR TMPF4091 3 SPR TP4091 3 SPR	40412 3 RCA BC639 3 PHIN D44T1 3 GESY	
BF115 2N2218 3 MOTA BF494 3 PHIN	D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF214 BF115 1 PHIN BF494 1 PHIN	BF245B 2N4416 1 INL 2N5338 3 MOTA	BF248 2N2221 1 PHIN 2N2222 1 PHIN	DE154 3 DGE GES4927 3 GESY THC4927 3 SPR TP4927 3 SPR	
BF494 3 PHIN D40E1 3 GESY D40E5 3 GESY DE128 3 DGE DE319 3 DGE	BF177 BF257 1 SGSI BF336 3 PHIN	MPSH04 3 MOTA	2N5459 3 INL 2N5485 3 INL 2N5952 3 IFC	2N2906A 1 PHIN BSS81B 3 SIEG BSS81C 3 SIEG	2N3439 3 RCA 2N3440 3 RCA BD115 3 PHIN	
BF118 BF338 1 PHIN D40V1 1 GESY	D40V1 3 GESY	BF215 BF115 1 PHIN BF494 1 PHIN	DE451 3 DGE DE452 3 DGE DE457 3 DGE	DE123A 3 DGE GES222A 3 GESY GES2222 3 GESY	BD115 3 PHIN MPSA42 3 MOTA	
2N3440 3 RCA BF259 3 SGSI	BF178 40412 1 RCA BF258 1 SGSI	MPSH04 3 MOTA	PN4303-18 3 NSC THJ4303 3 SPR THJ4416 3 SPR	PN2221 3 NSC PN2222 3 NSC THC2221 3 SPR	BF260 BF200 1 PHIN	
BF119 BF337 1 PHIN 2N3440 3 RCA	BF337 3 PHIN D40V1 3 GESY D44T2 3 GESY	BF222 BF115 1 PHIN BF494 1 PHIN	THJ5669 3 SPR TMPF4303 3 SPR TMPF4416 3 SPR	THC2222 3 SPR TMPT2221 3 SPR TMPT2222 3 SPR	BF261 BF196 1 PHIN BF198 1 PHIN	
BF258 3 SGSI	BF179 2N3440 1 RCA BF259 1 SGSI	MPSH24 3 MOTA SF245 3 MIKG	THJ5669 3 SPR TMPF4303 3 SPR TMPF4416 3 SPR	TP2221 3 SPR TP2222 3 SPR	BF268 BFY90 1 PHIN SD1300 3 THCS	
BF120 BC394 1 SGSI	BD115 3 PHIN BF338 3 PHIN	BF223 BF197 1 PHIN BF199 1 PHIN	TP5669 3 SPR TMPF5458 3 SPR TMPF5669 3 SPR	DE159 3 DGE GES2907 3 GESY PN2906A 3 NSC	BF272 2N2906 1 PHIN DE159 3 DGE	
BF123 BF197 1 PHIN BF199 1 PHIN	BFN18 3 SIEG BFN26 3 SIEG D40V3 3 GESY	MPSH04 3 MOTA SF245 3 MIKG	TP4303 3 SPR TP4416 3 SPR TP5669 3 SPR	GES2907 3 GESY PN2906A 3 NSC PN2907 3 NSC	THC2906 3 SPR TMPT2906 3 SPR TP2906 3 SPR	
MPSH24 3 MOTA SF245 3 MIKG	D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF230 BF195 1 PHIN BF495 1 PHIN	BF245C 2N4416 1 INL 2N5337 3 MOTA	THC2906A 3 SPR THC2907 3 SPR TMPT2906A 3 SPR	PN2906 3 NSC TMPT2906 3 SPR SF245 3 MIKG	
BF125 BF197 1 PHIN BF199 1 PHIN	BF179A 2N3440 1 RCA D40V1 1 GESY	MPSH04 3 MOTA	2N5484 3 INL 2N5486 3 INL 2N5950 3 IFC	TP2906A 3 SPR TP2907 3 SPR TPQ2906A 3 SPR	BF273 BF241 1 PHIN SF225 3 MIKG	
MPSH24 3 MOTA SF245 3 MIKG	BD115 3 PHIN BFN18 3 SIEG BFN26 3 SIEG	BF233 BF495 1 PHIN MPSH04 3 MOTA	2N5951 3 IFC 2N5953 3 IFC DE451 3 DGE	BF249 2N2906A 1 PHIN 2N2907 1 SGSI	BF291 BC107 1 SGSI BCX70G 3 PHIN	
BF127 BF197 1 PHIN BF199 1 PHIN	D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF237 BF115 1 PHIN BF494 1 PHIN	DE452 3 DGE DE457 3 DGE MPF108 3 MOTA	GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR	BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN	
MPSH24 3 MOTA SF245 3 MIKG	BF179B 2N3440 1 RCA D40V1 1 GESY	MPSH04 3 MOTA	PN4302-18 3 NSC THJ3819 3 SPR THJ4302 3 SPR	TP2907 3 SPR TPQ2906A 3 SPR	THBC107 3 SPR	
BF131 BF182 1 PHIN	BD115 3 PHIN BFN18 3 SIEG	BF238 BF115 1 PHIN BF494 1 PHIN	SIX 3 IFC THJ4416 3 SPR THJ5459 3 SPR	BF250 2N2222 1 SGSI BSS81C 3 SIEG	BF292 BF258 1 SGSI BF337 3 PHIN	
BF133 BF183 1 PHIN	BFN26 3 SIEG D44T2 3 GESY	MPSH04 3 MOTA	THJ5670 3 SPR TP4302 3 SPR TP4416 3 SPR	GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR	BF337 3 PHIN D40V1 3 GESY	
BF134 BF200 1 PHIN	D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF240 MPSH04 3 MOTA	TP5670 3 SPR THJ3819 3 SPR THJ4302 3 SPR	TP2222 3 SPR	BF292A D40V1 1 GESY	
BF137 2N3440 1 RCA BF257 1 SGSI	BF179C 2N3440 1 RCA D40V1 1 GESY	BF241 SF225 1 MIKG SF245 1 MIKG	THJ4416 3 SPR THJ5459 3 SPR THJ5670 3 SPR	BF251 BF199 1 PHIN MPSH24 3 MOTA	BF292B D40V1 1 GESY	
BD115 3 PHIN BF336 3 PHIN BFN18 3 SIEG	BFN26 3 SIEG D40V1 3 GESY D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	MPSH04 3 MOTA	BF244 2N5486 1 INL 2N5247 3 IFC	SF245 3 MIKG	BF292C D40V1 1 GESY	
BFN18 3 SIEG BFN26 3 SIEG D40V1 3 GESY D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF181 MPSH04 3 MOTA SF235 3 MIKG	BF243 MPSH54 1 MOTA	THJ5486 3 SPR TMPF5486 3 SPR	BF254 MPSH04 1 MOTA	BF293 BC107 1 SGSI BCX70G 3 PHIN	
BF153 BF495 1 PHIN MPSH04 3 MOTA	BF184 BF494 3 PHIN DE161 3 DGE	BF244 2N5486 1 INL 2N5247 3 IFC	BF244A 2N5484 1 INL THJBF244A 1 SPR	BF255 MPSH04 1 MOTA	BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN	
BF154 BF196 1 PHIN BF198 1 PHIN	BF185 2N2221 3 MOTA BF495 3 PHIN	THJ5486 3 SPR TMPF5486 3 SPR	THJBF244A 1 SPR 2N5246 3 IFC DE180 3 DGE	BF256 MPSH04 1 MOTA	BCX70L 3 PHIN BCX70M 3 PHIN THBC107 3 SPR	
BF155 BF180 1 PHIN	DE161 3 DGE	BF244B 2N5485 1 INL THJBF244B 1 SPR	THJ5485 3 SPR TMPF5485 3 SPR	BF257 2N5484 1 INL 2N5246 3 IFC	BF294 BC257 1 SGSI BD115 1 PHIN	
BF156 BF257 1 SGSI D40V1 1 GESY	BF186 BF337 1 PHIN 2N3440 3 RCA	THJ5484 3 SPR TMPF5484 3 SPR	BF246 2N5639 1 INL THJBF246A 1 SPR	DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR	D40V2 1 GESY 2N3440 3 RCA BC177 3 SGSI	
BF336 3 PHIN	BF189 BF115 1 PHIN BF494 1 PHIN	BF244C 2N5486 1 INL THJBF244C 1 SPR	THJBF246A 1 SPR TMPF5486 3 SPR BSV79 3 PHIN	BF258 2N5484 1 INL 2N5246 3 IFC	BC557 3 PHIN D44T1 3 GESY THBC257 3 SPR	
BF157 2N3440 1 RCA BF257 1 SGSI	MPSH04 3 MOTA DE161 3 DGE	THJ5639 3 SPR TIS74 3 IFC TMPF5639 3 SPR	BF246B 2N5638 1 INL THJBF246B 1 SPR	BF259 2N5484 1 INL 2N5246 3 IFC	BF295 BF257 1 SGSI BF336 1 PHIN	
D40V1 1 GESY BD115 3 PHIN	BF191 BF196 1 PHIN BF198 1 PHIN	BF246C 2N5638 1 INL THJBF246C 1 SPR	THJBF246B 1 SPR TMPF5486 3 SPR BSV78 3 PHIN	DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR	MPSA43 1 MOTA 2N3440 3 RCA BFN16 3 SIEG	
BF336 3 PHIN BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	BF195 BF495 3 PHIN	THJ5638 3 SPR TIS73 3 IFC TMPF5638 3 SPR	THJBF246B 1 SPR TMPF5486 3 SPR BSV78 3 PHIN	BF260 2N4416 1 INL THJBF256B 1 SPR	D40V1 3 GESY MPSA43C 3 SPR S298TS 3 ALGG TMPTA43 3 SPR	
BF160 BF495 1 PHIN MPSH04 3 MOTA	BF196 BF495 3 PHIN	BF245A 2N4416 1 INL 2N5338 3 MOTA	THJBF246C 1 SPR TMPF5486 3 SPR BSV78 3 PHIN	DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR	BF296 2N6515 1 MOTA BF258 1 SGSI	
BF161 BF183 1 PHIN	BF197 BF196 1 PHIN BF198 1 PHIN	BF245B 2N5486 1 INL 2N5247 3 IFC	THJ5638 3 SPR TIS73 3 IFC TMPF5638 3 SPR	TP4416 3 SPR	BF337 3 PHIN D40V1 3 GESY DE287 3 DGE	
BF162 BF200 1 PHIN	BF199 BF199 3 PHIN MPSH24 3 MOTA	BF245C 2N5486 1 INL 2N5247 3 IFC	BF247 2N4091 1 INL DE466 3 DGE	BF257 BF336 1 PHIN D40V1 1 GESY	BF297 BF259 1 SGSI MPSA42 1 MOTA	
BF163 BF196 1 PHIN BF198 1 PHIN		THJ5486 3 SPR TMPF5486 3 SPR	THJ4091 3 SPR	2N2218A 3 PHIN 2N3020 3 PHIN 2N3440 3 RCA	BF338 3 PHIN BFN18 3 SIEG D40V3 3 GESY	
BF164 BF196 1 PHIN						