

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
CM642 (Cont'd) TMPF4093 3 SPR TMPF4858 3 SPR TP4092 3 SPR TP4093 3 SPR TP4858 3 SPR	CM697 (Cont'd) 2N5434 1 SIX MPF4392 1 MOTA ITE4392 3 INL MFE2012 3 MOTA PN4392 3 SIX PN4392-18 3 SIX THJ5433 3 SPR THJ5434 3 SPR	CP643 (Cont'd) 2N5434 1 INL DE466 3 DGE MFE2012 3 MOTA THJ4856 3 SPR THJ5434 3 SPR TMPF4856 3 SPR	CTC1350M MRF1325M 1 MOTA CTC2001 MRF2001 1 MOTA CTC2001A MRF2001 1 MOTA CTC2002 MRF2003 1 MOTA CTC2003 MRF2003 1 MOTA CTC2003A MRF2003 1 MOTA CTC2005 MRF2005 1 MOTA CTC2005A MRF2005 1 MOTA CTC2010 MRF2010 1 MOTA CTRW D42C8 3 GESY CV5439 BC178 1 PHIN BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR CV5447 BC177 1 PHIN BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR CV5712 BC177 1 PHIN BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR CV5848 BCY34A 1 PHIN CV5876 BDX96 1 PHIN BDW22C 3 SGSI CV7005 BC177 1 PHIN BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR CV7008 BC179 1 PHIN BC559 1 PHIN BC478 3 SGSI BC858A 3 PHIN BCF29 3 PHIN THBC179 3 SPR CV7043 BCY33A 1 PHIN CV7044 BCY34A 1 PHIN CV7083 BDX96 1 PHIN BDW22C 3 SGSI CV7085 BDX96 1 PHIN BDW22C 3 SGSI CV7086 BDX96 1 PHIN BDW22C 3 SGSI CV7117 BCY31A 1 PHIN CV7338 BCY70 1 PHIN CV7347 BCY34A 1 PHIN CV7363 BCY34A 1 PHIN CV8340 BDX92 1 PHIN 2N4905 3 RCA BDW22A 3 SGSI CV8342 BDX96 1 PHIN BDW22C 3 SGSI CV8356 BDX92 1 PHIN 2N4905 3 RCA BDW22A 3 SGSI	D1-2-12 MRF581 1 MOTA D1-12B MRF870A 1 MOTA SD1409 1 THCS MRF838A 3 MOTA D1-12E MRF838A 1 MOTA D1-28 MRF313 1 MOTA SD1544 1 THCS MRF2001M 3 MOTA SD1020-6 3 THCS D1/2-12 MRF838A 1 MOTA D2-12B MRF870A 1 MOTA D2-12E MRF839 1 MOTA MRF870A 1 MOTA D2T918 IT129 1 INL MD918 1 MOTA IT122 3 INL MD8003 3 MOTA MP311 3 MPS D2T2218 IT129 1 INL MD2218 1 MOTA MP311 3 MPS D2T2218A IT129 1 INL MP311 3 MPS D2T2219 IT129 1 INL MD2219 1 MOTA MP311 3 MPS D2T2219A IT129 1 INL MD2219A 1 MOTA MP311 3 MPS D2T2904 IT139 1 INL MD2904 3 MOTA MP351 1 MOTA D2T2904A IT139 1 INL MP351 3 MPS D2T2905 IT139 1 INL MD2905 1 MOTA MP351 3 MPS D2T2905A IT139 1 INL MD2905A 1 MOTA MP351 3 MPS D3-28 MRF5174 1 MOTA SD1545 1 THCS MRF2003M 3 MOTA D4C2 2N6111 1 RCA BD202 3 APX PHIN DE197 3 DGE D5K1 2N6114 1 MOTA D5K2 2N6115 1 MOTA D08AM2 VN1206L 2 SIX BST74A 3 APX D80AM1 3 GESY TN0520N3 3 STX VN1310N3 3 STX ZVN0108A 3 FERB ZVN0109A 3 FERB ZVN0109K 3 FERB ZVN0110A 3 FERB ZVN1310A 3 FERB ZVN2117A 3 FERB D10-28 MRF321 1 MOTA D10P MRF1015MA 1 MOTA MRF1015MC 1 MOTA D13T1 MPU6027 1 MOTA D13T2 MPU6028 1 MOTA D16P1 D16P1C 1 SPR D16P1C D16P1 2 D20-28 MRF323 1 MOTA D29A4 D29A4C 1 SPR D29A4C D29A4 2 D29A5C D29A5C 1 SPR	D29A5C D29A5 2 D29E1 D29E1C 1 SPR D29E1C D29E1 2 D29E2 D29E2C 1 SPR D29E2C D29E2 2 D29E4 D29E4C 1 SPR D29E4C D29E4 2 D29E5 D29E5C 1 SPR D29E5C D29E5 2 D29E6 D29E6C 1 SPR D29E6C D29E6 2 D29E7 D29E7C 1 SPR D29E7C D29E7 2 D29E9 D29E9C 1 SPR D29E9C D29E9 2 D29E10 D29E10C 1 SPR D29E10C D29E10 2 D33D21 D33D21C 1 SPR D33D21C D33D21 2 D33D22 D33D22C 1 SPR D33D22C D33D22 2 D33D24 D33D24C 1 SPR D33D24C D33D24 2 D33D25 D33D25C 1 SPR D33D25C D33D25 2 D33D26 D33D26C 1 SPR D33D26C D33D26 2 D33D27 D33D27C 1 SPR D33D27C D33D27 2 D33D29 D33D29C 1 SPR D33D29C D33D29 2 D33D30 D33D30C 1 SPR D33D30C D33D30 2 D38H4 2N1893 3 RCA 2N4305 3 TRWS BD230 3 PHIN DE128 3 DGE ST486 3 STI THC3020 3 SPR TN3020 3 NSC D38H5 2N4305 3 TRWS BCX56-16 3 SIEG DE128 3 DGE THC3019 3 SPR TN3019 3 NSC D38H7 2N1893 3 SGSI 2N3440 3 RCA BSX21 3 PHIN D40C7 2N2723 3 MOTA D40D1 2N697 3 RCA 2N1613 3 SGSI 2N1711 3 SGSI 2N2218 3 PHIN 2N2218A 3 SGSI 2N2219 3 PHIN 2N2219 3 SGSI 2N2221 3 PHIN 2N2222A 3 PHIN 2N2297 3 PHIN 2N3053 3 RCA 2N3724 3 MOTA 2N3725 3 SGSI 2N3763 3 MOTA 2N3866 3 MOTA PHIN