

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N1302 DE103 1 DGE	2N1339 (Cont'd) DE128 3 DGE	2N1386 (Cont'd) THC2222 3 SPR	2N1423 (Cont'd) 2N5347 3 MOTA	2N1475A DE129 1 DGE	2N1486 (Cont'd) D44VM7 3 GESY
2N1303 DE102 1 DGE	THC3019 3 SPR	TMPT2222 3 SPR	2N1424 2N5477 1 GSE	2N1476 2N4928 1 MOTA	ST44C8 3 STI
2N1304 DE103 1 DGE	TN3019 3 NSC	TN2219 3 NSC	2N5347 3 MOTA	BFT28 3 RCA	STD5902 3 SOD
2N1305 DE102 1 DGE	2N1340 2N1613 1 PHIN	TP2219 3 SPR	2N1428 2N869A 1 MOTA	DE129 3 DGE	2N1487 2N4913 1 GSE
2N1306 DE103 1 DGE	2N3019 1 MOTA	TP2222 3 SPR	PN3640 3 NSC	GES4928 3 GESY	2N5877 1 MOTA
2N1307 DE102 1 DGE	D44T1 1 GESY	2N1387 2N2219 1 PHIN	2N1429 2N869A 1 MOTA	2N1477 2N4928 1 MOTA	BD191 1 PHIN
2N1308 DE103 1 DGE	2N4305 3 TRWS	2N2222 1 MOTA	PN3640 3 NSC	BFT28 3 RCA	DE280 1 DGE
2N1309 2N1307 1 LTE	BCX56-16 3 SIEG	BSS81C 3 SIEG	2N1439 2N2907A 1 MOTA	DE129 3 DGE	2N3054 3 RCA
DE102 1 DGE	D38H5 3 GESY	DE128 3 DGE	BSS82C 3 SIEG	GES4928 3 GESY	2N5758 3 MOTA
2N1310 DE103 1 DGE	D40D7 3 GESY	GES2219 3 GESY	PN2907A 3 NSC	2N1479 2N4237 1 GSE	BDX91 3 PHIN
2N1311 DE103 1 DGE	DE123 3 DGE	GES2222 3 GESY	2N1440 2N2907A 1 MOTA	BFX34 1 PHIN	D44H4 3 GESY
2N1312 DE103 1 DGE	DE128 3 DGE	NSC 3 NSC	BSS82C 3 SIEG	D44VH7 3 GESY	DE130 3 DGE
2N1313 DE126A 1 DGE	PN2221A 3 NSC	THC2219 3 SPR	PN2907A 3 NSC	2N1488 2N4914 1 GSE	2N4914 1 GSE
2N1314 2N3611 1 LTE	THC1613 3 SPR	THC2222 3 SPR	THC2907A 3 SPR	2N5878 1 MOTA	BDX95 1 PHIN
BD934 1 PHIN	THC3019 3 SPR	TMPT2222 3 SPR	TP2907A 3 SPR	BDX95 1 PHIN	DE280 1 DGE
DE121 1 DGE	TN3019 3 NSC	TN2219 3 NSC	2N1441 2N2907A 1 MOTA	DE280 1 DGE	DE280 1 DGE
BD240 3 RCA	2N1341 2N3019 1 MOTA	TP2219 3 SPR	BSS82C 3 SIEG	2N5786 3 RCA	2N5758 3 MOTA
SGSI	D44T1 1 GESY	TP2222 3 SPR	PN2907A 3 NSC	D40D4C 3 SPR	BDW21C 3 SGSI
2N1315 BDX92 1 PHIN	2N4305 3 TRWS	2N1388 2N2219 1 PHIN	THC2907A 3 SPR	2N1480 2N4238 1 GSE	BDX91 3 PHIN
DE121 1 DGE	BCX56-16 3 SIEG	2N2222 1 MOTA	TMPT2907A 3 SPR	MOTA	D44H7 3 GESY
2N4905 3 RCA	D38H5 3 GESY	BSS81C 3 SIEG	TP2907A 3 SPR	BFX34 1 PHIN	D44VH10 3 GESY
BDW22A 3 SGSI	DE128 3 DGE	DE128 3 DGE	2N1442 2N2907A 1 MOTA	D40D4 1 GESY	DE130 3 DGE
2N1316 DE102 1 DGE	THC3019 3 SPR	GES2219 3 GESY	DE129 1 DGE	DE128 1 DGE	2N1489 2N4913 1 GSE
2N1317 DE102 1 DGE	TN3019 3 NSC	GES2222 3 GESY	BSS82C 3 SIEG	2N5785 3 RCA	2N5877 1 MOTA
2N1318 DE102 1 DGE	2N1342 2N3019 1 MOTA	PN2222 3 NSC	PN2907A 3 NSC	BFY50 3 PHIN	BDX91 1 PHIN
2N1319 DE102 1 DGE	D44T1 1 GESY	THC2219 3 SPR	THC2907A 3 SPR	D40D4C 3 SPR	DE280 1 DGE
2N1320 2N2560 1 LTE	2N4305 3 TRWS	THC2222 3 SPR	TMPT2907A 3 SPR	D40D7 3 GESY	2N4914 1 GSE
DE176 3 DGE	BCX56-16 3 SIEG	TN2219 3 NSC	TP2907A 3 SPR	2N1481 2N4237 1 GSE	2N5758 3 MOTA
2N1322 2N2561 1 LTE	D38H5 3 GESY	TP2219 3 SPR	2N1443 2N2907A 1 MOTA	MOTA	BDW21A 3 SGSI
DE176 3 DGE	DE128 3 DGE	TP2222 3 SPR	DE129 1 DGE	BFX34 1 PHIN	BDX91 3 PHIN
2N1324 2N2562 1 LTE	THC3019 3 SPR	2N1389 2N2222 1 MOTA	BSS82C 3 SIEG	BSV64 1 PHIN	D44H7 3 GESY
DE176 3 DGE	TN3019 3 NSC	BSS81C 3 SIEG	PN2907A 3 NSC	D40D4 1 GESY	DE130 3 DGE
2N1326 2N2563 1 LTE	2N1352 2N651 1 LTE	GES2222 3 GESY	THC2907A 3 SPR	DE128 1 DGE	2N1490 2N4914 1 GSE
DE176 3 DGE	DE102 3 DGE	NSC 3 NSC	TMPT2907A 3 SPR	2N5786 3 RCA	2N5878 1 MOTA
2N1328 2N1042 1 LTE	2N1359 BD936 1 PHIN	THC2222 3 SPR	TP2907A 3 SPR	D40D4C 3 SPR	BDX95 1 PHIN
DE176 3 DGE	BD240A 3 SGSI	TP2222 3 SPR	2N1444 2N2907A 1 MOTA	2N1482 2N4238 1 GSE	DE163A 1 DGE
2N1331 2N1044 1 LTE	BD434 3 PHIN	2N1390 2N2222 1 MOTA	DE129 1 DGE	MOTA	2N5758 3 MOTA
2N1333 2N1045 1 LTE	2N1360 DE121 1 DGE	BSS81C 3 SIEG	BSS82C 3 SIEG	BFX34 1 PHIN	BDW21C 3 SGSI
2N1335 2N3019 1 MOTA	2N1362 BD938 1 PHIN	GES2222 3 GESY	PN2907A 3 NSC	BSV64 1 PHIN	BDX91 3 PHIN
D44T1 1 GESY	BD240B 3 RCA	NSC 3 NSC	THC2907A 3 SPR	D40D4 1 GESY	D44H7 3 GESY
2N4305 3 TRWS	SGSI	THC2222 3 SPR	TMPT2907A 3 SPR	DE324 1 DGE	D44VH10 3 GESY
BCX56-16 3 SIEG	2N1363 DE121 1 DGE	TP2222 3 SPR	2N1445 2N5859 1 MOTA	2N5785 3 RCA	DE130 3 DGE
D38H5 3 GESY	2N1364 BD940 1 PHIN	2N1409 2N2562 1 LTE	2N4307 3 TRWS	BFY50 3 PHIN	DE281 3 DGE
DE128 3 DGE	DE121 1 DGE	D40D1 1 GESY	DE324 3 DGE	DE128 3 DGE	2N1491 2N2222 1 PHIN
THC3019 3 SPR	DE121 1 DGE	2N4307 3 TRWS	2N1446 D44T1 1 GESY	2N1483 BD935 1 PHIN	DE195A 1 DGE
TN3019 3 NSC	BD240C 3 RCA	DE324 3 DGE	DE128 1 DGE	D44C5 1 GESY	MRF586 1 MOTA
2N1336 2N3019 1 MOTA	2N1365 DE121 1 DGE	2N1409A 2N5859 1 MOTA	2N1448 2N1191 1 LTE	DE375 1 DGE	BSS81C 3 SIEG
D44T1 1 GESY	2N1366 DE103 1 DGE	2N4307 3 TRWS	2N1449 2N1189 1 LTE	TIP41 1 MOTA	GES2222 3 GESY
2N4305 3 TRWS	2N1372 DE102 1 DGE	DE324 3 DGE	DE102 3 DGE	2N6290 3 RCA	PN2222 3 NSC
BCX56-16 3 SIEG	2N1373 DE102 1 DGE	2N1410 2N5859 1 MOTA	2N1451 2N464 1 LTE	BD201 3 PHIN	THC2222 3 SPR
D38H5 3 GESY	2N1374 DE102 1 DGE	D40D1 1 GESY	DE100 3 DGE	BD239A 3 RCA	TP2222 3 SPR
DE128 3 DGE	2N1375 DE102 1 DGE	2N4307 3 TRWS	2N1452 2N1191 1 LTE	SGSI	2N1492 2N2222 1 PHIN
THC3019 3 SPR	2N1376 DE102 1 DGE	DE324 3 DGE	2N1470 D44C8 1 GESY	BD243 3 RCA	DE195A 1 DGE
TN3019 3 NSC	2N1377 DE102 1 DGE	2N1411 DE102 1 DGE	2N6292 3 RCA	BU407 3 APX	BSS81C 3 SIEG
2N1337 2N3019 1 MOTA	2N1378 DE102 1 DGE	2N1414 DE102 1 DGE	BD239A 3 RCA	D44VM4 3 GESY	GES2222 3 GESY
D44T1 1 GESY	2N1379 DE102 1 DGE	2N1415 DE102 1 DGE	BU407 3 APX	ST44C5 3 STI	PN2222 3 NSC
2N4305 3 TRWS	2N1380 DE102 1 DGE	2N1418 BC107 1 PHIN	ST44C8 3 STI	STD5901 3 SOD	THC2222 3 SPR
BCX56-16 3 SIEG	2N1381 DE102 1 DGE	BC547 1 PHIN	2N1484 BD937 1 PHIN	2N1485 D44C5 1 GESY	TP2222 3 SPR
D38H5 3 GESY	2N1382 DE102 1 DGE	BCX70G 3 PHIN	D44C8 1 GESY	DE375 1 DGE	2N1493 DE154 1 DGE
DE128 3 DGE	2N1383 DE102 1 DGE	BCX70H 3 PHIN	TIP41A 1 MOTA	2N6292 3 RCA	2N1495 AC128 1 PHIN
THC3019 3 SPR	2N1384 DE126A 1 DGE	BCX70J 3 PHIN	2N6292 3 RCA	BD203 3 PHIN	AC188 1 PHIN
TN3019 3 NSC	2N1385 DE126A 1 DGE	THBC107 3 SPR	BD239A 3 RCA	BD239A 3 RCA	2N1499 DE129A 1 DGE
2N1338 2N2219 1 MOTA	2N1386 DE126A 1 DGE	THBC547 3 SPR	BD239B 3 RCA	SGSI	2N1499A DE126A 1 DGE
D44T1 1 GESY	2N1387 DE102 1 DGE	2N1421 2N5477 1 GSE	2N1472 2N834 1 MOTA	BD243A 3 RCA	2N1499B DE126A 1 DGE
DE128 3 DGE	2N1388 DE102 1 DGE	2N5347 3 MOTA	BCY56 3 PHIN	BU407 3 APX	2N1500 DE126A 1 DGE
GES2219 3 GESY	2N1389 DE102 1 DGE	2N1422 2N5477 1 GSE	BSX20 3 SGSI	D44VM7 3 GESY	2N1501 2N2561 1 LTE
THC2219 3 SPR	2N1390 2N2219 1 PHIN	2N5347 3 MOTA	MPS834 3 NSC	ST44C8 3 STI	BDX96 1 PHIN
TP2219 3 SPR	2N1391 2N2222 1 MOTA	2N1423 2N5477 1 GSE	2N1474 2N2906A 1 MOTA	STD5902 3 SOD	BDW22C 3 SGSI
2N1339 2N3019 1 MOTA	BSS81C 3 SIEG	2N1424 2N5477 1 GSE	DE129 1 DGE	2N1486 D44C8 1 GESY	DE176 3 DGE
D44T1 1 GESY	DE128 3 DGE	2N1425 2N2906A 1 MOTA	PN2906A 3 NSC	DE375 1 DGE	2N1502 2N2562 1 LTE
2N4305 3 TRWS	GES2219 3 GESY	THC2906A 3 SPR	THC2906A 3 SPR	TIP41A 1 MOTA	BDX92 1 PHIN
BCX56-16 3 SIEG	GES2222 3 GESY	TMPT2906A 3 SPR	TPQ2906A 3 SPR	2N6290 3 RCA	2N4905 3 RCA
D38H5 3 GESY	PN2222 3 NSC	TP2906A 3 SPR	2N1474A 2N2906A 1 MOTA	BD201 3 PHIN	BDW22A 3 SGSI
DE128 3 DGE	2N1399 2N3019 1 MOTA	2N1426 2N5477 1 GSE	DE129 1 DGE	BD239 3 RCA	DE176 3 DGE
THC3019 3 SPR	D44T1 1 GESY	2N1427 2N2906A 1 MOTA	PN2906A 3 NSC	BD243 3 RCA	2N1505 2N2218A 1 PHIN
TN3019 3 NSC	2N4305 3 TRWS	DE129 1 DGE	THC2906A 3 SPR	BU407 3 APX	2N2219A 1 MOTA
2N1399 2N3019 1 MOTA	BCX56-16 3 SIEG	2N1428 2N2906A 1 MOTA	TMPT2906A 3 SPR	D44VM4 3 GESY	D40D3 1 DGE
D44T1 1 GESY	DE128 3 DGE	2N2906A 3 SPR	TPQ2906A 3 SPR	SP44H 3 SODI	D40D2 3 MOTA
2N4305 3 TRWS	GES2219 3 GESY	2N1429 2N2906A 1 MOTA	2N1475 2N2906A 1 MOTA	ST44C5 3 STI	GES2218A 3 GESY
BCX56-16 3 SIEG	PN2222 3 NSC	DE129 1 DGE	DE129 1 DGE	STD5901 3 SOD	GES2219A 3 GESY
D38H5 3 GESY	THC2219 3 SPR	2N1430 2N2906A 1 MOTA	DE129 1 DGE	2N1487 D44C5 1 GESY	THC2218A 3 SPR