

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N1302</b> DE103 1 DGE	<b>2N1339</b> (Cont'd) DE128 3 DGE	<b>2N1386</b> (Cont'd) THC2222 3 SPR	<b>2N1423</b> (Cont'd) 2N5347 3 MOTA	<b>2N1475A</b> DE129 1 DGE	<b>2N1486</b> (Cont'd) D44VM7 3 GESY
<b>2N1303</b> DE102 1 DGE	THC3019 3 SPR	TMPT2222 3 SPR	<b>2N1424</b> 2N5477 1 GSE	<b>2N1476</b> 2N4928 1 MOTA	ST44C8 3 STI
<b>2N1304</b> DE103 1 DGE	TN3019 3 NSC	TN2219 3 NSC	2N5347 3 MOTA	BFT28 3 RCA	STD5902 3 SOD
<b>2N1305</b> DE102 1 DGE	<b>2N1340</b> 2N1613 1 PHIN	TP2219 3 SPR	<b>2N1428</b> 2N869A 1 MOTA	DE129 3 DGE	<b>2N1487</b> 2N4913 1 GSE
<b>2N1306</b> DE103 1 DGE	2N3019 1 MOTA	TP2222 3 SPR	PN3640 3 NSC	GES4928 3 GESY	2N5877 1 MOTA
<b>2N1307</b> DE102 1 DGE	D44T1 1 GESY	<b>2N1387</b> 2N2219 1 PHIN	<b>2N1429</b> 2N869A 1 MOTA	<b>2N1477</b> 2N4928 1 MOTA	BD191 1 PHIN
<b>2N1308</b> DE103 1 DGE	2N4305 3 TRWS	2N2222 1 MOTA	PN3640 3 NSC	BFT28 3 RCA	DE280 1 DGE
<b>2N1309</b> 2N1307 1 LTE	BCX56-16 3 SIEG	BSS81C 3 SIEG	<b>2N1439</b> 2N2907A 1 MOTA	DE129 3 DGE	2N3054 3 RCA
DE102 1 DGE	D38H5 3 GESY	DE128 3 DGE	BSS82C 3 SIEG	GES4928 3 GESY	2N5758 3 MOTA
<b>2N1310</b> DE103 1 DGE	D40D7 3 GESY	GES2219 3 GESY	PN2907A 3 NSC	<b>2N1479</b> 2N4237 1 GSE	BDX91 3 PHIN
<b>2N1311</b> DE103 1 DGE	DE123 3 DGE	GES2222 3 GESY	<b>2N1440</b> 2N2907A 1 MOTA	BFX34 1 PHIN	D44H4 3 GESY
<b>2N1312</b> DE103 1 DGE	DE128 3 DGE	NSC 3 NSC	BSS82C 3 SIEG	D44VH7 3 GESY	DE130 3 DGE
<b>2N1313</b> DE126A 1 DGE	PN2221A 3 NSC	THC2219 3 SPR	PN2907A 3 NSC	<b>2N1488</b> 2N4914 1 GSE	2N4914 1 GSE
<b>2N1314</b> 2N3611 1 LTE	THC1613 3 SPR	THC2222 3 SPR	THC2907A 3 SPR	2N5878 1 MOTA	BDX95 1 PHIN
BD934 1 PHIN	THC3019 3 SPR	TMPT2222 3 SPR	TP2907A 3 SPR	DE280 1 DGE	BDX91 1 PHIN
DE121 1 DGE	TN3019 3 NSC	TN2219 3 NSC	<b>2N1441</b> 2N2907A 1 MOTA	DE280 1 DGE	DE280 1 DGE
BD240 3 RCA	<b>2N1341</b> 2N3019 1 MOTA	TP2219 3 SPR	BSS82C 3 SIEG	2N4914 1 GSE	2N5758 1 MOTA
<b>2N1315</b> BDX92 1 PHIN	D44T1 1 GESY	TP2222 3 SPR	PN2907A 3 NSC	2N5758 1 MOTA	BDW21C 3 SGSI
DE121 1 DGE	2N4305 3 TRWS	<b>2N1388</b> 2N2219 1 PHIN	THC2907A 3 SPR	BDX91 3 PHIN	D44H7 3 GESY
2N4905 3 RCA	BCX56-16 3 SIEG	2N2222 1 MOTA	TMPT2907A 3 SPR	D44VH10 3 GESY	DE130 3 DGE
BDW22A 3 SGSI	D38H5 3 GESY	BSS81C 3 SIEG	TP2907A 3 SPR	<b>2N1489</b> 2N4913 1 GSE	2N4913 1 GSE
<b>2N1316</b> DE102 1 DGE	DE128 3 DGE	GES2219 3 GESY	<b>2N1442</b> 2N2907A 1 MOTA	2N5878 1 MOTA	2N5758 1 MOTA
<b>2N1317</b> DE102 1 DGE	THC3019 3 SPR	GES2222 3 GESY	DE129 1 DGE	D40D4C 3 SPR	BDW21A 3 SGSI
<b>2N1318</b> DE102 1 DGE	TN3019 3 NSC	NSC 3 NSC	BSS82C 3 SIEG	BFX34 1 PHIN	D44H4 3 GESY
<b>2N1319</b> DE102 1 DGE	<b>2N1342</b> 2N3019 1 MOTA	THC2219 3 SPR	PN2907A 3 NSC	D40D4 1 GESY	D44VH10 3 GESY
<b>2N1320</b> 2N2560 1 LTE	D44T1 1 GESY	THC2222 3 SPR	THC2907A 3 SPR	DE128 1 DGE	DE130 3 DGE
DE176 3 DGE	2N4305 3 TRWS	TMPT2222 3 SPR	TP2907A 3 SPR	2N5785 3 RCA	<b>2N1490</b> 2N4914 1 GSE
<b>2N1322</b> 2N2561 1 LTE	BCX56-16 3 SIEG	TN2219 3 NSC	<b>2N1443</b> 2N2907A 1 MOTA	D40D4C 3 SPR	2N5878 1 MOTA
DE176 3 DGE	D38H5 3 GESY	TP2219 3 SPR	DE129 1 DGE	D40D4C 3 SPR	BDX95 1 PHIN
<b>2N1324</b> 2N2562 1 LTE	DE128 3 DGE	<b>2N1389</b> 2N2222 1 MOTA	BSS82C 3 SIEG	<b>2N1481</b> 2N4237 1 GSE	DE163A 1 DGE
DE176 3 DGE	THC3019 3 SPR	BSS81C 3 SIEG	PN2907A 3 NSC	MOTA 1 MOTA	2N5758 3 MOTA
<b>2N1326</b> 2N2563 1 LTE	DE121 1 DGE	GES2222 3 GESY	THC2907A 3 SPR	BFX34 1 PHIN	BDW21C 3 SGSI
DE176 3 DGE	BD240B 3 RCA	NSC 3 NSC	TMPT2907A 3 SPR	D44H7 3 GESY	BDX91 3 PHIN
<b>2N1328</b> 2N1042 1 LTE	<b>2N1352</b> 2N651 1 LTE	THC2219 3 SPR	TP2907A 3 SPR	DE128 1 DGE	D44VH10 3 GESY
DE176 3 DGE	DE102 3 DGE	TMPT2222 3 SPR	<b>2N1444</b> 2N5859 1 MOTA	2N5785 3 RCA	DE130 3 DGE
<b>2N1331</b> 2N1044 1 LTE	<b>2N1359</b> BD936 1 PHIN	TP2222 3 SPR	2N4307 3 TRWS	BFY50 3 PHIN	DE281 3 DGE
<b>2N1333</b> 2N1045 1 LTE	BD240A 3 SGSI	<b>2N1390</b> 2N2222 1 MOTA	DE324 3 DGE	DE128 3 DGE	<b>2N1491</b> 2N2222 1 PHIN
<b>2N1335</b> 2N3019 1 MOTA	BD434 3 PHIN	BSS81C 3 SIEG	<b>2N1409</b> 2N5859 1 MOTA	<b>2N1483</b> BD935 1 PHIN	DE195A 1 DGE
D44T1 1 GESY	<b>2N1360</b> DE121 1 DGE	GES2222 3 GESY	D40D1 1 GESY	D44C5 1 GESY	MRF586 1 MOTA
2N4305 3 TRWS	<b>2N1362</b> BD938 1 PHIN	NSC 3 NSC	2N4307 3 TRWS	DE375 1 DGE	BSS81C 3 SIEG
BCX56-16 3 SIEG	DE121 1 DGE	THC2222 3 SPR	DE324 3 DGE	TIP41 1 MOTA	GES2222 3 GESY
D38H5 3 GESY	BD240B 3 RCA	TMPT2222 3 SPR	<b>2N1409A</b> 2N5859 1 MOTA	2N6290 3 RCA	PN2222 3 NSC
DE128 3 DGE	SGSI 3 SGSI	TP2222 3 SPR	2N4307 3 TRWS	BD201 3 PHIN	THC2222 3 SPR
THC3019 3 SPR	<b>2N1363</b> DE121 1 DGE	<b>2N1410</b> 2N5859 1 MOTA	DE324 3 DGE	BD239A 3 RCA	TP2222 3 SPR
TN3019 3 NSC	<b>2N1364</b> BD940 1 PHIN	2N4307 3 TRWS	<b>2N1411</b> DE102 1 DGE	BD239A 3 RCA	<b>2N1492</b> 2N2222 1 PHIN
<b>2N1336</b> 2N3019 1 MOTA	DE121 1 DGE	DE324 3 DGE	<b>2N1414</b> DE102 1 DGE	BD203 3 PHIN	DE195A 1 DGE
D44T1 1 GESY	<b>2N1365</b> DE121 1 DGE	<b>2N1418</b> BC107 1 PHIN	<b>2N1415</b> DE102 1 DGE	BD239A 3 RCA	BSS81C 3 SIEG
2N4305 3 TRWS	<b>2N1366</b> DE103 1 DGE	BC547 1 PHIN	<b>2N1418A</b> 2N5859 1 MOTA	BD239A 3 RCA	GES2222 3 GESY
BCX56-16 3 SIEG	DE103 1 DGE	BCX70G 3 PHIN	D40D1 1 GESY	BD239A 3 RCA	PN2222 3 NSC
D38H5 3 GESY	DE103 1 DGE	BCX70H 3 PHIN	2N4307 3 TRWS	BD239A 3 RCA	THC2222 3 SPR
DE128 3 DGE	DE103 1 DGE	BCX70J 3 PHIN	DE324 3 DGE	BD239B 3 RCA	TMPT2222 3 SPR
THC3019 3 SPR	DE103 1 DGE	BCX70K 3 PHIN	<b>2N1419</b> DE105 1 DGE	<b>2N1484</b> BD937 1 PHIN	TP2222 3 SPR
TN3019 3 NSC	DE103 1 DGE	THBC107 3 SPR	<b>2N1419A</b> DE102 1 DGE	D44C8 1 PHIN	<b>2N1493</b> DE154 1 DGE
<b>2N1337</b> 2N3019 1 MOTA	<b>2N1367</b> DE103 1 DGE	THBC547 3 SPR	<b>2N1420</b> 2N2219 1 MOTA	DE375 1 DGE	<b>2N1495</b> AC128 1 PHIN
D44T1 1 GESY	DE103 1 DGE	<b>2N1409A</b> 2N5859 1 MOTA	<b>2N1421</b> 2N5477 1 GSE	TIP41A 1 MOTA	AC188 1 PHIN
2N4305 3 TRWS	DE103 1 DGE	2N4307 3 TRWS	2N5347 3 MOTA	2N6290 3 RCA	<b>2N1499</b> DE129A 1 DGE
BCX56-16 3 SIEG	DE103 1 DGE	DE324 3 DGE	<b>2N1422</b> 2N5477 1 GSE	BD201 3 PHIN	DE176 3 DGE
D38H5 3 GESY	DE103 1 DGE	<b>2N1410A</b> 2N5859 1 MOTA	<b>2N1423</b> 2N5347 3 MOTA	BD239A 3 RCA	<b>2N1502</b> 2N2562 1 LTE
DE128 3 DGE	DE103 1 DGE	D40D1 1 GESY	<b>2N1424</b> 2N5477 1 GSE	BD203 3 PHIN	BDX92 1 PHIN
THC3019 3 SPR	DE103 1 DGE	2N4307 3 TRWS	<b>2N1425</b> 2N5347 3 MOTA	BD239A 3 RCA	2N4905 3 RCA
TN3019 3 NSC	DE103 1 DGE	DE324 3 DGE	<b>2N1426</b> 2N5347 3 MOTA	BD239A 3 RCA	BDW22A 3 SGSI
<b>2N1338</b> 2N2219 1 MOTA	<b>2N1368</b> DE126A 1 DGE	<b>2N1411A</b> 2N5859 1 MOTA	<b>2N1427</b> 2N834 1 MOTA	BD239B 3 RCA	DE176 3 DGE
D44T1 1 GESY	DE126A 1 DGE	D40D1 1 GESY	BCY56 3 PHIN	<b>2N1472</b> 2N834 1 MOTA	<b>2N1499A</b> DE126A 1 DGE
DE128 3 DGE	DE126A 1 DGE	2N4307 3 TRWS	BSX20 3 SGSI	BD243A 3 RCA	<b>2N1499B</b> DE126A 1 DGE
GES2219 3 GESY	DE126A 1 DGE	DE324 3 DGE	MPS834 3 NSC	BU407 3 APX	<b>2N1500</b> DE126A 1 DGE
THC2219 3 SPR	<b>2N1369</b> 2N2219 1 PHIN	<b>2N1412</b> 2N5477 1 GSE	<b>2N1473</b> 2N2906A 1 MOTA	D44VM7 3 GESY	<b>2N1501</b> 2N2561 1 LTE
TN2219 3 NSC	2N2222 1 MOTA	<b>2N1423</b> 2N5347 3 MOTA	DE129 1 DGE	ST44C8 3 STI	BDW22C 3 SGSI
TP2219 3 SPR	2N2222 1 MOTA	<b>2N1423A</b> 2N5347 3 MOTA	PN2906A 3 SPR	STD5902 3 SOD	DE176 3 DGE
<b>2N1339</b> 2N3019 1 MOTA	BSS81C 3 SIEG	<b>2N1424</b> 2N5477 1 GSE	THC2906A 3 SPR	<b>2N1485</b> D44C5 1 GESY	<b>2N1502</b> 2N2562 1 LTE
D44T1 1 GESY	DE128 3 DGE	<b>2N1425</b> 2N5477 1 GSE	TMPT2906A 3 SPR	DE375 1 DGE	BDX96 1 PHIN
2N4305 3 TRWS	GES2219 3 GESY	<b>2N1426</b> 2N5477 1 GSE	TPQ2906A 3 SPR	TIP41 1 MOTA	DE126A 1 DGE
BCX56-16 3 SIEG	GES2222 3 GESY	<b>2N1427</b> 2N5477 1 GSE	<b>2N1474</b> 2N2906A 1 MOTA	2N6290 3 RCA	BDW22C 3 SGSI
D38H5 3 GESY	PN2222 3 NSC	<b>2N1428</b> 2N5477 1 GSE	DE129 1 DGE	BD201 3 PHIN	DE176 3 DGE
DE128 3 DGE	THC2219 3 SPR	<b>2N1429</b> 2N5477 1 GSE	PN2906A 3 NSC	BD239 3 RCA	<b>2N1502</b> 2N2562 1 LTE
THC3019 3 SPR	<b>2N1399</b> 2N3019 1 MOTA	<b>2N1430</b> 2N5477 1 GSE	THC2906A 3 SPR	BD239A 3 RCA	BDX92 1 PHIN
TN3019 3 NSC	D44T1 1 GESY	<b>2N1431</b> 2N5477 1 GSE	TPQ2906A 3 SPR	BD239B 3 RCA	2N4905 3 RCA
<b>2N1339</b> 2N3019 1 MOTA	DE128 3 DGE	<b>2N1432</b> 2N5477 1 GSE	<b>2N1475</b> 2N2906A 1 MOTA	<b>2N1486</b> D44C8 1 GESY	BDW22A 3 SGSI
D44T1 1 GESY	2N2222 1 MOTA	<b>2N1433</b> 2N5477 1 GSE	DE129 1 DGE	DE375 1 DGE	DE176 3 DGE
2N4305 3 TRWS	BSS81C 3 SIEG	<b>2N1434</b> 2N5477 1 GSE	PN2906A 3 NSC	TIP41A 1 MOTA	<b>2N1505</b> 2N2218A 1 PHIN
BCX56-16 3 SIEG	DE128 3 DGE	<b>2N1435</b> 2N5477 1 GSE	THC2906A 3 SPR	2N6292 3 RCA	2N2219A 1 MOTA
D38H5 3 GESY	GES2219 3 GESY	<b>2N1436</b> 2N5477 1 GSE	TMPT2906A 3 SPR	BD203 3 PHIN	D40D3 1 DGE
DE128 3 DGE	PN2222 3 NSC	<b>2N1437</b> 2N5477 1 GSE	TP2906A 3 SPR	BD239A 3 RCA	D40D2 3 MOTA
THC2219 3 SPR	THC2219 3 SPR	<b>2N1438</b> 2N5477 1 GSE	<b>2N1476</b> 2N2906A 1 MOTA	BD243A 3 RCA	GES2218A 3 GESY
TN2219 3 NSC	<b>2N1399</b> 2N3019 1 MOTA	<b>2N1439</b> 2N5477 1 GSE	DE129 1 DGE	BU407 3 APX	GES2219A 3 GESY
TP2219 3 SPR	D44T1 1 GESY	<b>2N1440</b> 2N5477 1 GSE	PN2906A 3 NSC	<b>2N1487</b> D44C8 1 PHIN	THC2218A 3 SPR
<b>2N1339</b> 2N3019 1 MOTA	DE128 3 DGE	<b>2N1441</b> 2N5477 1 GSE	THC2906A 3 SPR	D44VH7 3 GESY	THC2219A 3 SPR
D44T1 1 GESY	GES2219 3 GESY	<b>2N1442</b> 2N5477 1 GSE	TPQ2906A 3 SPR	DE130 3 DGE	
2N4305 3 TRWS	PN2222 3 NSC	<b>2N1443</b> 2N5477 1 GSE	<b>2N1477</b> 2N2906A 1 MOTA		
BCX56-16 3 SIEG	THC2219 3 SPR	<b>2N1444</b> 2N5477 1 GSE	DE129 1 DGE		
D38H5 3 GESY	<b>2N1399</b> 2N3019 1 MOTA	<b>2N1445</b> 2N5477 1 GSE	BSS82C 3 SIEG		
DE128 3 DGE	D44T1 1 GESY	<b>2N1446</b> 2N5477 1 GSE	PN2907A 3 NSC		
THC3019 3 SPR	2N4305 3 TRWS	<b>2N1447</b> 2N5477 1 GSE	THC2907A 3 SPR		
TN3019 3 NSC	BCX56-16 3 SIEG	<b>2N1448</b> 2N5477 1 GSE	TMPT2907A 3 SPR		
<b>2N1339</b> 2N3019 1 MOTA	D38H5 3 GESY	<b>2N1449</b> 2N5477 1 GSE	TP2907A 3 SPR		
D44T1 1 GESY	DE128 3 DGE	<b>2N1450</b> 2N5477 1 GSE	<b>2N1478</b> 2N834 1 MOTA		
2N4305 3 TRWS	THC3019 3 SPR	<b>2N1451</b> 2N5477 1 GSE	BCY56 3 PHIN		
BCX56-16 3 SIEG	TN3019 3 NSC	<b>2N1452</b> 2N5477 1 GSE	BSX20 3 SGSI		
D38H5 3 GESY	<b>2N1399</b> 2N3019 1 MOTA	<b>2N1453</b> 2N5477 1 GSE	MPS834 3 NSC		
DE128 3 DGE	D44T1 1 GESY	<b>2N1454</b> 2N5477 1 GSE	<b>2N1479</b> 2N2906A 1 MOTA		
THC3019 3 SPR	2N4305 3 TRWS	<b>2N1455</b> 2N5477 1 GSE	DE129 1 DGE		
TN3019 3 NSC	BCX56-16 3 SIEG	<b>2N1456</b> 2N5477 1 GSE	PN2906A 3 NSC		
<b>2N1339</b> 2N3019 1 MOTA	D38H5 3 GESY	<b>2N1457</b> 2N5477 1 GSE	THC2906A 3 SPR		
D44T1 1 GESY	DE128 3 DGE	<b>2N1458</b> 2N5477 1 GSE	TPQ2906A 3 SPR		
2N4305 3 TRWS	THC3019 3 SPR	<b>2N1459</b> 2N5477 1 GSE	<b>2N1480</b> 2N4238 1 GSE		
BCX56-16 3 SIEG	TN3019 3 NSC	<b>2N1460</b> 2N5477 1 GSE	MOTA 1 MOTA		
D38H5 3 GESY	<b>2N1399</b> 2N3019 1 MOTA	<b>2N1461</b> 2N5477 1 GSE	BFX34 1 PHIN		
DE128 3 DGE	D44T1 1 GESY	<b>2N1462</b> 2N5477 1 GSE	BSV64 1 PHIN		
THC3019 3 SPR	2N4305 3 TRWS	<b>2N1463</b> 2N5477 1 GSE	D40D4 1 GESY		</