

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>U1994E</b> (Cont'd)	<b>U3012</b> (Cont'd)	<b>UC110</b> (Cont'd)	<b>UC201</b> (Cont'd)	<b>UC241</b> (Cont'd)	<b>UC401</b> (Cont'd)
THJ5245 3 SPR	2N4338 1 INL	2N3821 3 MOTA	2N5364 1 IFC	TMPF5361 3 SPR	TMPF5116 3 SPR
THJ5486 3 SPR	2N4340 3 SIX	2N4220 3 INL	2N4222 3 INL	TP3822 3 SPR	TP3993 3 SPR
TMPF4416 3 SPR	BFW12 3 PHIN	2N4221 3 INL	2N4224 3 SIX	TP4868 3 SPR	TP3994 3 SPR
TMPF5245 3 SPR	BFW13 3 PHIN	BFW12 3 PHIN	BFW10 3 PHIN	TP5361 3 SPR	TP5019 3 SPR
TMPF5486 3 SPR	DE312 3 DGE	BFW13 3 PHIN	DE452 3 DGE		TP5116 3 SPR
TP4416 3 SPR	THJ3460 3 SPR	DE312 3 DGE	DE459 3 DGE	<b>UC250</b>	<b>UC410</b>
TP5245 3 SPR	THJ4338 3 SPR	DE459 3 DGE	DE466 3 DGE	2N4091 1 INL	2N2609 1 NSC
<b>U1994J</b>	THJ4338 3 SPR	THJ4339 3 SPR	THJ3824 3 SPR		SIX
2N5485 1 MOTA	TMPF3460 3 SPR	THJ5360 3 SPR	THJ4393 3 SPR	2N4391 1 IFC	2N3330 1 IFC
2N5245 3 IFC	TMPF4338 3 SPR	TMPF4339 3 SPR	THJ4416 3 SPR		SIX
DE451 3 DGE	TP3460 3 SPR	TMPF5360 3 SPR	THJ5364 3 SPR		2N5268 1 INL
THJ5485 3 SPR	TP4338 3 SPR	TP4339 3 SPR	TMPF3824 3 SPR	DE466 3 DGE	2N2608 3 INL
TMPF5485 3 SPR	<b>U1897E</b>	TP5360 3 SPR	TMPF4393 3 SPR	THJ4091 3 SPR	SIX
	U1897-18 1 SIX	<b>UC115</b>	TMPF4416 3 SPR	THJ4391 3 SPR	THJ2609 3 SPR
<b>U2047</b>	<b>UA78H05</b>	2N3459 1 IFC	TMPF5364 3 SPR	TMPF4091 3 SPR	THJ3330 3 SPR
PN4416 1 NSC	SG323 1 SGL	2N4340 1 INL	TP3824 3 SPR	TMPF4391 3 SPR	TMPF2609 3 SPR
ITE4416 3 INL	IP123-5 3 IPS	2N4339 3 INL	TP4393 3 SPR	TP4091 3 SPR	TMPF3330 3 SPR
<b>U2047E</b>	LAS1905 3 LAM	2N4341 3 SIX	TP4416 3 SPR	TP4391 3 SPR	TP2609 3 SPR
2N4416 1 INL	M78H05 3 MPI	2N4342 3 SIX	TP5364 3 SPR		TP3330 3 SPR
2N5486 1 MOTA	MC78T05C 3 MOTA	BFW12 3 PHIN	<b>UC210</b>	<b>UC251</b>	<b>UC420</b>
PN4416 1 SIX	<b>UA5116</b>	DE459 3 DGE	2N3822 1 NSC	2N4093 1 MOTA	2N3329 1 IFC
PN4416-18 1 NSC	TP5116 1 NSC	THJ3459 3 SPR	SIX	2N4392 1 IFC	NSC
2N5247 3 IFC	2N5116 3	THJ4340 3 SPR	2N4416 1 INL		SIX
DE452 3 DGE		TMPF3459 3 SPR		DE466 3 DGE	2N5265 1 MOTA
ITE4416 3 INL	<b>UC20</b>	TMPF4340 3 SPR		THJ4093 3 SPR	2N5267 1 INL
THJ4416 3 SPR	2N3686 1 INL	TP3459 3 SPR		THJ4392 3 SPR	2N2607 3 INL
THJ5486 3 SPR	2N4341 1 SIX	TP4340 3 SPR		TMPF4093 3 SPR	2N2608 3 INL
TMPF4416 3 SPR	2N5358 1 IFC	<b>UC120</b>		TMPF4392 3 SPR	SIX
TMPF5486 3 SPR	2N5486 1 MOTA	2N3686 1 INL		TP4093 3 SPR	2N3330 3 MOTA
TP4416 3 SPR	2N3458 3 IFC	2N4220A 1 MOTA		TP4392 3 SPR	THJ3329 3 SPR
<b>U2047J</b>	2N3821 3 IFC	2N3821 3 IFC			TMPF3329 3 SPR
2N5486 1 MOTA	2N4220 3 INL	2N3821 3 IFC			TP3329 3 SPR
2N5247 3 IFC	2N4340 3 SIX	2N4220 3 INL			2N3993 1 MOTA
THJ5486 3 SPR	2N5247 3 IFC	2N4340 3 SIX			2N5114 1 INL
TMPF5486 3 SPR	BFW11 3 PHIN	BFW13 3 PHIN			SIX
<b>U3000</b>	THJ4341 3 INL	DE312 3 DGE			2N3386 3 SIX
2N3459 1 IFC	THJ5358 3 SPR	THJ4341 3 INL			2N5116 3 NSC
2N4341 1 INL	THJ5486 3 SPR	2N4220 3 INL			SIX
SIX	TMPF4341 3 SPR	2N4340 3 SIX			DE160 3 DGE
2N3458 3 IFC	TMPF5358 3 SPR	2N5247 3 IFC			THJ3993 3 SPR
2N4339 3 INL	TMPF5486 3 SPR	THJ4341 3 INL			THJ5114 3 SPR
BFW11 3 PHIN	TP5358 3 SPR	THJ5358 3 SPR			TMPF3993 3 SPR
BFW12 3 PHIN	<b>UC21</b>	THJ5486 3 SPR			TMPF5114 3 SPR
DE312 3 DGE	2N3687 1 INL	TMPF4341 3 SPR			TP3993 3 SPR
THJ3459 3 SPR	2N5486 1 MOTA	TP4341 3 SPR			TP5114 3 SPR
THJ4341 3 SPR	2N4341 3 SIX	<b>UC150</b>			<b>UC451</b>
TMPF3459 3 SPR	THJ5486 3 SPR	2N4416 1 MOTA			2N3994 1 MOTA
TMPF4341 3 SPR	TMPF5486 3 SPR	DE452 3 DGE			2N5116 1 INL
TP3459 3 SPR	TMPF5486 3 SPR	THJ4416 3 SPR			SIX
TP4341 3 SPR	TMPF5486 3 SPR	TMPF4416 3 SPR			2N3382 3 SIX
<b>U3001</b>	TMPF5486 3 SPR	TP4416 3 SPR			2N5116 3 NSC
2N3459 1 IFC		<b>UC150W</b>			DE160 3 DGE
2N4339 1 INL		2N4416 1 MOTA			THJ3994 3 SPR
SIX		DE452 3 DGE			THJ5116 3 SPR
2N4341 3 SIX		THJ4416 3 SPR			TMPF3994 3 SPR
BFW12 3 PHIN		TMPF4416 3 SPR			TMPF5116 3 SPR
BFW13 3 PHIN		TP4416 3 SPR			TP3994 3 SPR
DE312 3 DGE		<b>UC155</b>			TP5116 3 SPR
THJ3459 3 SPR		2N4416 1 INL			<b>UC452</b>
THJ4339 3 SPR		2N4416 1 MOTA			2N4392 1 MOTA
TMPF3459 3 SPR		2N4221 3 DGE			DE466 3 DGE
TMPF4339 3 SPR		THJ4416 3 SPR			THJ4392 3 SPR
TP3459 3 SPR		TMPF4416 3 SPR			TMPF4392 3 SPR
TP4339 3 SPR		TP4416 3 SPR			TP4392 3 SPR
<b>U3002</b>		<b>UC155W</b>			<b>UC588</b>
2N4338 1 INL		2N5364 1 IFC			2N4416 1 INL
SIX		2N4222 3 INL			2N4417 1 SIX
2N3460 3 IFC		2N4224 3 SIX			MPF4416 1 MOTA
BFW13 3 PHIN		BFW10 3 PHIN			PN4416-18 1 NSC
DE312 3 DGE		DE452 3 DGE			SIX
THJ4338 3 SPR		THJ4416 3 SPR			2N4416 3 MOTA
TMPF4338 3 SPR		THJ5364 3 SPR			DE452 3 DGE
TP4338 3 SPR		TMPF4416 3 SPR			THJ4416 3 SPR
<b>U3010</b>		TMPF5364 3 SPR			TMPF4416 3 SPR
2N3458 1 IFC		TP4416 3 SPR			TP4416 3 SPR
2N4341 1 INL		TP5364 3 SPR			<b>UC701</b>
SIX		<b>UC155W</b>			2N4220 1 MOTA
BFW10 3 PHIN		2N5640 1 MOTA			BFW13 3 PHIN
BFW11 3 PHIN		BSV90 3 PHIN			DE456 3 DGE
DE312 3 DGE		THJ5640 3 SPR			THJ4220 3 SPR
THJ3458 3 SPR		TIS75 3 IFC			TMPF4220 3 SPR
THJ4341 3 SPR		TMPF5640 3 SPR			TP4220 3 SPR
TMPF3458 3 SPR		<b>UC201</b>			<b>UC703</b>
TMPF4341 3 SPR		2N3824 1 INL			2N3822 1 NSC
TP3458 3 SPR		SIX			SIX
TP4341 3 SPR		2N4393 1 MOTA			2N4220 1 INL
<b>U3011</b>		NSC			MOTA
2N3459 1 IFC		SIX			SIX
2N4340 1 INL		BFW10 3 PHIN			2N5362 1 IFC
SIX		DE459 3 DGE			2N4222 3 INL
2N4339 3 INL		DE466 3 DGE			2N4339 3 SIX
2N4341 3 SIX		THJ3824 3 SPR			BFW11 3 PHIN
BFW12 3 PHIN		THJ4393 3 SPR			2N5116 1 INL
DE459 3 DGE		TMPF3824 3 SPR			SIX
THJ3459 3 SPR		TMPF4393 3 SPR			2N3382 3 SIX
THJ4340 3 SPR		TP3824 3 SPR			2N3386 3 SIX
TMPF3459 3 SPR		TP4393 3 SPR			2N3993 3 IFC
TMPF4340 3 SPR		<b>UC201</b>			2N3994 3 MOTA
TP3459 3 SPR		2N3824 1 INL			2N5116 1 INL
TP4340 3 SPR		SIX			SIX
<b>U3012</b>		2N4393 1 MOTA			2N3382 3 SIX
2N3460 1 IFC		2N4416 1 NSC			2N4222 3 INL
		SIX			2N4339 3 SIX
					THJ3822 3 PHIN
					DE456 3 DGE
					DE459 3 DGE
					THJ3822 3 SPR
					THJ3994 3 SPR
					THJ5019 3 SPR
					THJ5118 3 SPR
					THJ5362 3 SPR
					TMPF3822 3 SPR
					TMPF4220 3 SPR
					TMPF5362 3 SPR
					TP3822 3 SPR