

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N3734 (Cont'd) 2N5337 3 MOTA D42C8 3 GESY	2N3742 (Cont'd) THC3742 1 SPR D44T4 3 GESY DE996 3 DGE	2N3767 (Cont'd) D42T1 3 GESY D44C6 3 GESY D44C8 3 GESY DE384 3 DGE MJE182 3 NSC SD339 3 MIKG ST44C11 3 STI	2N3788 (Cont'd) SVT7523 3 TRWS	2N3798A (Cont'd) TMPT3798A 1 SPR TP3798A 1 SPR 2N2905A 3 PHIN DE159 3 DGE GES6017 3 GESY THC3798 3 SPR TMPT3798 3 SPR TP3798 3 SPR	2N3808 (Cont'd) MP351-78 1 MPS IT132 3 INL MP310 3 MPS MP351-52 3 MPS MP352-78 3 MPS
2N3735 2N4305 1 TRWS BSX59 1 PHIN D40D7 1 GESY 2N5321 3 RCA 2N5337 3 MOTA BSX32 3 SGSI D40D4 3 GESY	2N3743 2N5416 1 RCA BFT19B 1 RCA DE154 1 DGE GES3743 1 GESY THC3743 1 SPR DE397 3 DGE	2N3768 SFN350 1 SOD	2N3799 2N3791 1 RCA BDV92 1 PHIN D44H7 1 GESY DE219 1 DGE 2N6246 3 RCA 2N6292 3 RCA 2N6469 3 RCA BDV94 3 PHIN BDX92 3 PHIN BUV26 3 APX D44H8 3 GESY D45C2 3 GESY D45C5 3 GESY D45C6 3 GESY D45VH7 3 GESY ST44H7 3 STI	2N3799A (Cont'd) DE159 1 DGE GES6017 1 GESY THC3799 1 SPR TP3799 1 SPR BFX37 3 SGSI THC3799A 3 SPR TP3799A 3 SPR	2N3809 2N3811A 1 MOTA IT122 1 INL MP351-78 1 MPS IT132 3 INL MP310 3 MPS MP352-78 3 MPS
2N3736 D40D1 1 GESY	2N3744 D44C5 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C5 3 STI	2N3771 DE181 1 DGE 2N4311 3 TRWS	2N3799A 2N3792 1 RCA BDV94 1 PHIN D44H10 1 GESY DE219 1 DGE 2N6247 3 RCA 2N6292 3 RCA BDX94 3 PHIN BUV26 3 APX D44H11 3 GESY D45VH10 3 GESY ST44H10 3 STI	2N3799A 2N3799 1 MOTA THC3799A 1 SPR TP3799A 1 SPR DE159 3 DGE GES6017 3 GESY THC3799 3 SPR TP3799 3 SPR	2N3810 DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3737 D40D7 1 GESY DE123A 3 DGE	2N3745 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3773 DE284 1 DGE	2N3799A 2N3792 1 RCA BDV94 1 PHIN D44H10 1 GESY DE219 1 DGE 2N6247 3 RCA 2N6292 3 RCA BDX94 3 PHIN BUV26 3 APX D44H11 3 GESY D45VH10 3 GESY ST44H10 3 STI	2N3800 2N3806 1 MOTA DE82 1 DGE IT132 1 INL MP351-52 1 MPS 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811 DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3738 2N3584 1 RCA D42T1 1 GESY DE124 1 DGE 2N3583 3 RCA BU133 3 PHIN BUX67A 3 RCA BUX67B 3 RCA D40V1 3 GESY D44T1 3 GESY D44T2 3 GESY DE286 3 DGE	2N3746 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3774 2N4234 1 MOTA 2N5783 1 RCA DE129 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY SDT3552 3 SOD	2N3799A BDV94 1 PHIN D44H8 1 GESY DE219 1 DGE 2N4904 3 RCA 2N4905 3 RCA 2N6246 3 RCA 2N6292 3 RCA BDV92 3 PHIN BDX92 3 PHIN BUV26 3 APX D44H7 3 GESY D45C6 3 GESY D45C8 3 GESY ST44H8 3 STI	2N3800 DE82 1 DGE IT132 1 INL MP351-52 1 MPS 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3739 2N3585 1 RCA D42T2 1 GESY DE124 1 DGE 2N3584 3 RCA 2N4240 3 GSE BU126 3 PHIN BUX67B 3 RCA BUX67C 3 RCA D40V1 3 GESY D40V3 3 GESY D40V4 3 GESY D44T2 3 GESY D44T3 3 GESY D44T4 3 GESY DE286 3 DGE	2N3747 D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C6 3 STI	2N3775 2N4235 1 MOTA 2N5781 1 RCA DE129 1 DGE 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY SDT3550 3 SOD SDT3553 3 SOD	2N3799A BDV94 1 PHIN D44H8 1 GESY DE219 1 DGE 2N4904 3 RCA 2N4905 3 RCA 2N6246 3 RCA 2N6292 3 RCA BDV92 3 PHIN BDX92 3 PHIN BUV26 3 APX D44H7 3 GESY D45C6 3 GESY D45C8 3 GESY ST44H8 3 STI	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3740 2N5955 1 RCA D45C7 1 GESY DE218 1 DGE 2N6107 3 RCA 2N6317 3 MOTA BD240A 3 RCA SDT3576 3 SOD SDT3702 3 SOD SDT3704 3 SOD SDT3707 3 SOD SDT3708 3 SOD SDT3710 3 SOD SDT3711 3 SOD SDT3713 3 SOD SDT3716 3 SOD SDT3722 3 SOD SDT3727 3 SOD SDT3730 3 SOD ST45C7 3 STI	2N3748 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3776 2N4236 1 MOTA 2N5321 1 SGSI 2N5781 3 RCA D41E7 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	2N3799A BDV94 1 PHIN D44H11 1 GESY DE219 1 DGE 2N6247 3 RCA 2N6292 3 RCA BUV26 3 APX D44H10 3 GESY ST44H11 3 STI	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3741 2N5954 1 RCA BD140 1 PHIN D45C10 1 GESY DE218 1 DGE 2N4920 3 MOTA 2N6107 3 RCA 2N6318 3 MOTA BD240B 3 RCA MJE172 3 NSC SD340 3 MIKG SDT3577 3 SOD SDT3705 3 SOD SDT3714 3 SOD SDT3718 3 SOD SDT3723 3 SOD SDT3728 3 SOD SDT3731 3 SOD ST45C10 3 STI	2N3749 D43C6 1 GESY 2N6109 3 RCA D41D4 3 GESY DE128 3 DGE MDS77 3 MOTA THC3120 3 SPR	2N3777 2N5322 1 SGSI 2N5679 1 MOTA DE323 1 DGE D42C8 3 GESY DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
2N3742 2N3439 1 RCA DE154 1 DGE GES3742 1 GESY	2N3750 D43C8 1 GESY 2N6107 3 RCA D40D1 3 GESY DE106 3 DGE MDS77 3 MOTA THC3072 3 SPR	2N3778 2N4234 1 MOTA 2N5783 1 RCA DE323 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3751 D43C8 1 GESY 2N6107 3 RCA MDS77 3 MOTA	2N3779 2N4235 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3752 2N6373 1 RCA D44C8 1 GESY DE175 1 DGE 2N3054 3 RCA 2N3878 3 RCA 2N3879 3 RCA 2N4923 3 MOTA 2N6292 3 RCA 2N6315 3 MOTA BD235 3 PHIN BD239A 3 RCA BU407 3 APX D40V1 3 GESY D42C2 3 GESY D42C5 3 GESY D42C6 3 GESY D42C8 3 GESY D44C2 3 GESY D44C3 3 GESY D44C4 3 GESY D44C5 3 GESY D44C7 3 GESY MJE182 3 NSC SD339 3 MIKG ST44C8 3 STI	2N3780 2N4236 1 MOTA 2N5321 1 SGSI 2N5781 3 RCA D41E7 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3753 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3781 2N5679 1 MOTA DE323 3 DGE	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3754 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3782 2N4234 1 MOTA 2N5783 1 RCA BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3755 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3783 2N5679 1 MOTA DE323 3 DGE	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3756 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3784 2N4235 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3757 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3785 2N4236 1 MOTA 2N5781 3 RCA D41E7 3 GESY DE129 3 DGE	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3758 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3786 2N4234 1 MOTA 2N5783 1 RCA BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3759 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3787 2N4235 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3760 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3788 2N4236 1 MOTA 2N5321 1 SGSI 2N5781 3 RCA D41E7 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3761 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3789 2N4234 1 MOTA 2N5783 1 RCA DE323 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY DE129 3 DGE	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3762 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3790 2N4235 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3763 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3791 2N4236 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3764 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3792 2N4234 1 MOTA 2N5783 1 RCA DE323 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	2N3799A BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	2N3801 2N3807 1 MOTA DE82 1 DGE IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	2N3811A DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
	2N3765 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	2N3793 2N4235 1 MOTA 2N5781 1 RCA 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY DE129 3 DGE SDT3550 3 SOD SDT3553 3 SOD	2N3799A BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN THBC108 3 SPR THBC337 3 SPR	2N3801 2N3807 1	