

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.																							
<b>2N3666</b> (Cont'd) TN3019 3 NSC	<b>2N3684A</b> (Cont'd) TP4221 3 SPR	<b>2N3686</b> (Cont'd) THJ3969A 3 SPR THJ4340 3 SPR TMPF3821 3 SPR TMPF3969 3 SPR TMPF3969A 3 SPR TMPF4340 3 SPR TP3821 3 SPR TP3969 3 SPR TP3969A 3 SPR TP4340 3 SPR	<b>2N3700</b> (Cont'd) BC547B 3 PHIN BFY73 3 SGSI DE108 3 DGE MPSA05 3 MOTA THC760 3 SPR THC760A 3 SPR	<b>2N3706</b> (Cont'd) GES930 3 GESY MPS3706C 3 SPR PN930 3 NSC THBC338 3 SPR THC930 3 SPR TP930 3 SPR	<b>2N3719</b> (Cont'd) D43C5 3 GESY D43C7 3 GESY DE323 3 DGE MDS77 3 MOTA																							
<b>2N3667</b> 2N5881 1 MOTA BDW51A 3 SGSI DE181 3 DGE	<b>2N3685</b> 2N3821 1 IFC MOTA 2N4339 1 SIX BFW12 1 PHIN 2N3329 3 NSC	<b>2N3686A</b> NSC 2N3686 1 INL 2N3821 1 IFC MOTA 2N4340 3 SIX BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR	<b>2N3701</b> 2N3019 1 MOTA THC3701 1 SPR TP3701 1 SPR 2N4305 3 TRWS BCX56-16 3 SIEG D38H5 3 GESY DE128 3 DGE THC3019 3 SPR TN3019 3 NSC	<b>2N3707</b> BC547B 1 PHIN MPS3707 1 GESY THC3707 1 SPR BCW72 3 PHIN MPS3707C 3 SPR THBC547B 3 SPR	<b>2N3720</b> 2N5922 1 RCA BSS44 1 SGSI D43C8 1 GESY DE129 1 DGE THC3720 1 SPR 2N5781 3 RCA 2N6107 3 RCA D42C8 3 GESY D43C7 3 GESY DE323 3 DGE MDS77 3 MOTA																							
<b>2N3671</b> 2N2905 1 MOTA DE129 1 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>2N3686A</b> 2N4220A 3 MOTA 2N4221 3 MOTA 2N4221A 3 MOTA 2N4340 3 INL	<b>2N3687</b> 2N4341 1 SIX 2N3458 3 IFC 2N4091 3 MOTA 2N4220A 3 MOTA SIX 2N4338 3 INL NSC SIX 2N5358 3 IFC 2N5362 3 IFC 2N5457 3 MOTA 2N5486 3 MOTA 2N5639 3 MOTA BFW11 3 PHIN DE312 3 DGE SIX 2N5368 3 IFC 2N5457 3 MOTA 2N5486 3 MOTA 2N5639 3 MOTA BFW11 3 PHIN DE312 3 DGE J201-18 3 SIX MPF4220 3 MOTA PN3685-18 3 NSC THJ3821 3 SPR THJ3968 3 SPR THJ3968A 3 SPR THJ4339 3 SPR THJ5556 3 SPR TMPF3821 3 SPR TMPF3968 3 SPR TMPF3968A 3 SPR TMPF4339 3 SPR TMPF5556 3 SPR TP3821 3 SPR TP3968 3 SPR TP3968A 3 SPR TP4339 3 SPR TP5556 3 SPR	<b>2N3702</b> 2N3250 1 MOTA BC557 1 PHIN DE234 1 DGE MPS3702 1 GESY PN200 1 NSC THC3702 1 SPR 2N2905 3 PHIN 2N3905 3 NSC BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN DE159 3 DGE GES3250 3 GESY MPS3702C 3 SPR THBC557 3 SPR THC3250 3 SPR TP3250 3 SPR	<b>2N3708</b> BC547B 1 PHIN THC3708 1 SPR BCW72 3 PHIN THBC547B 3 SPR	<b>2N3710</b> BC547B 1 PHIN MPS3710 1 GESY THC3710 1 SPR BCW72 3 PHIN MPS3710C 3 SPR THBC547B 3 SPR	<b>2N3721</b> DE289A 1 DGE THC3721 1 SPR																						
<b>2N3672</b> 2N699 1 RCA DE159 1 DGE DE128 3 DGE THC699 3 SPR	<b>2N3687A</b> 2N4416 3 INL 2N4540 3 SIX 2N5359 3 IFC 2N5360 3 IFC 2N5458 3 MOTA 2N5639 3 MOTA 2N5953 3 IFC A5T3821 3 IFC BFW13 3 PHIN DE312 3 DGE DE456 3 DGE J202-18 3 SIX MPF4220 3 MOTA PN3685-18 3 NSC THJ3821 3 SPR THJ3968 3 SPR THJ3968A 3 SPR THJ4339 3 SPR THJ5556 3 SPR TMPF3821 3 SPR TMPF3968 3 SPR TMPF3968A 3 SPR TMPF4339 3 SPR TMPF5556 3 SPR	<b>2N3687B</b> 2N4341 1 SIX 2N3458 3 IFC 2N4091 3 MOTA 2N4220A 3 MOTA SIX 2N4338 3 INL NSC SIX 2N5358 3 IFC 2N5362 3 IFC 2N5457 3 MOTA 2N5486 3 MOTA 2N5639 3 MOTA BFW11 3 PHIN DE312 3 DGE SIX 2N5368 3 IFC 2N5457 3 MOTA 2N5486 3 MOTA 2N5639 3 MOTA BFW11 3 PHIN DE312 3 DGE J201-18 3 SIX MPF4220 3 MOTA PN3685-18 3 NSC THJ3821 3 SPR THJ3968 3 SPR THJ3968A 3 SPR THJ4339 3 SPR THJ5556 3 SPR TMPF3821 3 SPR TMPF3968 3 SPR TMPF3968A 3 SPR TMPF4339 3 SPR TMPF5556 3 SPR	<b>2N3703</b> 2N3251 1 MOTA BC557 1 PHIN DE234 1 DGE MPS3703 1 GESY THC3703 1 SPR 2N2905 3 PHIN 2N3906 3 NSC BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN DE159 3 DGE GES3251 3 GESY MPS3703C 3 SPR THBC557 3 SPR THC3251 3 SPR TP3251 3 SPR	<b>2N3709</b> BC547B 1 PHIN MPS3709 1 GESY THC3709 1 SPR BCW72 3 PHIN MPS3709C 3 SPR THBC547B 3 SPR	<b>2N3711</b> BC547B 1 PHIN MPS3711 1 GESY THC3711 1 SPR BCW72 3 PHIN MPS3711C 3 SPR THBC547B 3 SPR	<b>2N3712</b> 2N3440 1 RCA BD115 1 PHIN BF257 1 SGSI D44T1 1 GESY DE154 1 DGE BF336 3 PHIN BFN18 3 SIEG BFN26 3 SIEG D40V1 3 GESY D44T2 3 GESY DE396 3 DGE TN3440 3 NSC	<b>2N3713</b> 2N3715 1 RCA BDV93 1 PHIN D45H7 1 GESY DE130 1 DGE 2N6107 3 RCA 2N6470 3 RCA 2N6471 3 RCA BDX91 3 PHIN D44VH7 3 GESY D45H8 3 GESY ST45H7 3 STI	<b>2N3714</b> 2N3716 1 RCA D45H10 1 GESY DE130 1 DGE BDV95 3 PHIN BDX93 3 PHIN D44VH10 3 PHIN D45H11 3 GESY DE280 3 DGE ST45H10 3 STI	<b>2N3715</b> BDV93 1 PHIN D45H8 1 GESY DE130 1 DGE 2N3055 3 RCA 2N4914 3 RCA 2N6107 3 RCA D44C8 3 GESY D45H7 3 GESY DE328 3 DGE ST45H8 3 STI	<b>2N3716</b> BDV95 1 PHIN D45H11 1 GESY 2N3055 3 RCA 2N4915 3 RCA 2N6107 3 RCA D45H10 3 GESY DE130 3 DGE DE328 3 DGE ST45H11 3 STI	<b>2N3717</b> BDV93 1 PHIN D45H8 1 GESY DE130 1 DGE 2N3055 3 RCA 2N4914 3 RCA 2N6107 3 RCA D44C8 3 GESY D45H7 3 GESY DE328 3 DGE ST45H8 3 STI	<b>2N3718</b> 2N2903 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3719</b> 2N2903A 1 MOTA IT121 1 INL IT120 3 INL MP311 3 MPS MP312-78 3 MPS	<b>2N3720</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3721</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3722</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3723</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3724</b> BSX60 1 PHIN D40D1 1 GESY THC3724 1 SPR TN3724 1 NSC TP3724 1 SPR 2N3725 3 SGSI 2N5321 3 RCA THC3724A 3 SPR TP3724A 3 SPR	<b>2N3725</b> BSX59 1 PHIN D40E7 1 GESY THC3725 1 SPR TN3725 1 NSC 2N5321 3 RCA 2N5859 3 MOTA 2N5861 3 MOTA BSX32 3 SGSI BSX60 3 PHIN D40D1 3 GESY D40D4 3 GESY D40D7 3 GESY D40D8 3 GESY DE311 3 DGE DE324 3 DGE THC3252 3 SPR THC4047 3 SPR TP3252 3 SPR	<b>2N3726</b> D40D4 1 GESY THC3725A 1 SPR D40D4C 3 SPR	<b>2N3727</b> IT131 1 INL MP351-78 1 MPS DE82 3 DGE IT137 3 INL IT138 3 INL IT139 3 INL MP351 3 MPS	<b>2N3728</b> IT130 1 INL MP351-78 1 MPS MP352 3 MPS	<b>2N3729</b> 2N2903 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3730</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3731</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3732</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3733</b> 2N3622 1 MOTA IT122 1 INL DE81 3 DGE MP310 3 MPS MP312-78 3 MPS	<b>2N3734</b> 2N4307 1 TRWS BSX60 1 PHIN D40D1 1 GESY 2N3725 3 SGSI 2N5321 3 RCA