

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>ETK81-050</b> (Cont'd) QM50HA-H 3 MITJ	<b>FE100A</b> (Cont'd) THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654A</b> 2N4386 1 INL 2N5486 1 MOTA	<b>FE4303</b> 2N5459 1 INL 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE THJ5459 3 SPR TMPF5459 3 SPR	<b>FE5457</b> (Cont'd) THJ5953 3 SPR TIS58 3 PHIN TMPF5457 3 SPR TMPF5953 3 SPR TP5953 3 SPR	<b>FF400</b> (Cont'd) 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR
<b>ETL81-050</b> KS224510 1 WESY MJ100BE55 1 MOTA D67FFP5.6.7 3 GESY MG100G1AL3 3 TOSJ MJ10100 3 MOTA QM100HA-H 3 MITJ SPK1300 3 SOD	<b>FE102</b> 2N4119 1 INL THJ4119 3 SPR TMPF4119 3 SPR TP4119 3 SPR	2N5950 1 IFC 2N2906 3 MOTA 2N5247 3 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FE4304</b> 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR	<b>FE5458</b> 2N5458 1 INL 2N5952 1 IFC 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 NSC	<b>FI100</b> 2N4352 1 MOTA 3N163 3 INL 3N163 3 SIX DE465 3 DGE
<b>ETN81-050</b> KS324520 1 WESY MG200H1FL1 3 TOSJ MJ10200 3 MOTA QM200HA-H 3 MITJ	<b>FE102A</b> 2N4119 1 INL THJ4119 3 SPR TMPF4119 3 SPR TP4119 3 SPR	DE128 3 DGE PN4416 3 SIX THC4386 3 SPR THJ5486 3 SPR THJ5950 3 SPR TMPF5486 3 SPR TMPF5950 3 SPR TP4386 3 SPR TP5950 3 SPR	<b>FE5245</b> 2N4416 1 INL 2N5245 1 IFC 2N5486 1 MOTA 2N5245-18 3 SIX 2N5247 3 IFC 2N5248-18 3 NSC DE129 3 DGE DE452 3 DGE ITE4416 3 INL PN4416 3 SIX THJ4416 3 SPR THJ5245 3 SPR THJ5486 3 SPR TMPF4416 3 SPR TMPF5245 3 SPR	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FLB4018X2</b> 3907 2 HAM DE465 3 DGE
<b>ETN81-055</b> PTC4200 1 PTC KS621K2010 3 WESY MG200H2CK1 3 TOSJ	<b>FE104</b> 2N4118 1 INL THJ4118 3 SPR TMPF4118 3 SPR TP4118 3 SPR	<b>FE0654B</b> 2N5485 1 INL 2N5951 1 IFC 2N5245 3 IFC 2N5486 3 INL 2N5640 3 MOTA 2N5951-18 3 NSC	<b>FE5246</b> 2N5246 1 IFC 2N5484 1 INL 2N5486 1 MOTA 2N5246-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1100</b> 2N3954A 1 INL 2N5545 3 IFC MP841 3 MPS
<b>EV31-050</b> PTC2400 1 PTC KS52450510 3 WESY QM50DY-H 3 MITJ	<b>FE104A</b> 2N4118 1 INL THJ4118 3 SPR TMPF4118 3 SPR TP4118 3 SPR	DE451 3 DGE PN4416 3 SIX THJ5485 3 SPR THJ5951 3 SPR TIS59 3 TII TMPF5485 3 SPR TMPF5951 3 SPR TP5951 3 SPR	2N5247 3 IFC DE132 3 DGE DE180 3 DGE J305-18 3 SIX THJ5246 3 SPR THJ5484 3 SPR THJ5486 3 SPR TMPF5247 3 SPR TMPF5486 3 SPR TP5247 3 SPR	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1100A</b> 2N3954A 1 INL 2N5545 3 IFC MP841 3 MPS
<b>EV31T050</b> MJ15FG45 1 MOTA	<b>FE200</b> 2N3821 1 INL THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1101</b> 2N5906 1 INL MP5906 3 MPS U422 3 SIX
<b>EV1234</b> PTC2000 1 PTC KS221K0510 3 WESY QM50DY2H 3 MITJ	<b>FE202</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1102</b> 2N3954 1 INL MP841 3 MPS THJ3954 3 SPR
<b>EV1234M</b> KD221K05 1 WESY MJ50BX100 3 MOTA QM50DY2H 3 MITJ	<b>FE202</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1102A</b> 2N5906 1 INL MP5906 3 MPS U422 3 SIX
<b>EV1255</b> PTC4100 1 PTC KD421K1010 3 WESY MG100M2CK1 3 TOSJ QM100DY2H 3 MITJ	<b>FE202</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1103</b> 2N3955 1 INL 2N5546 3 IFC MP3954 3 MPS THJ3955 3 SPR
<b>EV1255-65M</b> KD421K10 1 WESY MJ100BX100 3 MOTA QM100DY2H 3 MITJ S2921 3 TOSJ	<b>FE204</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1103A</b> 2N5908 1 INL MP5908 3 MPS U423 3 SIX
<b>EV1277</b> KD221K03 1 WESY PTC2010 1 PTC KS221K0310 3 WESY MG25MCK1 3 TOSJ QM30DY2H 3 MITJ	<b>FE300</b> 2N3822 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1104</b> 2N3957 1 INL 2N5547 3 IFC MP3957 3 MPS THJ3957 3 SPR
<b>EV1298</b> KD421K15 1 WESY PTC4000 1 PTC KD4215K150 3 WESY MG150M2CK1 3 TOSJ MJ150BX100 3 MOTA QM150DY2H 3 MITJ S2904 3 TOSJ	<b>FE300</b> 2N3822 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1104A</b> 2N5909 1 INL 2N5908 3 SIX MP5909 3 MPS U423 3 SIX
<b>EVG31-050</b> KD224503 1 WESY MJ30BD45 1 MOTA PTC2200 1 PTC MG3062CL2 3 TOSJ PTC2200-1 3 PTC QM30DY-H 3 MITJ	<b>FE302</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1105</b> 2N3954A 1 INL 2N5545 3 IFC MP841 3 MPS
<b>EVK31-050</b> KD224505 1 WESY MJ50BD45 1 MOTA MG50G2CL2 3 TOSJ MJ50B2D45 3 MOTA PMD050PLA45 3 GESY PMD050PLA55 3 GESY PTC2400-1 3 PTC QM50DY-H 3 MITJ	<b>FE302</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1105A</b> 2N3954A 1 INL 2N5545 3 IFC MP841 3 MPS
<b>EVK71-050</b> KD224575 1 WESY PTC2300-1 3 PTC QM75DY-H 3 MITJ	<b>FE304</b> 2N3821 1 INL BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1106</b> 2N3954A 1 INL 2N5545 3 IFC MP841 3 MPS
<b>EVL31-050</b> KD324510 1 WESY MJ100BE55 1 MOTA QM100DY-H 3 MITJ	<b>FE400</b> 2N3436 1 MOTA 2N3458 3 IFC 2N3968 3 NSC SIX 2N4340 3 INL 2N4341 3 SIX	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1106A</b> IT500 1 INL
<b>EV31-050</b> PTC2400 1 PTC KS52450510 3 WESY QM50DY-H 3 MITJ	<b>FE400</b> 2N3436 1 MOTA 2N3458 3 IFC 2N3968 3 NSC SIX 2N4340 3 INL 2N4341 3 SIX	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1107</b> 2N3954 1 INL MP841 3 MPS THJ3954 3 SPR
<b>EV31T050</b> MJ15FG45 1 MOTA	<b>FE400</b> 2N3436 1 MOTA 2N3458 3 IFC 2N3968 3 NSC SIX 2N4340 3 INL 2N4341 3 SIX	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1107A</b> IT500 1 INL
<b>F3</b> P100F 2 GIC	<b>FE402</b> 2N3437 1 MOTA 2N3459 3 IFC 2N3968 3 NSC SIX 2N4340 3 INL 2N4341 3 SIX	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1108</b> 2N3955 1 INL 2N5546 3 IFC MP3954 3 MPS THJ3955 3 SPR
<b>FE100</b> 2N3821 1 INL SIX BFW13 3 PHIN DE456 3 DGE THJ3821 3 SPR TMPF3821 3 SPR TP3821 3 SPR	<b>FE402</b> 2N3437 1 MOTA 2N3459 3 IFC 2N3968 3 NSC SIX 2N4340 3 INL 2N4341 3 SIX	<b>FE0654C</b> 2N5485 1 MOTA 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1108A</b> IT502 1 INL
<b>FE100A</b> 2N3821 1 INL SIX BFW13 3 PHIN DE456 3 DGE	<b>FE404</b> 2N3436 1 MOTA 2N3458 3 IFC 2N4222 3 NSC SIX 2N4341 3 INL SIX	<b>FE4302</b> 2N5457 1 INL 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR	<b>FE5247</b> 2N5247 1 IFC 2N5486 1 INL 2N5486 1 MOTA 2N5247-18 3 NSC	<b>FE5459</b> 2N5459 1 INL 2N5950 1 IFC 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC	<b>FM1109</b> 2N3957 1 INL 2N5547 3 IFC MP3957 3 MPS THJ3957 3 SPR