

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>BC297</b> (Cont'd) BCX17 3 PHIN BCX51 3 PHIN D41D7 3 GESY THBC327 3 SPR THBC836 3 SPR	<b>BC309C</b> THBC309C 1 SPR	<b>BC322C</b> BC558B 1 PHIN BCW30 3 PHIN BCW61B 3 PHIN BCW61C 3 PHIN THBC558B 3 SPR	<b>BC332</b> (Cont'd) THBC547 3 SPR	<b>BC333</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	<b>BC340</b> (Cont'd) DE128 3 DGE GES3053 3 GESY THC3053 3 SPR
<b>BC298</b> BC328 1 PHIN BC107A 3 PHIN BC547A 3 PHIN BCX18 3 PHIN THBC328 3 SPR	<b>BC310</b> 2N1893 1 RCA BC141 1 SGSI 2N5320 3 RCA D40D7 3 GESY D42T1 3 GESY DE128 3 DGE	<b>BC323</b> 2N5320 1 RCA DE128 3 DGE	<b>BC334</b> BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR	<b>BC340-6</b> 2N2218A 1 PHIN GES2218A 3 GESY THC2218A 3 SPR TN2218A 3 NSC TP2218A 3 SPR	<b>BC350</b> (Cont'd) BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR
<b>BC300</b> 2N1893 1 RCA BD139 1 PHIN 2N2405 3 RCA 2N2987 3 GSE 2N4923 3 MOTA 2N5681 3 GSE BC639 3 PHIN D42T1 3 GESY DE128 3 DGE MJE182 3 NSC SD339 3 MIKG	<b>BC311</b> 2N4314 1 RCA 2N3868 3 MOTA D41D7 3 GESY DE129 3 DGE THC4314 3 SPR TP4314 3 SPR	<b>BC324</b> 2N5320 1 RCA BC301 1 SGSI 2N699 3 RCA BD139 3 PHIN D40D7 3 GESY DE128 3 DGE	<b>BC335</b> BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	<b>BC340-10</b> 2N2219A 1 PHIN GES2219A 3 GESY THC2219A 3 SPR TN2219A 3 NSC TP2219A 3 SPR	<b>BC351</b> BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR
<b>BC301</b> 2N699 1 RCA BD139 1 PHIN D40D7 1 GESY 2N2219 3 PHIN 2N3053 3 RCA 2N4923 3 MOTA 2N5320 3 RCA DE128 3 DGE MJE182 3 NSC SD339 3 MIKG THC699 3 SPR	<b>BC312</b> BC639 1 PHIN BF258 1 SGSI D44T1 1 GESY BCX56 3 PHIN BF337 3 PHIN D40V1 3 GESY THBC639 3 SPR	<b>BC325</b> BC640 1 PHIN BCX53 3 PHIN THBC640 3 SPR	<b>BC336</b> BC178 1 SGSI BC858A 3 PHIN THBC178 3 SPR	<b>BC341</b> 2N3053A 1 RCA BC141 1 SGSI 2N5320 3 RCA D40D7 3 GESY GES3053 3 GESY	<b>BC352</b> BC179 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR THBC558 3 SPR
<b>BC302</b> 2N2270 1 RCA BSX59 1 PHIN 2N5321 3 RCA BSX32 3 SGSI D40D4 3 GESY DE128 3 DGE THC2270 3 SPR	<b>BC313</b> BC303 1 SGSI D40D4 1 GESY 2N4314 3 RCA BD140 3 PHIN D40D4C 3 SPR	<b>BC327</b> BC297 1 SGSI BCX17 1 PHIN THBC327 1 SPR 2N2905 3 SGSI 2N2906 3 SGSI 2N2907 3 SGSI 2N4403 3 MOTA BC139 3 SGSI BC177 3 SGSI BC556A 3 PHIN BCW68F 3 SIEG BSS80C 3 SIEG D41D7 3 GESY DE129 3 DGE DE159 3 DGE GES3644 3 GESY MPS6533C 3 SPR MPS6534C 3 SPR MPS6535C 3 SPR PN200 3 NSC PN3644-5 3 NSC THC3644 3 SPR THC4289 3 SPR THC4402 3 SPR THC4403 3 SPR TMPT4402 3 SPR TMPT4403 3 SPR TP3644 3 SPR	<b>BC337</b> BC377 1 SGSI BCX19 1 PHIN THBC337 1 SPR 2N2218A 3 SGSI 2N2222A 3 MOTA 2N4401 3 MOTA 2N4923 3 NSC BC107 3 SGSI BC108 3 SGSI BC378 3 SGSI BC394 3 SGSI BCW66F 3 SIEG BFY56A 3 SGSI BSS79B 3 SIEG BSS79C 3 SIEG DE85 3 DGE DE123AP 3 DGE DE128 3 DGE DE192A 3 DGE DE199 3 DGE DE289A 3 DGE GES3568 3 GESY MPS3704 3 GESY MPS3705 3 GESY PN100 3 NSC PN3568-5 3 NSC PN3642-5 3 NSC THC3404 3 SPR THC3405 3 SPR THC3416 3 SPR THC3417 3 SPR THC3568 3 SPR THC3642 3 SPR THC3704 3 SPR THC3705 3 SPR THC3793 3 SPR THC3794 3 SPR THC4400 3 SPR THC4401 3 SPR THC4424 3 SPR THC4951 3 SPR THC4952 3 SPR THC4953 3 SPR TMPT4401 3 SPR TP3568 3 SPR TP3642 3 SPR	<b>BC342</b> 2N2102 1 RCA BC141 1 SGSI BC639 1 PHIN 2N2297 3 PHIN 2N4239 3 GSE 2N5320 3 RCA BCX56 3 PHIN BCX56-6 3 SIEG BCX56-10 3 SIEG BFY55 3 PHIN D40D7 3 GESY D40D10 3 GESY DE128 3 DGE THBC639 3 SPR THC2102 3 SPR	<b>BC353</b> 2N4036 1 RCA BC161 1 SGSI BC640 1 PHIN 2N5322 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC
<b>BC303</b> 2N4314 1 RCA BD140 1 PHIN 2N3868 3 MOTA 2N4036 3 RCA 2N4920 3 MOTA BC640 3 PHIN D40D4 3 GESY D41D7 3 GESY DE129 3 DGE MJE712 3 NSC SD340 3 MIKG THC4314 3 SPR TP4314 3 SPR	<b>BC314</b> BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR	<b>BC328-16</b> THBC327-16 1 SPR BC179 3 SGSI DE290 3 DGE PN200 3 NSC THC4290 3 SPR THC4291 3 SPR	<b>BC338</b> BC298 1 SGSI BCX18 1 PHIN THBC328 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BCW67A 3 SIEG	<b>BC343</b> 2N4036 1 RCA BC161 1 SGSI BC640 1 PHIN 2N5322 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC	<b>BC354</b> BC478 1 SGSI BC558 1 PHIN BC557 3 PHIN BC858A 3 PHIN THBC558 3 SPR
<b>BC304</b> 2N4037 1 RCA BC640 1 PHIN BCX52-10 3 SIEG BCX53 3 PHIN BD138 3 PHIN D41D4 3 GESY DE129 3 DGE THBC640 3 SPR THC4037 3 SPR TN4037 3 NSC	<b>BC315</b> BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC557 3 SPR	<b>BC327-25</b> THBC327-25 1 SPR	<b>BC339</b> BC298 1 SGSI BCX18 1 PHIN THBC328 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BCW67A 3 SIEG	<b>BC344</b> 2N2405 1 RCA BC300 1 SGSI BC639 1 PHIN 2N1893 3 RCA 2N2987 3 GSE BCX56 3 PHIN BD139 3 PHIN D42T1 3 GESY THBC639 3 SPR	<b>BC355</b> BC478 1 SGSI BC558 1 PHIN BC557 3 PHIN BC858A 3 PHIN THBC558 3 SPR
<b>BC307</b> BC177 1 SGSI SC307 1 MIKG THBC307 1 SPR BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	<b>BC316</b> BC107 1 SGSI BC547 1 PHIN THBC317 1 SPR	<b>BC328-25</b> THBC328-16 1 SPR THBC328-25 1 SPR	<b>BC340</b> BC377 1 SGSI BCX20 1 PHIN THBC338 1 SPR 2N830 3 MOTA BC108 3 SGSI BC109 3 SGSI BCW65A 3 SIEG DE85 3 DGE DE192A 3 DGE DE289A 3 DGE MPS3706 3 GESY PN100 3 NSC THC3402 3 SPR THC3403 3 SPR THC3414 3 SPR THC3415 3 SPR THC3706 3 SPR THC4954 3 SPR	<b>BC345</b> 2N4036 1 RCA BC303 1 SGSI BC640 1 PHIN 2N4314 3 RCA BCX53 3 PHIN BCX53-6 3 SIEG BCX53-10 3 SIEG BD140 3 PHIN D41D7 3 GESY DE129 3 DGE THBC640 3 SPR THC4036 3 SPR TN4036 3 NSC	<b>BC356</b> BC109 1 SGSI BC548 1 PHIN BC108 1 PHIN BC108 3 SGSI BCF32 3 PHIN THBC109 3 SPR THBC548 3 SPR
<b>BC307A</b> THBC307A 1 SPR	<b>BC317</b> BC107 1 SGSI BC547 1 PHIN THBC317 1 SPR	<b>BC329</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC341</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	<b>BC346</b> 2N2405 1 RCA BC300 1 SGSI BC639 1 PHIN 2N1893 3 RCA 2N2987 3 GSE BCX56 3 PHIN BD139 3 PHIN D42T1 3 GESY THBC639 3 SPR	<b>BC357</b> BC479 1 SGSI BC559 1 PHIN BC557 3 PHIN BC859A 3 PHIN
<b>BC307B</b> THBC307B 1 SPR	<b>BC318</b> BC108 1 SGSI BC548 1 PHIN THBC318 1 SPR	<b>BC330</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	<b>BC342</b> BC107 1 SGSI BC378 3 SGSI BC394 3 SGSI BCW66F 3 SIEG BFY56A 3 SGSI BSS79B 3 SIEG BSS79C 3 SIEG DE85 3 DGE DE123AP 3 DGE DE128 3 DGE DE192A 3 DGE DE199 3 DGE DE289A 3 DGE GES3568 3 GESY MPS3704 3 GESY MPS3705 3 GESY PN100 3 NSC PN3568-5 3 NSC PN3642-5 3 NSC THC3404 3 SPR THC3405 3 SPR THC3416 3 SPR THC3417 3 SPR THC3568 3 SPR THC3642 3 SPR THC3704 3 SPR THC3705 3 SPR THC3793 3 SPR THC3794 3 SPR THC4400 3 SPR THC4401 3 SPR THC4424 3 SPR THC4951 3 SPR THC4952 3 SPR THC4953 3 SPR TMPT4401 3 SPR TP3568 3 SPR TP3642 3 SPR	<b>BC347</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	<b>BC358</b> BC109 1 SGSI BC548 1 PHIN BC108 3 SGSI BCF32 3 PHIN THBC109 3 SPR THBC548 3 SPR
<b>BC307C</b> THBC307C 1 SPR	<b>BC319</b> BC109 1 SGSI BC549 1 PHIN THBC319 1 SPR BCF32 3 PHIN THBC109 3 SPR	<b>BC331</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC343</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	<b>BC348</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	<b>BC359</b> BC479 1 SGSI BC559 1 PHIN BC557 3 PHIN BC859A 3 PHIN
<b>BC308A</b> THBC308A 1 SPR	<b>BC320</b> BC177 1 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR	<b>BC332</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC344</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR	<b>BC349</b> BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	<b>BC360-6</b> 2N2904 1 PHIN DE129 3 DGE THC2904 3 SPR TN2904 3 NSC TP2904 3 SPR
<b>BC308B</b> THBC308B 1 SPR	<b>BC321</b> BC178 1 SGSI BC558 1 PHIN BC478 3 SGSI BC858A 3 PHIN THBC178 3 SPR THBC558 3 SPR	<b>BC333</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC345</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	<b>BC360-10</b> 2N2905 1 PHIN DE129 3 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>BC361</b> 2N4036 1 RCA BC161 1 SGSI 2N5322 3 RCA BCX53-6 3 SIEG BCX53-10 3 SIEG D41D7 3 GESY DE129 3 DGE THC4036 3 SPR TN4036 3 NSC
<b>BC308C</b> THBC308C 1 SPR	<b>BC322</b> BC179 1 SGSI BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR	<b>BC334</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC346</b> BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR	<b>BC360-16</b> 2N2905 1 PHIN DE129 3 DGE THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR	<b>BC362</b> BC440 1 SGSI BC868 1 PHIN THBC368 1 SPR BC635 3 PHIN
<b>BC309</b> BC179 1 SGSI SC309 1 MIKG THBC309 1 SPR BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR	<b>BC323</b> BC178 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	<b>BC335</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC347</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	<b>BC363</b> BC460 1 SGSI BC869 1 PHIN THBC369 1 SPR 2N5323 3 RCA	<b>BC363</b> BC440 1 SGSI BC868 1 PHIN THBC368 1 SPR BC635 3 PHIN
<b>BC309B</b> THBC309B 1 SPR	<b>BC324</b> BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR	<b>BC336</b> BC637 1 PHIN BFY76 1 SGSI 2N2484 3 PHIN BCX55 3 PHIN THBC637 3 SPR	<b>BC348</b> BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR	<b>BC364</b> BC460 1 SGSI BC869 1 PHIN THBC369 1 SPR 2N5323 3 RCA	<b>BC364</b> BC298 1 SGSI BC328 1 PHIN