

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>ITE2722</b> (Cont'd)	<b>ITE3067</b> (Cont'd)	<b>ITE4025</b>	<b>ITE4340</b> (Cont'd)	<b>ITE4416</b> (Cont'd)	<b>ITE4869</b> (Cont'd)
MP312 3 MPS	J201 3 INL	IT137 1 INL	2N5486 1 MOTA	2N5485-18 3 NSC	THJ5953 3 SPR
<b>ITE2903</b>	THJ3460 3 SPR	MP352 3 MPS	2N5953 1 IFC	SIX 3 NSC	TIS58 3 TII
IT122 1 INL	THJ4338 3 SPR	<b>ITE4091</b>	J202-18 1 SIX	2N5486 3 MOTA	TMPF4869 3 SPR
MP310 3 MPS	THJ5639 3 SPR	MPF4091 1 MOTA	2N3459 3 IFC	NSC 3 NSC	TMPF5459 3 SPR
<b>ITE2913</b>	TIS74 3 IFC	2N5638 3 MOTA	2N5247 3 IFC	SIX 3 NSC	TMPF5953 3 SPR
IT122 1 INL	TMPF3460 3 SPR	PN4091 3 NSC	2N5484 3 INL	2N5953 3 IFC	TP4869 3 SPR
MP310 3 MPS	TMPF4338 3 SPR	PN4091-18 3 NSC	2N5640 3 MOTA	DE129 3 DGE	TP5953 3 SPR
<b>ITE2914</b>	TMPF5639 3 SPR	PN4391-18 3 SIX	2N5952-18 3 SIX	DE452 3 DGE	
IT122 1 INL	TP3460 3 SPR	TIS73 3 IFC	2N5953-18 3 NSC	J304 3 SIX	<b>IVN201HNN</b>
MP310 3 MPS	TP4338 3 SPR	<b>ITE4092</b>	SIX 3 SIX	J304-18 3 NSC	VN1001A 1 SIX
<b>ITE2915</b>	<b>ITE3068</b>	MPF4092 1 MOTA	BFW12 3 PHIN	J305-18 3 NSC	BUZ25 3 SIEG
IT120 1 INL	2N3687 1 INL	2N5639 3 MOTA	DE459 3 DGE	J306 3 SIX	IRF132 3 FSC
MP312 3 MPS	2N4338 1 NSC	PN4092 3 NSC	J202 3 INL	J309 3 SIX	GESY
<b>ITE2916</b>	2N5639 1 MOTA	PN4092-18 3 NSC	J305 3 SIX	MPF4393 3 MOTA	MOTA
IT120 1 INL	J201-18 1 SIX	PN4392-18 3 SIX	SX3819 3 TII	PN4416 3 NSC	MTM12N10 3 MOTA
MP312 3 MPS	2N3460 3 IFC	TIS74 3 IFC	THJ4340 3 SPR	THJ4416 3 SPR	SDT20 3 SODI
<b>ITE2917</b>	2N4341 3 SIX	<b>ITE4093</b>	THJ5486 3 SPR	THJ5245 3 SPR	ZVN0209M 3 FERB
IT122 1 INL	BFW13 3 PHIN	MPF4093 1 MOTA	THJ5953 3 SPR	TMPF4416 3 SPR	ZVN2101M 3 FERB
MP310 3 MPS	BSV79 3 PHIN	2N5640 3 MOTA	TIS58 3 TII	TMPF5245 3 SPR	ZVN1109M 3 FERB
<b>ITE2918</b>	DE312 3 DGE	PN4093 3 NSC	TMPF4340 3 SPR	IRF722 3 SPR	<b>IVN600CNS</b>
IT122 1 INL	J201 3 INL	PN4093-18 3 NSC	TMPF5486 3 SPR	TP4416 3 SPR	IRF22 1 INR
MP310 3 MPS	THJ4338 3 SPR	PN4393-18 3 SIX	TMPF5953 3 SPR	TP5245 3 SPR	2SK309 3 HITJ
<b>ITE2919</b>	THJ5639 3 SPR	TIS75 3 IFC	TP4340 3 SPR	U310 3 SIX	APX
IT120 1 INL	TIS74 3 IFC	<b>ITE4117</b>	TP5953 3 SPR	<b>ITE4856</b>	SIE
MP312 3 MPS	TMPF4338 3 SPR	2N4117 1 INL	<b>ITE4341</b>	PN4856 3 NSC	SIEG
<b>ITE2920</b>	TMPF5639 3 SPR	SIX 3 SIX	2N4341 1 INL	<b>ITE4857</b>	BUZ726A 3 SIT
IT120 1 INL	TP4338 3 SPR	2N5640 1 MOTA	2N4391 1 NSC	PN4857 3 NSC	IVN600CNS 3 INL
MP312 3 MPS	<b>ITE3347</b>	PN4117-18 1 NSC	2N5486 1 MOTA	<b>ITE4858</b>	MTM3N40 3 MOTA
<b>ITE2936</b>	IT137 1 INL	BSV80 3 PHIN	2N5953 1 IFC	PN4858 3 NSC	MTP2N40 3 MOTA
IT120 1 INL	MP352 3 MPS	THJ4117 3 SPR	J203-18 1 SIX	<b>ITE4859</b>	MTP3N40 3 MOTA
MP312 3 MPS	<b>ITE3348</b>	THJ5640 3 SPR	2N3458 3 IFC	PN4859 3 NSC	MTP5N40 3 MOTA
<b>ITE2937</b>	IT138 1 INL	TIS75 3 IFC	2N5247 3 IFC	<b>ITE4860</b>	RFP3N45 3 RCA
IT120 1 INL	MP351 3 MPS	TMPF4117 3 SPR	2N5484 3 INL	PN4860 3 NSC	SDT60 3 SODI
MP312 3 MPS	<b>ITE3349</b>	TMPF5640 3 SPR	2N5640 3 MOTA	<b>ITE4861</b>	SNF722 3 SOD
<b>ITE2938</b>	IT139 1 INL	TP4117 3 SPR	2N5952-18 3 SIX	PN4861 3 NSC	SGSP331 3 SGSI
IT122 1 INL	MP351 3 MPS	<b>ITE4118</b>	2N5953-18 3 NSC	<b>ITE4867</b>	TX126 3 TXC
MP310 3 MPS	<b>ITE3350</b>	2N4118 1 INL	SIX 3 SIX	2N3460 1 IFC	UFN722 3 UNI
<b>ITE2973</b>	IT137 1 INL	SIX 3 SIX	BFW11 3 PHIN	2N4867 1 INL	VN0340N5 3 STX
IT122 1 INL	MP352 3 MPS	2N5640 1 MOTA	DE312 3 DGE	2N5457 1 MOTA	ZVNO340L 3 FERB
MP310 3 MPS	<b>ITE3351</b>	PN4118-18 1 NSC	DE466 3 DGE	J230-18 1 SIX	<b>IVN600CNT</b>
<b>ITE2974</b>	IT138 1 INL	BSV80 3 PHIN	J203 3 INL	PN3686-18 1 NSC	IRF821 1 INR
IT120 1 INL	MP351 3 MPS	THJ4118 3 SPR	J305 3 SIX	2N4220A 3 MOTA	BUZ42C 3 SIT
MP312 3 MPS	<b>ITE3680</b>	THJ5640 3 SPR	SX3819 3 TII	2N4338 3 INL	BUZ74 3 APX
<b>ITE2975</b>	IT120 1 INL	TIS75 3 IFC	THJ4341 3 SPR	2N4339 3 NSC	SIEG
IT120 1 INL	MP312 3 MPS	TIS75 3 IFC	THJ4391 3 SPR	SIX 3 SIX	GESY
MP312 3 MPS	<b>ITE3800</b>	TMPF4118 3 SPR	THJ4391 3 SPR	2N4340 3 SIX	IVN6000CNT 3 INL
<b>ITE2976</b>	IT132 1 INL	TMPF5640 3 SPR	THJ5486 3 SPR	2N5953 3 IFC	MTP4N45 3 MOTA
IT120 1 INL	MP351 3 MPS	TP4118 3 SPR	THJ5953 3 SPR	BF245A 3 PHIN	RFP3N45 3 RCA
MP312 3 MPS	<b>ITE3802</b>	<b>ITE4119</b>	TIS58 3 TII	BFW12 3 PHIN	SDT41A 3 SODI
<b>ITE2977</b>	IT132 1 INL	2N4119 1 INL	TMPF4341 3 SPR	DE451 3 DGE	SFN821 3 SOD
IT120 1 INL	MP351 3 MPS	SIX 3 SIX	TMPF4391 3 SPR	DE459 3 DGE	SGSP330 3 SGSI
MP312 3 MPS	<b>ITE3804</b>	2N5640 1 MOTA	TMPF5486 3 SPR	THJ3460 3 SPR	TX127 3 TXC
<b>ITE2978</b>	IT130 1 INL	PN4119-18 1 NSC	TMPF5953 3 SPR	THJ4867 3 SPR	UFN821 3 UNI
IT120 1 INL	MP352 3 MPS	BSV80 3 PHIN	TP4341 3 SPR	THJ5457 3 SPR	VN0345N5 3 STX
MP312 3 MPS	<b>ITE3806</b>	THJ4119 3 SPR	TP4391 3 SPR	TMPF3460 3 SPR	ZVN0345L 3 FERB
<b>ITE2979</b>	IT132 1 INL	THJ5640 3 SPR	TP5953 3 SPR	TMPF4867 3 SPR	<b>IVN5000AND</b>
IT120 1 INL	MP351 3 MPS	TIS75 3 IFC	<b>ITE4391</b>	TMPF5457 3 SPR	IRFD120 1 INR
MP312 3 MPS	<b>ITE3807</b>	TMPF4119 3 SPR	MPF4391 1 MOTA	TP3460 3 SPR	MPF910 1 MOTA
<b>ITE3066</b>	IT132 1 INL	TP4119 3 SPR	PN4391-18 1 NSC	TP4867 3 SPR	SD1117BD 1 SEP
2N3685 1 INL	MP351 3 MPS	<b>ITE4338</b>	SIX 3 SIX	<b>ITE4868</b>	VN0606M 1 SIX
2N4340 1 NSC	<b>ITE3808</b>	2N3460 1 IFC	TIS73 1 IFC	2N3459 1 IFC	2SK422 3
2N5639 1 MOTA	IT132 1 INL	2N4338 1 INL	2N4869 3 MOTA	2N4868 1 INL	BSS100 3 SIT
2N5953 1 IFC	MP351 3 MPS	NSC 3 NSC	2N5638 3 MOTA	2N5458 1 MOTA	D80AK2 3 GESY
J202-18 1 SIX	<b>ITE3809</b>	2N5486 1 MOTA	PN4391 3 NSC	J231-18 1 SIX	D82AL2 3 GESY
2N3459 3 IFC	IT132 1 INL	J201-18 1 SIX	PN4856-18 3 NSC	PN3685-18 1 NSC	IRFD123 3 INR
2N3821 3 IFC	MP351 3 MPS	2N4340 3 SIX	PN4859-18 3 NSC	2N3459 3 NSC	IVN5000ANE 3 INL
MOTA	<b>ITE3810</b>	2N5247 3 IFC	SD1117BD 3 TOP	2N4220A 3 MOTA	IVN5001AND 3 INL
2N4339 3 SIX	IT130 1 INL	BFW12 3 PHIN	<b>ITE4392</b>	MPF960 3 MOTA	IVN5001ANE 3 INL
2N5484 3 INL	MP352 3 MPS	BFW13 3 PHIN	MPF4392 1 MOTA	MPF660 3 MOTA	MPF960 3 MOTA
2N5640 3 MOTA	<b>ITE3811</b>	DE312 3 DGE	PN4392-18 1 NSC	2N4341 3 SIX	SD1106AD 3 TOP
2N5952-18 3 SIX	IT130 1 INL	J201 3 INL	SIX 3 SIX	2N5952 3 IFC	SD1107BD 3 TOP
2N5953-18 3 NSC	MP352 3 MPS	THJ3460 3 SPR	TIS74 1 IFC	BF245B 3 PHIN	SFN101A 3 SOD
BFW12 3 PHIN	<b>ITE3907</b>	THJ4338 3 SPR	2N4860 3 MOTA	DE451 3 DGE	TIS73 3
BSV79 3 PHIN	IT120 1 INL	THJ5486 3 SPR	2N5639 3 MOTA	DE459 3 DGE	TIS173 3
DE459 3 DGE	MP312 3 MPS	TMPF3460 3 SPR	2N5640 3 MOTA	THJ3459 3 SPR	TX101 3 TXC
J202 3 INL	<b>ITE3908</b>	TMPF4338 3 SPR	J111 3 NSC	THJ4868 3 SPR	VN10KMA 3 GESY
J305 3 SIX	IT120 1 INL	TMPF5486 3 SPR	MPF4092 3 MOTA	THJ5458 3 SPR	VN0106N3 3 STX
SX3819 3 TII	MP312 3 MPS	TP3460 3 SPR	MPF4292 3 MOTA	TMPF3459 3 SPR	VN0109N3 3 STX
THJ4340 3 SPR	<b>ITE4017</b>	TP4338 3 SPR	PN4392 3 NSC	TMPF4868 3 SPR	VN1306N3 3 STX
THJ5639 3 SPR	IT139 1 INL	<b>ITE4339</b>	SIX 3 SIX	TMPF5458 3 SPR	ZVN2106A 3 FERB
THJ5953 3 SPR	MP351 3 MPS	2N3460 1 IFC	PN4857-18 3 NSC	TP3459 3 SPR	<b>IVN5000ANE</b>
TIS58 3 TII	<b>ITE4018</b>	2N4339 1 INL	PN4860-18 3 NSC	TP4868 3 SPR	IRFD120 1 INR
TIS74 3 IFC	IT139 1 INL	NSC 3 NSC	SD1107BD 3 TOP	<b>ITE4869</b>	MPF910 1 MOTA
TMPF4340 3 SPR	MP351 3 MPS	2N5486 1 MOTA	<b>ITE4393</b>	2N4869 1 INL	SD1117BD 1 SEP
TMPF5639 3 SPR	<b>ITE4019</b>	J201-18 1 SIX	MPF4393 1 MOTA	2N5459 1 MOTA	SD1106M 1 SIX
TMPF5953 3 SPR	IT139 1 INL	2N4338 3 INL	PN4393-18 1 NSC	2N5953 1 IFC	2SK422 3
TP4340 3 SPR	MP351 3 MPS	2N4340 3 SIX	SIX 3 SIX	J232-18 1 SIX	BSS100 3 SIT
TP5953 3 SPR	<b>ITE4020</b>	2N5247 3 IFC	TIS75 1 IFC	2N4221 3 MOTA	D80AK2 3 GESY
<b>ITE3067</b>	IT139 1 INL	BFW12 3 PHIN	2N4861 3 MOTA	2N4341 3 NSC	D82AL2 3 GESY
2N3460 1 IFC	MP351 3 MPS	BFW13 3 PHIN	2N5640 3 MOTA	SIX 3 SIX	IRFD123 3 INR
2N3686 1 INL	<b>ITE4021</b>	DE312 3 DGE	J111 3 NSC	2N5484 3 INL	IVN5000AND 3 INL
2N4338 1 NSC	IT139 1 INL	J201 3 INL	PN4393 3 NSC	2N5640 3 MOTA	IVN5001AND 3 INL
2N5639 1 MOTA	MP351 3 MPS	THJ3460 3 SPR	SIX 3 SIX	2N5951 3 IFC	IVN5001ANE 3 INL
J201-18 1 SIX	<b>ITE4022</b>	THJ4339 3 SPR	PN4858-18 3 NSC	2N5952-18 3 SIX	MPF960 3 MOTA
3 IFC	IT139 1 INL	THJ5486 3 SPR	PN4861-18 3 NSC	2N5953-18 3 NSC	MPF660 3
2N3821 3 IFC	MP351 3 MPS	TMPF3460 3 SPR	<b>ITE4416</b>	SIX 3 SIX	SD1106AD 3 TOP
MOTA	<b>ITE4023</b>	TMPF4339 3 SPR	2N4416 1 MOTA	BF245C 3 PHIN	SD1107BD 3 TOP
2N4338 3 INL	IT137 1 INL	TMPF5486 3 SPR	2N5245 1 IFC	DE451 3 DGE	SFN101A 3 SOD
2N4340 3 SIX	MP352 3 MPS	TP3460 3 SPR	PN4416 1 SIX	DE459 3 DGE	TIS73 3
BFW12 3 PHIN	<b>ITE4024</b>	TP4339 3 SPR	PN4416-18 1 NSC	J305 3 SIX	TIS173 3
BFW13 3 PHIN	IT137 1 INL	<b>ITE4340</b>	2N3823 3 MOTA	SX3819 3 TII	TX101 3 TXC
BSV79 3 PHIN	MP352 3 MPS	2N4340 1 INL	2N5245-18 3 SIX	THJ4869 3 SPR	VN10KMA 3 GESY
DE312 3 DGE		NSC 3 NSC	2N5248-18 3 NSC	THJ5459 3 SPR	VN0106N3 3 STX