

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
ITE2722 (Cont'd) MP312 3 MPS	ITE3067 (Cont'd) J201 3 INL THJ3460 3 SPR THJ4338 3 SPR THJ5639 3 SPR	ITE4025 IT137 1 INL MP352 3 MPS	ITE4340 (Cont'd) 2N5486 1 MOTA 2N5953 1 IFC J202-18 1 SIX 2N3459 3 IFC 2N5247 3 IFC 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 IFC	ITE4416 (Cont'd) 2N5485-18 3 NSC 2N5486 3 MOTA 2N5953 3 IFC DE129 3 DGE DE452 3 DGE J304 3 SIX J304-18 3 NSC J305-18 3 NSC J306 3 SIX J309 3 SIX MPF4393 3 MOTA PN4416 3 NSC THJ4416 3 SPR THJ5245 3 SPR TMPF4416 3 SPR TMPF5245 3 SPR IRF722 3 SPR TP4416 3 SPR TP5245 3 SPR U310 3 SIX	ITE4869 (Cont'd) THJ5953 3 SPR TIS58 3 TII TMPF4869 3 SPR TMPF5459 3 SPR TMPF5953 3 SPR TP4869 3 SPR TP5953 3 SPR
ITE2903 IT122 1 INL MP310 3 MPS	ITE2913 IT122 1 INL MP310 3 MPS	ITE4091 MPF4091 1 MOTA 2N5638 3 MOTA PN4091 3 NSC PN4091-18 3 NSC PN4391-18 3 SIX TIS73 3 IFC	ITE4092 MPF4092 1 MOTA 2N5639 3 MOTA PN4092 3 NSC PN4092-18 3 NSC PN4392-18 3 SIX TIS74 3 IFC	ITE4856 PN4856 3 NSC	IVN201HNN VN1001A 1 SIX BUZ25 3 SIEG IRF132 3 FSC GESY 3 MOTA
ITE2915 IT120 1 INL MP312 3 MPS	ITE2916 IT120 1 INL MP312 3 MPS	ITE4093 MPF4093 1 MOTA 2N5640 3 MOTA PN4093 3 NSC PN4093-18 3 NSC PN4393-18 3 SIX TIS75 3 IFC	ITE4099 MPF4099 1 MOTA 2N5640 3 MOTA PN4099 3 NSC TMPF5486 3 SPR TMPF5953 3 SPR TP4340 3 SPR TP5953 3 SPR	ITE4857 PN4857 3 NSC	IVN600CNS IRF722 1 INR 2SK309 3 HITJ BUZ76A 3 APX SIE 3 SIEG SIT 3 SIT INL 3 INL MOTM3N40 3 MOTA MTP2N40 3 MOTA MTP3N40 3 MOTA MTP5N40 3 MOTA RFP3N45 3 RCA SDT60 3 SODI SFN722 3 SOD SGSP331 3 SGSI TX126 3 TXC UFN722 3 UNI VN0340N5 3 STX ZVN0340L 3 FERB
ITE2917 IT122 1 INL MP310 3 MPS	ITE2918 IT122 1 INL MP310 3 MPS	ITE4117 2N4117 1 INL SIX 3 SIX 2N5640 1 MOTA PN4117-18 1 NSC BSV80 3 PHIN THJ4117 3 SPR THJ5640 3 SPR TIS75 3 IFC TMPF4117 3 SPR TMPF5640 3 SPR TP4117 3 SPR	ITE4341 2N4341 1 INL 2N4391 1 NSC 2N5486 1 MOTA 2N5953 1 IFC J203-18 1 SIX 2N3458 3 IFC 2N5247 3 IFC 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 NSC	ITE4858 PN4858 3 NSC	IVN600CNT IRF821 1 INR BUZ42C 3 SIT BUZ74 3 APX SIEG 3 SIEG GESY 3 GESY INL 3 INL MOTM600CNT 3 MOTA MTP4N45 3 MOTA RFP3N45 3 RCA SDT41A 3 SODI SFN821 3 SOD SGSP330 3 SGSI TX127 3 TXC UFN821 3 UNI VN0345N5 3 STX ZVN0345L 3 FERB
ITE2919 IT120 1 INL MP312 3 MPS	ITE2920 IT120 1 INL MP312 3 MPS	ITE4118 2N4118 1 INL SIX 3 SIX 2N5640 1 MOTA PN4118-18 1 NSC BSV80 3 PHIN THJ4118 3 SPR THJ5640 3 SPR TIS75 3 IFC TMPF4118 3 SPR TMPF5640 3 SPR TP4118 3 SPR	ITE4342 BFW11 3 PHIN DE312 3 DGE DE466 3 DGE J203 3 INL J305 3 SIX SX3819 3 TII THJ4341 3 SPR THJ4391 3 SPR THJ5486 3 SPR THJ5953 3 SPR TIS58 3 TII TMPF4341 3 SPR TMPF4391 3 SPR TMPF5486 3 SPR TMPF5953 3 SPR TP4341 3 SPR TP4391 3 SPR TP5953 3 SPR	ITE4859 PN4859 3 NSC	IVN5000AND IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000ANE 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX VN0109N3 3 STX VN1306N3 3 STX ZVN2106A 3 FERB
ITE2921 IT120 1 INL MP312 3 MPS	ITE2922 IT120 1 INL MP312 3 MPS	ITE4119 2N4119 1 INL SIX 3 SIX 2N5640 1 MOTA PN4119-18 1 NSC BSV80 3 PHIN THJ4119 3 SPR THJ5640 3 SPR TIS75 3 IFC TMPF4119 3 SPR TMPF5640 3 SPR TP4119 3 SPR	ITE4343 TIS73 1 IFC 2N4859 3 MOTA 2N5638 3 MOTA PN4391 3 NSC PN4856-18 3 NSC PN4859-18 3 NSC SD1117BD 3 TOP	ITE4860 PN4860 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX VN0109N3 3 STX VN1306N3 3 STX ZVN2106A 3 FERB
ITE2923 IT120 1 INL MP312 3 MPS	ITE2924 IT120 1 INL MP312 3 MPS	ITE4338 2N3460 1 IFC 2N4338 1 INL NSC 3 NSC 2N5486 1 MOTA J201-18 1 SIX 2N4340 3 SIX 2N5247 3 IFC BFW12 3 PHIN BFW13 3 PHIN DE312 3 DGE J201 3 INL THJ3460 3 SPR THJ4338 3 SPR THJ5486 3 SPR TMPF3460 3 SPR TMPF4338 3 SPR TMPF5486 3 SPR TP3460 3 SPR TP4338 3 SPR	ITE4391 MPF4391 1 MOTA PN4391-18 1 NSC SIX 3 SIX TIS73 1 IFC 2N4859 3 MOTA 2N5638 3 MOTA PN4391 3 NSC PN4856-18 3 NSC PN4859-18 3 NSC SD1117BD 3 TOP	ITE4861 PN4861 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX VN0109N3 3 STX VN1306N3 3 STX ZVN2106A 3 FERB
ITE2925 IT120 1 INL MP312 3 MPS	ITE2926 IT120 1 INL MP312 3 MPS	ITE4339 2N3460 1 IFC 2N4339 1 INL NSC 3 NSC 2N5486 1 MOTA J201-18 1 SIX 2N4338 3 INL 2N4340 3 SIX 2N5247 3 IFC BFW12 3 PHIN BFW13 3 PHIN DE312 3 DGE J201 3 INL THJ3460 3 SPR THJ4339 3 SPR THJ5486 3 SPR TMPF3460 3 SPR TMPF4339 3 SPR TMPF5486 3 SPR TP3460 3 SPR TP4339 3 SPR	ITE4392 MPF4392 1 MOTA PN4392-18 1 NSC SIX 3 SIX TIS74 1 IFC 2N4860 3 MOTA 2N5639 3 MOTA 2N5640 3 MOTA J111 3 NSC MPF4092 3 MOTA MPF4292 3 MOTA PN4392 3 NSC SIX 3 SIX PN4857-18 3 NSC PN4860-18 3 NSC SD1107BD 3 TOP	ITE4862 PN4862 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX VN0109N3 3 STX VN1306N3 3 STX ZVN2106A 3 FERB
ITE2927 IT120 1 INL MP312 3 MPS	ITE2928 IT120 1 INL MP312 3 MPS	ITE4340 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4393 MPF4393 1 MOTA PN4393-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4393 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4863 PN4863 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2929 IT120 1 INL MP312 3 MPS	ITE2930 IT120 1 INL MP312 3 MPS	ITE4341 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4394 MPF4394 1 MOTA PN4394-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4394 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4864 PN4864 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2931 IT120 1 INL MP312 3 MPS	ITE2932 IT120 1 INL MP312 3 MPS	ITE4342 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4395 MPF4395 1 MOTA PN4395-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4395 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4865 PN4865 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2933 IT120 1 INL MP312 3 MPS	ITE2934 IT120 1 INL MP312 3 MPS	ITE4343 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4396 MPF4396 1 MOTA PN4396-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4396 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4866 PN4866 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2935 IT120 1 INL MP312 3 MPS	ITE2936 IT120 1 INL MP312 3 MPS	ITE4344 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4397 MPF4397 1 MOTA PN4397-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4397 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4867 PN4867 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2937 IT120 1 INL MP312 3 MPS	ITE2938 IT120 1 INL MP312 3 MPS	ITE4345 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4398 MPF4398 1 MOTA PN4398-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4398 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4868 PN4868 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2939 IT120 1 INL MP312 3 MPS	ITE2940 IT120 1 INL MP312 3 MPS	ITE4346 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4399 MPF4399 1 MOTA PN4399-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4399 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4869 PN4869 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2941 IT120 1 INL MP312 3 MPS	ITE2942 IT120 1 INL MP312 3 MPS	ITE4347 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4400 MPF4400 1 MOTA PN4400-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4400 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4870 PN4870 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2943 IT120 1 INL MP312 3 MPS	ITE2944 IT120 1 INL MP312 3 MPS	ITE4348 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4401 MPF4401 1 MOTA PN4401-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4401 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4871 PN4871 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2945 IT120 1 INL MP312 3 MPS	ITE2946 IT120 1 INL MP312 3 MPS	ITE4349 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4402 MPF4402 1 MOTA PN4402-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4402 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4872 PN4872 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2947 IT120 1 INL MP312 3 MPS	ITE2948 IT120 1 INL MP312 3 MPS	ITE4350 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4403 MPF4403 1 MOTA PN4403-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4403 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4873 PN4873 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GESY VN0106N3 3 STX
ITE2949 IT120 1 INL MP312 3 MPS	ITE2950 IT120 1 INL MP312 3 MPS	ITE4351 2N4416 1 MOTA 2N5245 1 IFC PN4416 1 SIX PN4416-18 1 NSC 2N3823 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC	ITE4404 MPF4404 1 MOTA PN4404-18 1 NSC SIX 3 SIX TIS75 1 IFC 2N4861 3 MOTA 2N5640 3 MOTA J111 3 NSC PN4404 3 NSC SIX 3 SIX PN4858-18 3 NSC PN4861-18 3 NSC	ITE4874 PN4874 3 NSC	IVN5000ANE IRFD120 1 INR MPF910 1 MOTA SD1117BD 1 SEP VN0606M 1 SIX 2SK422 3 BSS100 3 SIT D80AK2 3 GESY D82AL2 3 GESY IRFD123 3 INR IVN5000AND 3 INL IVN5001AND 3 INL IVN5001ANE 3 INL MPF960 3 MOTA MPF6660 3 SD1106AD 3 TOP SD1107BD 3 TOP SFND101A 3 SOD TIS73 3 TIS173 3 TX101 3 TXC VN10KMA 3 GES