

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N2481</b> (Cont'd) 2N2222 3 SGSI BC548A 3 PHIN DE123AP 3 DGE THC3903 3 SPR TMPT3903 3 SPR	<b>2N2498</b> (Cont'd) 2N2498JAN 1 MOTA 2N3330JAN 1 MOTA	<b>2N2532</b> (Cont'd) DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2586</b> 2N930A 1 MOTA 2N2484 1 PHIN THC2586 1 SPR 2N3903 3 GESY 2N5210 3 NSC BCX41 3 SIEG BSS64 3 SIEG DE123A 3 DGE THC930A 3 SPR THC2484 3 SPR TMPT2484 3 SPR TP2484 3 SPR	<b>2N2608</b> (Cont'd) 2N3330 3 MOTA 2N3330-5 3 NSC 2N3331 3 NSC 2N3332 3 SIX 2N3332-5 3 NSC 2N3686 3 INL 2N3820 3 NSC 2N3822 3 IFC 2N3909 3 MOTA 2N4318 3 NSC 2N5020 3 NSC 2N5265 3 MOTA 2N5267 3 MOTA 2N5460 3 MOTA 2N5462-5 3 NSC 3N163 3 SIX 3N172 3 INL A5T5460 3 IFC A5T5462 3 IFC DE326 3 DGE DE460 3 DGE J270 3 SIX MPF161 3 MOTA PN5033-18 3 NSC THJ3820 3 SPR THJ5021 3 SPR THJ5033 3 SPR TMPP3820 3 SPR TMPP5021 3 SPR TMPP5033 3 SPR TP3820 3 SPR TP5021 3 SPR TP5033 3 SPR	<b>2N2618</b> (Cont'd) DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR
<b>2N2483</b> 2N2484 1 MOTA 2N2509 1 NSC DE123A 1 DGE GES2483 1 GESY 2N720A 3 MOTA 2N3700 3 MOTA 2N3903 3 GESY 2N4409 3 NSC 2N5210 3 NSC BC377 3 SGSI BC547B 3 PHIN BCX41 3 SIEG BFY73 3 SGSI BSS64 3 SIEG DE108 3 DGE DE154 3 DGE THC760 3 SPR THC760A 3 SPR THC2484 3 SPR THC2509 3 SPR TMPT2484 3 SPR TP2484 3 SPR	<b>2N2499</b> 2N2609 1 INL 2N3331 1 SIX 2N3331-5 1 NSC 2N3909A 1 MOTA 2N3909 3 SIX 2N5270 3 INL 2N5462 3 NSC THJ2609 3 SPR THJ3331 3 SPR TMPP2609 3 SPR TMPP3331 3 SPR TP2609 3 SPR TP3331 3 SPR	<b>2N2533</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2594</b> 2N5336 1 GSE D40D7 1 GESY 2N4309 3 TRWS D44VM10 3 GESY	<b>2N2598</b> S4015C 1 TCE	<b>2N2628</b> 2N6081 3 MOTA
<b>2N2484</b> 2N3903 1 GESY 2N5210 1 NSC BCX41 1 SIEG BSS64 1 SIEG DE123A 1 DGE THC2484 1 SPR TMPT2484 1 SPR TP2484 1 SPR 2N930A 3 MOTA 2N2222 3 SGSI 2N2509 3 NSC BC107 3 SGSI BC478 3 SGSI BC547B 3 PHIN BC548A 3 PHIN DE123AP 3 DGE GES2483 3 GESY MMB2484 3 MOTA MMBT2484 3 MOTA MMBT5550 3 MOTA MMBTA05 3 MOTA MMBTA06 3 MOTA PN100 3 NSC THC2586 3 SPR THC3903 3 SPR THC5210 3 SPR TMPT3903 3 SPR	<b>2N2500</b> 2N2608 1 INL 2N3332 1 SIX 2N3332-5 1 NSC 2N5267 1 MOTA 2N2608 3 SIX 2N3330 3 MOTA 2N5268 3 INL THJ2608 3 SPR THJ3332 3 SPR TMPP2608 3 SPR TP2608 3 SPR TP3332 3 SPR	<b>2N2534</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2598</b> S4015C 1 TCE	<b>2N2600</b> 2N3497 1 MOTA DE288 3 DGE GES3497 3 GESY	<b>2N2628</b> 2N6081 3 MOTA
<b>2N2485</b> DE128 1 DGE	<b>2N2501</b> 2N2369 1 PHIN 2N3903 1 GESY DE123A 1 DGE 2N2222 3 SGSI BC548A 3 PHIN BCW60A 3 SIEG BF198 3 PHIN DE123 3 DGE DE123AP 3 DGE PN2369 3 NSC THC3903 3 SPR TMPT3903 3 SPR	<b>2N2538</b> 2N2219 1 PHIN 2N5859 1 MOTA D40D1 1 GESY DE128 1 DGE RCA1A06 1 RCA 2N4307 3 TRWS DE324 3 DGE GES2219 3 GESY THC2219 3 SPR TN2219 3 NSC TP2219 3 SPR	<b>2N2600</b> 2N3497 1 MOTA DE288 3 DGE GES3497 3 GESY	<b>2N2602</b> DE159 1 DGE	<b>2N2639</b> IT120 1 INL MP311-78 1 MPS MP312 3 MPS
<b>2N2486</b> DE128 1 DGE	<b>2N2509</b> 2N720A 1 MOTA DE154 1 DGE THC2509 1 SPR 2N2484 3 MOTA DE123A 3 DGE GES2483 3 GESY	<b>2N2539</b> 2N2222 1 PHIN DE123A 1 DGE GES2221 1 GESY BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC THC2222 3 SPR TMPT2222 3 SPR TP2222 3 SPR	<b>2N2602</b> DE159 1 DGE	<b>2N2603</b> DE159 1 DGE	<b>2N2639JTV</b> DE281 1 DGE IT122 1 INL MP311-78 1 MPS MP310 3 MPS
<b>2N2487</b> DE126A 1 DGE	<b>2N2510</b> 2N930 1 MOTA DE123A 1 DGE THC2510 1 SPR GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2540</b> 2N222 1 PHIN DE123A 1 DGE GES2222 1 GESY DE102A 3 DGE	<b>2N2603</b> DE159 1 DGE	<b>2N2604</b> 2N5086 1 NSC BCY70 1 PHIN DE159 1 DGE THC2604 1 SPR BC557 3 PHIN BCX71C 3 SIEG BCX71D 3 SIEG BCY79 3 SGSI PN200 3 NSC THC5086 3 SPR TMPT5086 3 SPR	<b>2N2640</b> DEB1 1 DGE IT122 1 INL MP311-78 1 MPS MP310 3 MPS
<b>2N2488</b> DE126A 1 DGE	<b>2N2511</b> 2N930A 1 MOTA BFY76 1 SGSI DE123A 1 DGE THC2511 1 SPR 2N2484 3 PHIN THC930A 3 SPR	<b>2N2541</b> DE176 1 DGE	<b>2N2604</b> 2N5086 1 NSC BCY71 1 PHIN DE159 1 DGE THC2605 1 SPR BC557 3 PHIN BCX71C 3 SIEG BCX71D 3 SIEG BCY79 3 SGSI PN200 3 NSC THC5086 3 SPR TMPT5086 3 SPR	<b>2N2605</b> 2N2607 1 INL 2N5020 1 NSC 2N2608 3 SIX 2N2843 3 INL 2N3329 3 SIX 2N5265 3 MOTA DE460 3 DGE THJ5020 3 SPR TMPP5020 3 SPR TP5020 3 SPR	<b>2N2640JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
<b>2N2489</b> DE126A 1 DGE	<b>2N2514</b> DE123A 1 DGE	<b>2N2542</b> DE176 1 DGE	<b>2N2605</b> 2N5086 1 NSC BCY71 1 PHIN DE159 1 DGE THC2605 1 SPR BC557 3 PHIN BCX71C 3 SIEG BCX71D 3 SIEG BCY79 3 SGSI PN200 3 NSC THC5086 3 SPR TMPT5086 3 SPR	<b>2N2606</b> 2N2607 1 INL 2N5020 1 NSC 2N2608 3 SIX 2N2843 3 INL 2N3329 3 SIX 2N5265 3 MOTA DE460 3 DGE THJ5020 3 SPR TMPP5020 3 SPR TP5020 3 SPR	<b>2N2642JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
<b>2N2490</b> DE105 1 DGE	<b>2N2515</b> DE123A 1 DGE	<b>2N2543</b> DE176 1 DGE	<b>2N2606</b> 2N2607 1 INL 2N5020 1 NSC 2N2608 3 SIX 2N2843 3 INL 2N3329 3 SIX 2N5265 3 MOTA DE460 3 DGE THJ5020 3 SPR TMPP5020 3 SPR TP5020 3 SPR	<b>2N2607</b> 2N2608 1 SIX	<b>2N2644</b> IT122 1 INL MP311-78 1 MPS MP310 3 MPS
<b>2N2492</b> DE105 1 DGE	<b>2N2516</b> 2N3485A 1 MOTA DE123A 1 DGE	<b>2N2544</b> DE176 1 DGE	<b>2N2607</b> 2N2608 1 SIX	<b>2N2608</b> 2N2608JAN 1 SIX	<b>2N2644JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
<b>2N2493</b> DE105 1 DGE	<b>2N2517</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2545</b> DE176 1 DGE	<b>2N2608</b> 2N2608 1 SIX	<b>2N2608</b> 2N2608JAN 1 SIX	<b>2N2645</b> DEB1 1 DGE IT122 1 INL MP311-78 1 MPS MP310 3 MPS
<b>2N2494</b> DE160 1 DGE	<b>2N2518</b> DE123A 1 DGE	<b>2N2546</b> DE176 1 DGE	<b>2N2609</b> 2N2608 1 SIX	<b>2N2609</b> THJ2609 1 SPR TMPP2609 1 SPR TP2609 1 SPR 2N2608 3 IFC	<b>2N2645JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
<b>2N2495</b> DE160 1 DGE	<b>2N2519</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2547</b> DE176 1 DGE	<b>2N2610</b> 2N2608 1 SIX	<b>2N2610</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2646</b> DEB1 1 DGE IT122 1 INL MP311-78 1 MPS MP310 3 MPS
<b>2N2496</b> DE160 1 DGE	<b>2N2520</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2548</b> DE176 1 DGE	<b>2N2611</b> 2N3766 1 GSE 2N6373 3 RCA BD139 3 PHIN D44C8 3 GESY DE175 3 DGE	<b>2N2611</b> 2N3766 1 GSE 2N6373 3 RCA BD139 3 PHIN D44C8 3 GESY DE175 3 DGE	<b>2N2646JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
<b>2N2497</b> 2N2608 1 INL 2N3329 1 SIX 2N3329-5 1 NSC 2N5267 1 MOTA 2N2608 3 SIX 2N3330 3 MOTA 2N5267 3 INL THJ2608 3 SPR THJ3329 3 SPR TMPP2608 3 SPR TMPP3329 3 SPR TP2608 3 SPR TP3329 3 SPR	<b>2N2521</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2549</b> DE176 1 DGE	<b>2N2612</b> DE102A 1 DGE	<b>2N2612</b> DE102A 1 DGE	<b>2N2647</b> DE6401 1 DGE
<b>2N2498</b> 2N2608 1 INL 2N3330 1 MOTA 2N3330-5 1 NSC 2N5268 3 INL THJ2608 3 SPR THJ3330 3 SPR TMPP2608 3 SPR	<b>2N2522</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2550</b> DE176 1 DGE	<b>2N2613</b> 2N1193 1 LTE DE102A 1 DGE	<b>2N2613</b> 2N1193 1 LTE DE102A 1 DGE	<b>2N2648</b> DEB1 1 DGE IT120 1 INL MP311-78 1 MPS MP312 3 MPS
	<b>2N2523</b> DE123A 1 DGE	<b>2N2551</b> DE176 1 DGE	<b>2N2614</b> 2N1193 1 LTE DE102A 1 DGE	<b>2N2614</b> 2N1193 1 LTE DE102A 1 DGE	<b>2N2648JTV</b> 2N2642 1 MOTA DEB1 3 DGE IT120 3 INL MP311-78 3 MPS
	<b>2N2524</b> 2N3485A 1 MOTA DE123A 1 DGE	<b>2N2552</b> DE176 1 DGE	<b>2N2615</b> DE123A 1 DGE	<b>2N2615</b> DE123A 1 DGE	<b>2N2655</b> 2N5681 1 GSE D44T2 3 GESY DE128 3 DGE
	<b>2N2525</b> 2N930 1 MOTA DE123A 3 DGE GES930 3 GESY PN930 3 NSC THC930 3 SPR TP930 3 SPR	<b>2N2553</b> DE176 1 DGE	<b>2N2616</b> 2N918 1 THCS DE123A 1 DGE BF799 3 SIEG	<b>2N2616</b> 2N918 1 THCS DE123A 1 DGE BF799 3 SIEG	<b>2N2657</b> 2N4238 1 MOTA D4C7 1 GESY 2N5785 3 RCA