

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
LDF805 (Cont'd) DE466 3 DGE THJ4221 3 SPR TMPF4221 3 SPR TP4221 3 SPR	LMJ1001 (Cont'd) D44E3 3 GESY PMD12K80 3 LAM RCA1001 3 RCA LMJ2500 2N6050 3 RCA BDX64 3 PHIN PMD11K60 3 LAM LMJ2501 2N6051 3 RCA BDX64A 3 PHIN PMD11K80 3 LAM LMJ3000 2N6057 3 RCA BDX65 3 PHIN PMD10K60 3 LAM LMJ3001 2N6058 3 RCA BDX65A 3 PHIN PMD10K80 3 LAM PMD10K100 3 LAM LMJ4030 2N6285 3 RCA BDX66 3 APX PHIN PMD11K60 3 LAM LMJ4031 2N6286 3 RCA BDX66A 3 APX PHIN PMD11K80 3 LAM LMJ4032 2N6287 3 RCA BDX66B 3 APX PHIN PMD11K100 3 LAM PMD17K100 3 LAM LMJ4033 2N6282 3 RCA BDX67 3 APX PHIN PMD16K60 3 LAM LMJ4034 2N6283 3 RCA BDX67A 3 APX PHIN PMD16K80 3 LAM LMJ4035 2N6284 3 RCA BDX67B 3 APX PHIN PMD16K100 3 LAM LMJ11011 PMD19K60 3 LAM LMJ11012 PMD18K60 3 LAM SVT6002 3 TRWS LMJ11013 PMD19K100 3 LAM LMJ11014 PMD18K100 3 LAM LPO80 L14R1 2 GESY OP580 3 TRWO LPT80 TIL411 2 TII L14Q1 3 GESY MTS360 3 GIC OP550 3 TRWO SEP.8406 3 HON	LPT100A (Cont'd) MRD3055 3 MOTA MTH320 3 GIC NSL610 3 NSC OP500SLD 3 TRWO OP803 3 TRWO STPT300 3 STE STPT2020-2 3 STE STPT2030-1 3 STE STPT2030-2 3 STE LPT100B SD5443-2 1 HON FPT100B 2 FSC BPY62-2 3 LTX CLT2140 3 CLA CLT2150 3 CLA GS4021-2 3 GSI K5255 3 OTK L14G2 3 GESY L14G3 3 GESY LPT100 3 LTX LPT100A 3 LTX MRD3054 3 MOTA MRD3055 3 MOTA MTH320 3 GIC NSL610 3 NSC OP803 3 TRWO STPT300 3 STE STPT2020-2 3 STE STPT2030-1 3 STE STPT2030-2 3 STE LPT110 SD3443-1 1 HON CLT2010 3 CLA CLT2030 3 CLA GS4123-1 3 GSI K5201 3 OTK K5202 3 OTK L14C1 3 GESY MT1 3 GIC MTH360 3 GIC OP801W 3 TRWO STPT1820-1 3 STE STPT1820-2 3 STE STPT1830-1 3 STE XC800W 3 NSC XC801W 3 NSC LPT110A SD3443-1 1 HON CLT2010 3 CLA CLT2030 3 CLA GS4123-1 3 GSI K5201 3 OTK K5202 3 OTK L14C1 3 GESY MT1 3 GIC MTH360 3 GIC OP801W 3 TRWO STPT1820-1 3 STE STPT1820-2 3 STE STPT1830-1 3 STE XC800W 3 NSC XC801W 3 NSC LS400 LISA600 2 GESY STPT40 2 STE LS600 OP600 1 TRWO OP640 2 TRW STPT80 2 STE SD2440-1 3 HON LS611 SP211 1 MIKG LS3069 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR LS3071 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR LS3458 J204 1 INL LS3459 J204 1 INL LS3460 J204 1 INL LS3684 J204 1 INL 2N3822 3 IFC MOTA	LS3684 (Cont'd) 2N4339 3 SIX BFW11 3 PHIN DE451 3 DGE LS3685 2N3685 1 INL 2N3821 3 IFC MOTA 2N4339 3 SIX BFW12 3 PHIN LS3686 2N3686 1 INL 2N3821 3 IFC MOTA 2N4340 3 SIX BFW13 3 PHIN LS3687 2N3687 1 INL 2N4341 3 SIX LS3819 2N5484 1 INL 2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR LS3821 2N5457 1 INL 2N5953 3 PHIN BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR LS3822 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR LS3921 2N3921 1 INL 2N5545 3 IFC MP844 3 MPS LS3922 2N3922 1 INL MP844 3 MPS LS3966 ITE4416 1 INL 2N4416 3 MOTA 2N5245 3 IFC PN4416 3 SIX PN4416-18 3 NSC LS3967 ITE4416 1 INL 2N4416 3 MOTA 2N5245 3 IFC PN4416 3 SIX PN4416-18 3 NSC LS3969 ITE4416 1 INL 2N4416 3 MOTA 2N5245 3 IFC PN4416 3 SIX PN4416-18 3 NSC LS4220 J204 1 INL LS4221 J202 1 INL THJJ202 3 SPR TMPFJ202 3 SPR LS4222 J203 1 INL THJJ203 3 SPR TMPFJ203 3 SPR LS4223 J202 1 INL THJJ202 3 SPR TMPFJ202 3 SPR LS4224 J202 1 INL THJJ202 3 SPR TMPFJ202 3 SPR LS4338 2N5457 1 INL 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR LS4339 (Cont'd) 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR LS4340 2N5457 1 INL 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR LS4341 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR LS4393 ITE4393 1 INL MPF4391 3 MOTA PN4391-18 3 NSC SIX TIS73 3 IFC LS4392 ITE4392 1 INL MPF4392 3 MOTA PN4392-18 3 NSC SIX TIS74 3 IFC LS4393 ITE4393 1 INL MPF4393 3 MOTA PN4393-18 3 NSC SIX TIS75 3 IFC LS4416 ITE4416 1 INL 2N4416 3 MOTA 2N5245 3 IFC PN4416 3 SIX PN4416-18 3 NSC LS4856 ITE4091 1 INL MPF4091 3 MOTA LS4857 ITE4092 1 INL MPF4092 3 MOTA LS4858 ITE4093 1 INL MPF4093 3 MOTA LS4859 ITE4091 1 INL MPF4091 3 MOTA LS4860 ITE4092 1 INL MPF4092 3 MOTA LS4861 ITE4093 1 INL MPF4093 3 MOTA LS5103 2N5484 1 INL 2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR LS5104 2N5485 1 INL 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR LS5105 2N5486 1 INL 2N5247 3 IFC THJ5486 3 SPR TMPF5486 3 SPR LS5245 ITE4416 1 INL 2N4416 3 MOTA 2N5245 3 IFC PN4416 3 SIX PN4416-18 3 NSC LS5246 2N5484 1 INL 2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR LS5247 2N5486 1 INL 2N5247 3 IFC THJ5486 3 SPR TMPF5486 3 SPR LS5248 2N5486 1 INL 2N5247 3 IFC THJ5486 3 SPR TMPF5486 3 SPR LS5358 J204 1 INL	LS5359 J204 1 INL LS5361 J202 1 INL THJJ202 3 SPR TMPFJ202 3 SPR LS5362 J203 1 INL THJJ203 3 SPR TMPFJ203 3 SPR LS5363 J203 1 INL THJJ203 3 SPR TMPFJ203 3 SPR LS5364 J203 1 INL THJJ203 3 SPR TMPFJ203 3 SPR LS5391 2N4867A 1 INL 2N4220A 3 MOTA LS5392 2N4868A 1 INL 2N4220A 3 MOTA LS5393 2N4869A 1 INL 2N4221A 3 MOTA 2N5361 3 IFC LS5394 2N4869A 1 INL 2N4221A 3 MOTA 2N5361 3 IFC LS5395 2N4869A 1 INL 2N4221A 3 MOTA 2N5361 3 IFC LS5396 2N4869A 1 INL 2N4221A 3 MOTA 2N5361 3 IFC LS5457 2N5457 1 INL 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR TMPF5457 3 SPR LS5458 2N5458 1 INL 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR TMPF5458 3 SPR LS5459 2N5459 1 INL 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE THJ5459 3 SPR TMPF5459 3 SPR LS5484 2N5484 1 INL 2N5246 3 IFC DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR LS5485 2N5485 1 INL 2N5245 3 IFC DE451 3 DGE THJ5485 3 SPR TMPF5485 3 SPR LS5486 2N5486 1 INL 2N5247 3 IFC THJ5486 3 SPR TMPF5486 3 SPR LS5556 2N3685 1 INL 2N3821 3 IFC MOTA 2N4339 3 SIX BFW12 3 PHIN LS5557 2N3684 1 INL 2N3822 3 IFC MOTA 2N4339 3 SIX BFW11 3 PHIN DE459 3 DGE LS5638 2N5638 1 INL BSV78 3 PHIN THJ5638 3 SPR TIS73 3 IFC TMPF5638 3 SPR	