

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N3544 (Cont'd) DE108 1 DGE BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR	2N3567 (Cont'd) THC1613 3 SPR 2N3568 BC337 1 PHIN BFY56A 1 SGSI DE128 1 DGE GES3568 1 GESY PN3568-5 1 NSC THC3568 1 SPR TP3568 1 SPR BC377 3 SGSI BCX19 3 PHIN BSW66 3 PHIN D40D8 3 GESY THBC337 3 SPR	2N3583 (Cont'd) D44C5 3 GESY D44TE3 3 GESY 2N3584 D44T2 1 GESY DE286 1 DGE 2N3738 3 MOTA 2N3739 3 MOTA 2N6077 3 RCA BD232 3 PHIN BUX67B 3 RCA D42T1 3 GESY D44TE3 3 GESY DE124 3 DGE 2N3585 2N4240 1 GSE D44T4 1 GESY DE286 1 DGE 2N3739 3 MOTA 2N6077 3 RCA 2N6079 3 RCA BD232 3 PHIN BUX67B 3 RCA BUX67C 3 RCA D42T2 3 GESY D44T3 3 GESY D44TE4 3 GESY DE124 3 DGE 2N3586 2N5794 1 MOTA DE81 3 DGE IT129 3 INL 2N3587 2N5794 1 MOTA DE81 1 DGE IT122 1 INL IT129 3 INL MP310 3 MPS 2N3588 DE160 1 DGE 2N3590 D44T2 1 GESY 2N3591 D44T1 1 GESY 2N3592 D44T2 1 GESY 2N3593 D44T1 1 GESY 2N3594 D44T2 1 GESY 2N3597 D44T2 1 GESY 2N3598 DE71 1 DGE 2N3599 DE71 1 DGE 2N3600 2N5179 1 MOTA THCS DE160 1 DGE 2N918 3 PHIN BF799 3 SIEG BFX89 3 PHIN DE161 3 DGE 2N3605 BSX60 1 PHIN 2N3725 3 SGSI 2N5321 3 RCA D40D1 3 GESY 2N3606 2N2369 1 PHIN DE289A 1 DGE 2N3903 3 GESY BCW60A 3 SIEG DE123A 3 DGE PN2369 3 NSC 2N3607 BC548A 1 PHIN BCW31 3 PHIN BCW60A 3 PHIN THBC548A 3 SPR 2N3608 2N2608 1 MOTA 3N163 1 SIX 3N172 1 INL 2N4352 3 MOTA THJ2608 3 SPR TMFP2608 3 SPR TP2608 3 SPR 2N3609 2N3799 1 MOTA DE159 3 DGE GES6017 3 GESY THC3799 3 SPR TP3799 3 SPR 2N3610 2N3799 1 MOTA DE159 3 DGE GES6017 3 GESY THC3799 3 SPR TP3799 3 SPR 2N3611 2N5660 1 GSE D44T2 1 GESY DE286 1 DGE 2N3738 3 MOTA 2N6077 3 RCA 2N6078 3 RCA 2N6233 3 MOTA 2N6261 3 RCA BD131 3 PHIN D40D4 3 GESY D42C8 3 GESY	2N3614 DE121 1 DGE BDX96 3 PHIN 2N3615 BDX96 1 PHIN DE121 1 DGE BDW22C 3 SGSI 2N3616 BDX96 1 PHIN DE121 1 DGE BDW22C 3 SGSI DE179 3 DGE 2N3617 BDX92 1 PHIN DE121 1 DGE 2N4905 3 RCA BDW22A 3 SGSI BDX96 3 PHIN 2N3618 BDX96 1 PHIN DE121 1 DGE BDW22C 3 SGSI 2N3619 D42C6 1 GESY 2N6290 3 RCA MDS27 3 MOTA 2N3620 D42C2 1 GESY 2N6288 3 RCA MDS26 3 MOTA 2N3621 BLX15 1 PHIN D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX MRF428 3 MOTA ST44C6 3 STI THX15 3 THCS 2N3622 BLX15 1 PHIN D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX MRF428 3 MOTA ST44C6 3 STI THX15 3 THCS 2N3623 D42C6 1 GESY 2N6290 3 RCA MDS27 3 MOTA 2N3624 D42C6 1 GESY 2N6290 3 RCA MDS27 3 MOTA 2N3625 BLX15 1 PHIN D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX MRF428 3 MOTA ST44C6 3 STI THX15 3 THCS 2N3626 BLX15 1 PHIN D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX MRF428 3 MOTA ST44C6 3 STI THX15 3 THCS 2N3627 D42C8 1 GESY 2N6292 3 RCA MDS27 3 MOTA 2N3628 D42C8 1 GESY 2N6292 3 RCA MDS27 3 MOTA 2N3629 D44C8 1 GESY DE72 1 DGE 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI 2N3630 D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI 2N3631 2N3797 1 MOTA DE462 3 DGE 2N3632 D44C5 1 GESY BC377 3 SGSI BCX19 3 PHIN GES2218A 3 GESY DE128 1 DGE PN3642-5 1 NSC THC3642 1 SPR TP3642 1 SPR BC377 3 SGSI BCX19 3 PHIN GES2218A 3 GESY THBC337 3 SPR	2N3632 (Cont'd) 2N3767 3 MOTA 2N3927 3 MOTA 2N4912 3 MOTA 2N5635 3 MOTA THCS 2N6260 3 RCA 2N6290 3 RCA 2N6373 3 RCA 2N6374 3 RCA BD135 3 PHIN BD137 3 PHIN BD239 3 RCA BU407 3 APX D40D4 3 GESY D40D7 3 GESY D42C4 3 GESY D44C4 3 GESY D44C7 3 GESY D44C8 3 GESY DE175 3 DGE SD1012 3 THCS ST44C5 3 STI 2N3633 D44C5 1 GESY DE108 1 DGE 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C5 3 STI 2N3634 GES3634 1 GESY THC3634 1 SPR 2N3635 GES3635 1 GESY THC3635 1 SPR 2N3636 GES3636 1 GESY 2N3637 GES3637 1 GESY 2N3638 2N2904 1 PHIN 2N2905 1 SGSI DE129 1 DGE MPS3638 1 GESY PN3638-5 1 NSC THC3638 1 SPR TMPT3638 1 SPR TP3638 1 SPR GES3638 3 GESY MPS3638 3 MPS3638C 3 SPR THC2904 3 SPR THC2905 3 SPR TN2904 3 NSC TN2905 3 NSC TP2904 3 SPR TP2905 3 SPR 2N3638A MPS3638A 1 GESY PN3638A-5 1 NSC THC3638A 1 SPR TMPT3638A 1 SPR TP3638A 1 SPR GES3638A 3 GESY MPS3638A 3 MPS3638AC 3 SPR 2N3639 DE159 1 DGE PN3638-18 1 NSC 2N3640 2N4091 1 MOTA BCY772 1 PHIN BF579 1 SIEG DE123A 1 PHIN PN3640-18 1 NSC DE466 3 DGE MMBT3640 3 MOTA THJ4091 3 SPR TMFP4091 3 SPR TP4091 3 SPR 2N3641 2N2218 1 SGSI DE123A 1 DGE PN3641-5 1 NSC THC3641 1 SPR TP3641 1 SPR 2N697 3 RCA DE128 3 DGE GES2218 3 GESY THC2218 3 SPR TN2218 3 NSC TP2218 3 SPR 2N3642 2N2218A 1 SGSI BC337 1 PHIN DE128 1 DGE PN3642-5 1 NSC THC3642 1 SPR TP3642 1 SPR BC377 3 SGSI BCX19 3 PHIN GES2218A 3 GESY THBC337 3 SPR	2N3642 (Cont'd) THC2218A 3 SPR TN2218A 3 NSC TP2218A 3 SPR 2N3643 2N2218 1 PHIN 2N2219 1 SGSI DE128 1 DGE PN3643-5 1 NSC THC3643 1 SPR TP3643 1 SPR 2N697 3 RCA GES2218 3 GESY GES2219 3 GESY THC2218 3 SPR THC2219 3 SPR TN2218 3 NSC TN2219 3 NSC TP2218 3 SPR TP2219 3 SPR 2N3644 2N2905 1 SGSI BC327 1 PHIN DE129 1 DGE GES3644 1 GESY PN3644-5 1 NSC THC3644 1 SPR TP3644 1 SPR BC297 3 SGSI BCX17 3 PHIN THBC327 3 SPR THC2905 3 SPR TN2905 3 NSC TP2905 3 SPR 2N3645 2N2905A 1 PHIN SGSI DE129 1 DGE PN3645-5 1 NSC THC2905A 3 SPR TN2905A 3 NSC TP2905A 3 SPR 2N3646 BSX20 1 PHIN BSX26 1 SGSI DE123A 1 DGE PN3646-18 1 NSC THC3646 1 SPR 2N2369 3 PHIN 2N3647 DE123A 1 DGE 2N3648 DE123A 1 DGE 2N3659 D44T1 1 GESY 2N3660 2N4234 1 MOTA D43C3 1 GESY DE323 1 DGE 2N5783 3 RCA 2N6111 3 RCA D41E1 3 GESY DE129 3 DGE MDS76 3 MOTA 2N3661 2N4235 1 MOTA D43C8 1 GESY 2N5782 3 RCA 2N6107 3 RCA D41E5 3 GESY DE129 3 DGE MDS77 3 MOTA 2N3662 2N918 1 PHIN DE107 1 DGE BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR 2N3663 BFY90 1 PHIN DE107 1 DGE SD1300 3 THCS 2N3664 2N1893 1 RCA 2N3020 1 MOTA 2N5335 1 GSE 2N4305 3 TRWS 2N5337 3 MOTA BUY47 3 SGSI D38H4 3 GESY D42T1 3 GESY DE128 3 DGE THC3020 3 SPR TN3020 3 NSC 2N3666 2N3019 1 MOTA 2N4305 3 TRWS BCX56-16 3 SIEG D38H5 3 GESY DE128 3 DGE THC3019 3 SPR