

**ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)**

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
2N5068		2N5758	3-116	2N5349		2N5339	3-97
2N5069		2N5758	3-116	2N5384		2N6191	3-158
2N5083		2N5339	3-97	2N5385		2N6191	3-158
2N5084		2N5339	3-97	2N5386		2N5038	3-83
2N5085		2N5339	3-97	2N5387		2N6546	3-225
2N5147		2N6191	3-158	2N5388		2N6546	3-225
2N5148		2N5337	3-97	2N5389		2N6546	3-225
2N5149		2N6191	3-158	2N5404		2N6191	3-158
2N5150		2N5337	3-97	2N5405		2N6191	3-158
2N5151		2N6191	3-158	2N5406		2N6191	3-158
2N5152		2N5337	3-97	2N5407		2N6193	3-158
2N5153		2N6191	3-158	2N5408		2N6191	3-158
2N5154		2N5337	3-97	2N5409		2N6193	3-158
2N5157		2N6545	3-221	2N5410		2N6191	3-158
2N5190	2N5190		3-85	2N5411		2N6193	3-158
2N5191	2N5191		3-85	2N5427	2N5428		3-101
2N5192	2N5192		3-85	2N5428	2N5428		3-101
2N5193	2N5193		3-89	2N5429	2N5429		3-101
2N5194	2N5194		3-89	2N5430	2N5430		3-101
2N5195	2N5195		3-89	2N5466		2N6545	3-221
2N5202		2N5428	3-101	2N5467		2N6545	3-221
2N5239		2N6306	3-181	2N5477		2N5339	3-97
2N5240		2N6545	3-221	2N5478		2N5339	3-97
2N5241		2N3902	3-60	2N5479		2N5339	3-97
2N5264		2N6249	3-164	2N5480		2N5339	3-97
2N5284		2N5339	3-97	2N5490		MJE3055T	3-904
2N5285		2N5339	3-97	2N5491		MJE3055T	3-904
2N5286		2N6191	3-158	2N5492		2N6292	3-151
2N5287		2N6191	3-158	2N5493		2N6292	3-151
2N5293		2N6123	3-154	2N5494		MJE3055T	3-904
2N5294		2N6123	3-154	2N5495		MJE3055T	3-904
2N5295		2N6121	3-154	2N5496		2N6292	3-151
2N5296		2N6121	3-154	2N5497		2N6292	3-151
2N5297		2N6122	3-154	2N5508		2N5428	3-101
2N5298		2N6122	3-154	2N5539		2N6379	3-191
2N5301	2N5301		3-93	2N5559		MJ15001	3-710
2N5302	2N5302		3-93	2N5575		2N5685	3-112
2N5302JAN	2N5302JAN		3-93	2N5578		2N5685	3-112
2N5302JTX	2N5302JTX		3-93	2N5598		2N5428	3-101
2N5302JTXV	2N5302JTXV		3-93	2N5600		2N5428	3-101
2N5303	2N5303		3-93	2N5602		2N5428	3-101
2N5303JAN	2N5303JAN		3-93	2N5604		2N5430	3-101
2N5303JTX	2N5303JTX		3-93	2N5606		2N5428	3-101
2N5303JTXV	2N5303JTXV		3-93	2N5610		2N5428	3-101
2N5325		2N5339	3-97	2N5612		2N5430	3-101
2N5333		2N6303	3-32	2N5614		2N3448	3-18
2N5334		2N5337	3-97	2N5616		2N3448	3-18
2N5335		2N5337	3-97	2N5618		2N3448	3-18
2N5336	2N5336		3-97	2N5629	2N5629		3-105
2N5337	2N5337		3-97	2N5630	2N5630		3-105
2N5338	2N5338		3-97	2N5631	2N5631		3-105
2N5339	2N5339		3-97	2N5632		2N5882	3-123
2N5339JAN	2N5339JAN		3-97	2N5633		MJ15001	3-710
2N5339JTX	2N5339JTX		3-97	2N5634		MJ15001	3-710
2N5339JTXV	2N5339JTXV		3-97	2N5651		2N3585	3-20
2N5344		2N6211	3-161	2N5655	2N5655		3-109
2N5345		2N6212	3-161	2N5656	2N5656		3-109
2N5346		2N5339	3-97	2N5657	2N5657		3-109
2N5347		2N5339	3-97	2N5660		2N3585	3-20
2N5348		2N5339	3-97	2N5661		2N3584	3-20

\*Consult Motorola if a direct replacement is necessary.