

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>THBC213</b> BC213 2 BC178 3 SGSI BC213L 3 SPR BC557 3 PHIN	<b>THBC309B</b> BC309B 2	<b>THBC485A</b> BC485A 2	<b>THC718</b> 2N2221A 3 PHIN 2N4400 3 NSC DE123A 3 DGE	<b>THC2219</b> DE128 3 DGE GES2219 3 GESY TN2219 3 NSC TP2219 3 SPR	<b>THC2908 (Cont'd)</b> TP2906 3 SPR
<b>THBC213A</b> BC213A 2 BC213LA 3 SPR	<b>THBC309C</b> BC309C 2	<b>THBC485B</b> BC485B 2	<b>THC760</b> 2N2483 3 PHIN 2N3700 3 MOTA BC547B 3 PHIN DE108 3 DGE	<b>THC2219A</b> GES2219A 3 GESY TN2219A 3 NSC TP2219A 3 SPR	<b>THC2906A</b> PN2906A 3 NSC TMPT2906A 3 SPR TP2906A 3 SPR TPQ2906A 3 SPR
<b>THBC213B</b> BC213B 2 BC213LB 3 SPR	<b>THBC317</b> BC317 2 BC107 3 SGSI BC547 3 PHIN	<b>THBC516</b> BC516 2	<b>THC780A</b> 2N2483 3 PHIN 2N3700 3 MOTA 2N4409 3 NSC BFY73 3 SGSI	<b>THC2221</b> BSS81B 3 SIEG DE123A 3 DGE GES222A 3 GESY PN2221 3 NSC TMPT2221 3 SPR TP2221 3 SPR	<b>THC2907</b> BSS80C 3 SIEG DE159 3 DGE GES2907 3 GESY PN2907 3 NSC TMPT2907 3 SPR TP2907 3 SPR
<b>THBC213C</b> BC213C 2 BC213LC 3 SPR	<b>THBC317A</b> BC317A 2	<b>THBC546</b> BC546 2	<b>THC915</b> 2N2221A 3 PHIN DE123A 3 DGE MP56565 3 NSC	<b>THC2221A</b> BSS79B 3 SIEG GES2221A 3 GESY TMPT2221A 3 SPR TP2221A 3 SPR	<b>THC2907A</b> BSS82C 3 SIEG PN2907A 3 NSC TMPT2907A 3 SPR TP2907A 3 SPR
<b>THBC214</b> BC214 2 2N5087 3 MOTA BC179 3 SGSI BC214L 3 SPR BC559 3 PHIN	<b>THBC317B</b> BC317B 2	<b>THBC546A</b> BC546A 2	<b>THC916</b> BCY56 3 PHIN DE123A 3 DGE	<b>THC2222</b> BSS81C 3 SIEG GES2222 3 GESY PN2222 3 NSC TMPT2222 3 SPR TP2222 3 SPR	<b>THC2923</b> DE199 3 DGE
<b>THBC214A</b> BC214A 2 BC214LA 3 SPR	<b>THBC318</b> BC318 2 BC108 3 SGSI BC548 3 PHIN	<b>THBC546B</b> BC546B 2	<b>THC917</b> 2N918 3 MOTA DE161 3 DGE PN3563 3 NSC	<b>THC2222A</b> BSS79C 3 SIEG DE102A 3 DGE DE123A 3 DGE GES2222A 3 GESY PN2222A 3 NSC TMPT2222A 3 SPR TP2222A 3 SPR	<b>THC2924</b> DE199 3 DGE
<b>THBC214B</b> BC214B 2 BC214LB 3 SPR	<b>THBC318A</b> BC318A 2	<b>THBC547</b> BC547 2	<b>THC918</b> BF799 3 SIEG DE161 3 DGE PN918 3 NSC TMPT918 3 SPR TP918 3 SPR	<b>THC2222B</b> BSS79D 3 SIEG DE102A 3 DGE DE123A 3 DGE GES2222A 3 GESY PN2222A 3 NSC TMPT2222A 3 SPR TP2222A 3 SPR	<b>THC2925</b> DE199 3 DGE
<b>THBC214C</b> BC214C 2 BC214LC 3 SPR	<b>THBC318B</b> BC318B 2	<b>THBC547A</b> BC547A 2	<b>THC919</b> 2N930 3 MOTA 2N4409 3 NSC BFY76 3 SGSI GES929 3 GESY	<b>THC2222C</b> BSS79E 3 SIEG DE102A 3 DGE DE123A 3 DGE GES2222A 3 GESY PN2222A 3 NSC TMPT2222A 3 SPR TP2222A 3 SPR	<b>THC2926</b> BC548B 3 PHIN DE199 3 DGE
<b>THBC237</b> BC237 2 BC107 3 SGSI BC547 3 PHIN SC237 3 MIKG	<b>THBC318C</b> BC318C 2	<b>THBC547B</b> BC547B 2	<b>THC929</b> 2N930 3 MOTA 2N4409 3 NSC BFY76 3 SGSI GES929 3 GESY	<b>THC2243</b> 2N1893 3 RCA 2N3020 3 MOTA BSW67 3 PHIN DE128 3 DGE	<b>THC2945</b> DE159 3 DGE TP2945 3 SPR
<b>THBC237A</b> BC237A 2	<b>THBC319</b> BC319 2 BC109 3 SGSI BC549 3 PHIN	<b>THBC547C</b> BC547C 2	<b>THC930</b> DE123A 3 DGE GES930 3 GESY PN930 3 NSC TP930 3 SPR	<b>THC2243A</b> 2N1893 3 RCA 2N3020 3 MOTA	<b>THC3009</b> 2N3013 3 SGSI DE123A 3 DGE PN3646 3 NSC
<b>THBC237B</b> BC237B 2	<b>THBC319B</b> BC319B 2	<b>THBC547D</b> BC547D 2	<b>THC930A</b> DE123A 3 DGE	<b>THC2270</b> D40D4 3 GESY DE128 3 DGE	<b>THC3013</b> PN3646 3 NSC
<b>THBC238</b> BC238 2 BC108 3 SGSI SC238 3 MIKG	<b>THBC319C</b> BC319C 2	<b>THBC548</b> BC548 2 BC108 3 SGSI	<b>THC930B</b> DE123A 3 DGE	<b>THC2270A</b> D40D4 3 GESY DE128 3 DGE	<b>THC3019</b> 2N4305 3 TRWS BCX56-16 3 SIEG D38H5 3 GESY DE128 3 DGE TN3019 3 NSC
<b>THBC238A</b> BC238A 2	<b>THBC327</b> BC327 2 BC297 3 SGSI BCX17 3 PHIN	<b>THBC548A</b> BC548A 2	<b>THC956</b> 2N1711 3 PHIN PN2222A 3 NSC	<b>THC2484</b> 2N3903 3 GESY 2N5210 3 NSC BCX41 3 SIEG BSS64 3 SIEG DE123A 3 DGE TMPT2484 3 SPR TP2484 3 SPR	<b>THC3053</b> BCX55-10 3 SIEG BSS79C 3 SIEG DE128 3 DGE GES3053 3 GESY
<b>THBC238B</b> BC238B 2	<b>THBC327-16</b> BC327-16 2	<b>THBC548B</b> BC548B 2	<b>THC981</b> 2N720A 3 MOTA 2N2219 3 MOTA	<b>THC2509</b> 2N720A 3 MOTA DE154 3 DGE	<b>THC3072</b> 2N3763 3 MOTA D40D1 3 GESY
<b>THBC238C</b> BC238C 2	<b>THBC327-25</b> BC327-25 2	<b>THBC548C</b> BC548C 2	<b>THC1420</b> 2N2219 3 MOTA	<b>THC2509A</b> 2N720A 3 MOTA DE154 3 DGE	<b>THC3073</b> 2N3763 3 MOTA D40D1 3 GESY
<b>THBC239</b> BC239 2 2N5089 3 MOTA BC109 3 SGSI SC239 3 MIKG	<b>THBC328-16</b> BC328-16 2	<b>THBC555</b> BC555 2 BC477 3 SGSI BC856A 3 PHIN	<b>THC1566</b> 2N1711 3 PHIN DE128 3 DGE	<b>THC2509B</b> 2N720A 3 MOTA DE154 3 DGE	<b>THC3072A</b> 2N3763 3 MOTA D40D1 3 GESY
<b>THBC239A</b> BC239A 2	<b>THBC328-25</b> BC328-25 2	<b>THBC555A</b> BC555A 2	<b>THC1613</b> D40D7 3 GESY DE123 3 DGE PN2221A 3 NSC	<b>THC2510</b> 2N930 3 MOTA DE123A 3 DGE	<b>THC3072B</b> 2N3763 3 MOTA D40D1 3 GESY
<b>THBC239B</b> BC239B 2	<b>THBC328-25</b> BC328-25 2	<b>THBC555B</b> BC555B 2	<b>THC1711</b> D40D5 3 GESY DE128 3 DGE PN2222A 3 NSC	<b>THC2511</b> 2N930A 3 MOTA BFY76 3 SGSI DE123A 3 DGE	<b>THC3073A</b> 2N3006A 3 SGSI DE159 3 DGE MP5A05 3 GESY
<b>THBC239C</b> BC239C 2	<b>THBC337</b> BC337 2 BC377 3 SGSI BCX19 3 PHIN	<b>THBC555C</b> BC555C 2	<b>THC2017</b> 2N2989 3 GSE D40D7 3 GESY DE128 3 DGE	<b>THC2566</b> 2N930A 3 MOTA 2N2484 3 PHIN	<b>THC3107</b> 2N3019 3 MOTA D40DB 3 GESY DE128 3 DGE
<b>THBC257</b> BC257 2 BC177 3 SGSI BC557 3 PHIN	<b>THBC337-16</b> BC337-16 2	<b>THBC557</b> BC557 2 BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN	<b>THC2102</b> 2N2297 3 PHIN 2N4239 3 GSE BCX56-6 3 SIEG BCX56-10 3 SIEG BFY55 3 PHIN D40D10 3 GESY DE128 3 DGE	<b>THC2604</b> 2N5086 3 NSC BCY70 3 PHIN DE159 3 DGE	<b>THC3108</b> 2N2102 3 RCA 2N3020 3 MOTA D40D7 3 GESY DE128 3 DGE
<b>THBC257A</b> BC257A 2	<b>THBC337-25</b> BC337-25 2	<b>THBC557A</b> BC557A 2	<b>THC2192</b> 2N2219A 3 PHIN 2N3019 3 MOTA D40D4 3 GESY DE128 3 DGE	<b>THC2604A</b> 2N5086 3 NSC BCY71 3 PHIN DE159 3 DGE	<b>THC3109</b> 2N3499 3 MOTA D40DB 3 GESY DE128 3 DGE
<b>THBC257B</b> BC257B 2	<b>THBC338</b> BC338 2 BC378 3 SGSI BCX20 3 PHIN	<b>THBC557B</b> BC557B 2	<b>THC2192A</b> 2N3019 3 MOTA D40D4 3 GESY DE128 3 DGE	<b>THC2604B</b> 2N5086 3 NSC BCY70 3 PHIN DE159 3 DGE	<b>THC3110</b> 2N2102 3 RCA 2N3020 3 MOTA D40D7 3 GESY DE128 3 DGE
<b>THBC258</b> BC258 2 BC178 3 SGSI	<b>THBC338-16</b> BC338-16 2	<b>THBC557C</b> BC557C 2	<b>THC2192B</b> 2N3019 3 MOTA D40D4 3 GESY	<b>THC2604C</b> 2N5086 3 NSC BCY71 3 PHIN DE159 3 DGE	<b>THC3111</b> 2N3440 3 RCA D44T1 3 GESY DE154 3 DGE
<b>THBC258A</b> BC258A 2	<b>THBC338-25</b> BC338-25 2	<b>THBC557D</b> BC557D 2	<b>THC2192C</b> 2N3019 3 MOTA D40D4 3 GESY	<b>THC2604D</b> 2N5086 3 NSC BCY71 3 PHIN DE159 3 DGE	<b>THC3115</b> 2N2221 3 MOTA DE123A 3 DGE MPS2221 3 GESY
<b>THBC258B</b> BC258B 2	<b>THBC369</b> BC369 2 BC460 3 SGSI BC869 3 PHIN	<b>THBC558</b> BC558 2 BC478 3 SGSI BC858A 3 PHIN	<b>THC2192D</b> 2N3019 3 MOTA D40D4 3 GESY	<b>THC2604E</b> 2N5086 3 NSC BCY71 3 PHIN DE159 3 DGE	<b>THC3116</b> 2N2222 3 MOTA DE123A 3 DGE MPS2222 3 GESY
<b>THBC258C</b> BC258C 2	<b>THBC369A</b> BC369A 2	<b>THBC558A</b> BC558A 2	<b>THC2192E</b> 2N3019 3 MOTA D40D4 3 GESY	<b>THC2604F</b> 2N5086 3 NSC BCY71 3 PHIN DE159 3 DGE	<b>THC3117</b> 2N930A 3 MOTA 2N5210 3 NSC BFR17 3 SGSI DE123A 3 DGE
<b>THBC259</b> BC259 2 BC179 3 SGSI	<b>THBC413</b> BC413 2 BC550 3 PHIN	<b>THBC558B</b> BC558B 2	<b>THC2195</b> 2N697 3 RCA 2N1711 3 PHIN 2N2904 3 MOTA BS2218 3 SGSI DE128 3 DGE	<b>THC2604G</b> 2N904A 3 SPR TP2904A 3 SPR	
<b>THBC259A</b> BC259A 2	<b>THBC413B</b> BC413B 2	<b>THBC558C</b> BC558C 2	<b>THC2195A</b> 2N697 3 RCA 2N2219 3 MOTA	<b>THC2604H</b> 2N904A 3 SPR TP2904A 3 SPR	
<b>THBC259B</b> BC259B 2	<b>THBC413C</b> BC413C 2	<b>THBC558D</b> BC558D 2	<b>THC2218</b> 2N697 3 RCA DE128 3 DGE GES2218 3 GESY TN2218 3 NSC TP2218 3 SPR	<b>THC2604I</b> 2N904A 3 SPR TP2904A 3 SPR	
<b>THBC259C</b> BC259C 2	<b>THBC414</b> BC414 2 BC550 3 PHIN	<b>THBC558E</b> BC558E 2	<b>THC2218A</b> GES2218A 3 GESY TN2218A 3 NSC TP2218A 3 SPR		
<b>THBC307</b> BC307 2 BC177 3 SGSI SC307 3 MIKG	<b>THBC414A</b> BC414A 2	<b>THBC558F</b> BC558F 2			
<b>THBC307A</b> BC307A 2	<b>THBC414B</b> BC414B 2	<b>THBC558G</b> BC558G 2			
<b>THBC307B</b> BC307B 2	<b>THBC414C</b> BC414C 2	<b>THBC558H</b> BC558H 2			
<b>THBC308</b> BC308 2 BC178 3 SGSI SC308 3 MIKG	<b>THBC414D</b> BC414D 2	<b>THBC558I</b> BC558I 2			
<b>THBC308A</b> BC308A 2	<b>THBC415</b> BC415 2 BC560 3 PHIN	<b>THBC558J</b> BC558J 2			
<b>THBC308B</b> BC308B 2	<b>THBC415A</b> BC415A 2	<b>THBC558K</b> BC558K 2			
<b>THBC308C</b> BC308C 2	<b>THBC415B</b> BC415B 2	<b>THBC558L</b> BC558L 2			
<b>THBC309</b> BC309 2 BC179 3 SGSI SC309 3 MIKG	<b>THBC415C</b> BC415C 2	<b>THBC558M</b> BC558M 2			
	<b>THBC416</b> BC416 2 BC560 3 PHIN	<b>THBC558N</b> BC558N 2			
	<b>THBC416A</b> BC416A 2	<b>THBC558O</b> BC558O 2			
	<b>THBC416B</b> BC416B 2	<b>THBC558P</b> BC558P 2			
	<b>THBC416C</b> BC416C 2	<b>THBC558Q</b> BC558Q 2			
	<b>THBC485</b> BC485 2	<b>THBC558R</b> BC558R 2			
		<b>THBC558S</b> BC558S 2			
		<b>THBC558T</b> BC558T 2			
		<b>THBC558U</b> BC558U 2			
		<b>THBC558V</b> BC558V 2			
		<b>THBC558W</b> BC558W 2			
		<b>THBC558X</b> BC558X 2			
		<b>THBC558Y</b> BC558Y 2			
		<b>THBC558Z</b> BC558Z 2			